| Lot Number | Title | Description | Thumbnail |
|---------------|-------------------------------------|--|---------------------|
| | | **All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes** IMPORTANT NOTICE FOR NORTHSIDE ISD AUCTION: All purchases will be subject to a 14% buyer's premium. There Will Be A 3% Administrative Fee For Purchases Not Made By Cash, Cashier's Check, Money Order, Wire Transfer or Direct Deposit.** | |
| | | *Social distancing will be enforced *Customers will not be allowed inside to use the restrooms. No Exceptions! *Please schedule an appointment prior to removal. Customers may be turned away without an appointment scheduled. *We recommend wearing gloves and face mask for personal safety and health while on auction location. | |
| 0 | Preview & Removal Information | Preview: (By Appointment Only-Mandatory-No Exceptions) Monday, October 5, 2020 (Hours Of Operation: 8:00 a.m 12:00 p.m.) Location: McClung Transportation Station, 14173 Old FM 471, San Antonio, TX 78253 Driving Directions Removal: (By Appointment Only-Mandatory-No Exceptions) Monday, October 12, 2020/Tuesday, October 13, 2020/Wednesday, October 14, 2020 (Hours Of Operation: 8:00 a.m 12:00 p.m.) | (ATTENTION) Read Me |
| | | Preview & Removal Contact: Xavier Quintero 210-825-2985 & Michael Butler 210-825-2967 | |
| | | Winning Bidder Solely Responsible For Removal. No Assistance Is Provided. | |
| | | There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. | |
| | | **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** | |
| | | Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed | |

| 1 | (1) 2013 Ford Van Vin #6397 - Will Need To Be Towed (Wrecked) | Will Need To Be Towed Unit #CT63 Passenger: 2 Engine In Front Engine Problems: Was Running At Time Of Accident Gas Has Battery Runs Automatic Transmission Type Or Condition: Fair Brakes: Hydraulic Approx. Mileage (NOT ACTUAL): 67,400 Interior Condition: Good Interior Problems: Needs Cleaning Body Condition: Poor Body Problems: Wrecked On Right Side Of Vehicle Tires Condition: Good Tire Problems: Unknown There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** - Current Condition Unknown | |
|---|--|--|--|
| 2 | (1) 2001 Ford Cargo Van Vin #9378 - Will Need To Be Towed | Will Need To Be Towed Unit #CT023 Passenger: 2 Engine Size/Type: 4.6 Engine In Front Engine Problems: Not Running Gas Has Battery Does Not Run Automatic Transmission Type Or Condition: Fair Brakes: Hydraulic Approx. Mileage (NOT ACTUAL): 62,865 Interior Condition: Fair Interior Problems: Torn Seats Body Condition: Fair Body Problems: Unknown Tires Condition: Fair Tire Problems: Old Additional Information: Possible Fuel Pump Problem There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** - Current Condition Unknown | Account to the second s |

| 3 | (1) 2000 Ford E150 Cargo Van Vin #1331 - Will Need To Be Towed | Will Need To Be Towed Unit #CT019 Passenger: 2 Engine Size/Type: 4.6 Engine In Front Engine Problems: Will Not Start Gas Does Not Have Battery Runs Automatic Transmission Type Or Condition: Fair Brakes: Hydraulic Approx. Mileage (NOT ACTUAL): 106,741 Interior Condition: Fair Interior Problems: Front Seats Torn - Needs Cleaning Body Condition: Fair Body Problems: Unknown Tires Condition: Fair Tire Problems: Old Additional Information: Won't Start - Was Running When Parked - Missing Catalytic Convertor There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** - Current Condition Unknown | |
|---|--|---|--|
| 4 | (1) 1982 Chevy Truck Flat Bed Vin #6171 - Will Need To Be Towed | Will Need To Be Towed Unit #W802 Passenger: 2 Engine Size/Type: 454 Engine In Front Engine Problems: Won't Stay Running Gas Does Not Have Battery Runs Automatic Transmission Type Or Condition: Automatic Brakes: Hydraulic Approx. Mileage (NOT ACTUAL): 90,284 Interior Condition: Good Interior Problems: Needs Cleaning Body Condition: Good Body Problems: Good Paint - No Dents - Lift Gate Will Not Go Up Tires Condition: Poor Tire Problems: Old Additional Information: Was Running When Parked - Won't Stay Running - Comes With Scrap Metal In Truck There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. ** - Current Condition Unknown | |

| 5 | (1) 2002 Ford Crown Victoria Sedan Vin #8422 - Will Need To Be Towed | Will Need To Be Towed Unit #R726 Passenger: 4 Engine Size/Type: 4.6 Engine In Front Engine Problems: Ran Well When Parked Gas Does Not Have Battery Runs Automatic Transmission Type Or Condition: Transmission Slipping - Will Turn On Brakes: Hydraulic Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Fair Interior Problems: Needs Cleaning Body Condition: Fair Body Problems: Normal Wear & Tear Tires Condition: Fair Tire Problems: Old There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** - Current Condition Unknown | |
|---|--|--|--|
| 6 | (1) 2009 Ford Crown Victoria Sedan Vin #3451 | Unit #PD-600 Passenger: 5 Engine Size/Type: 4.6 Engine In Front Engine Problems: Runs Well Gas Has Battery, Dead Runs Automatic Transmission Type Or Condition: Fair Brakes: Hydraulic Approx. Mileage (NOT ACTUAL): 117,450 Interior Condition: Poor Interior Problems: Needs Cleaning Body Condition: Fair To Poor Body Problems: Decals Tires Condition: Fair Tire Problems: Old There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** - Current Condition Unknown | |
| 7 | (Lot) Bus Hoods | (Approx. 3) 2004 IHC (1) 2005 IHC (1) 2015 Bluebird - Current Condition Unknown | |
| 8 | (1) Ford F- 250 Super Duty Cargo Bed | - Current Condition Unknown | |

| | 1 | | T |
|----|---|--|---|
| 9 | (1) Tommy Lift | Fits Ford F-250 - Current Condition Unknown | |
| 11 | (1) 2003 Chevy Cargo Van Vin #4237 | Unit #FS-843 Passenger: 2 Engine Size/Type: 5.3 Engine In Front Engine Problems: Runs, Has Misfire Gas Has Battery, Dead Runs Automatic Transmission Type Or Condition: Fair Brakes: Hydraulic Approx. Mileage (NOT ACTUAL): 71,471 Interior Condition: Fair Interior Problems: Needs Cleaning - Torn Seats Body Condition: Poor Body Problems: Peeling Paint Tires Condition: Fair Tire Problems: Old There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** - Current Condition Unknown | |
| 12 | (1) 1997 Ford E350 Box Truck Vin #7592 | Unit #FS-839 Passenger: 2 Engine Size/Type: 5.4 Engine In Front Engine Problems: Runs Well Gas Has Battery Runs Automatic Transmission Type Or Condition: Fair Brakes: Hydraulic Approx. Mileage (NOT ACTUAL): 147,340 Has Lift Gate Interior Condition: Fair Interior Problems: Needs Cleaning - Torn Seats Body Condition: Fair Body Problems: Unknown Tires Condition: Fair Tire Problems: Old Additional Information: Runs Well - Box Has No Leaks - Lift Gate Works Well There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** - Current Condition Unknown | |

| 13 | (1) 1999 Ford Pickup Vin #2310 | Unit #FS-810 Passenger: 2 Engine Size/Type: 4.6 Engine In Front Engine Problems: Runs Well Gas Has Battery, Dead Runs Automatic Transmission Type Or Condition: Fair Brakes: Hydraulic Approx. Mileage (NOT ACTUAL): 60,397 Interior Condition: Fair Interior Problems: Headliner Torn - Torn Seats Body Condition: Fair Body Problems: Unknown Tires Condition: Fair Tire Problems: Old Additional Information: Paint Faded - Dash Cluster Does Not Work - Pulls To The Right - Back Does Not Open There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** - Current Condition Unknown | |
|----|---|---|--|
| 14 | (1) 1998 International Box Truck Vin #8968 | Unit #FS-815 Passenger: 2 Engine Size/Type: DT466 Engine In Front Engine Problems: Runs Well Diesel Has Battery Runs Automatic Transmission Type Or Condition: Good Brakes: Air Approx. Mileage (NOT ACTUAL): 127,736 Has Lift Gate Interior Condition: Poor Interior Problems: Needs Cleaning - Drivers Seat Is Broken Body Condition: Good Body Problems: Front Bumper Bent - Box Has No Leaks Tires Condition: Good Tire Problems: Unknown Additional Information: Reefer Not Complete, Not Working There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** - Current Condition Unknown | |