











Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	<p><b>** All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes**</b></p> <p><b>IMPORTANT NOTICE FOR CHANNELVIEW ISD AUCTION: All purchases will be subject to a 14% buyer's premium. There Will Be A 3% Administrative Fee For Purchases Not Made By Cash, Cashier's Check, Money Order, Wire Transfer or Direct Deposit.**</b></p> <p><b>*Social distancing will be enforced</b>  <b>*Customers will not be allowed inside to use the restrooms. No Exceptions!</b>  <b>*Please schedule an appointment prior to removal. Customers may be turned away without an appointment scheduled.</b>  <b>*We recommend wearing gloves and face mask for personal safety and health while on auction location.</b></p> <p><b>Preview:</b> (By Appointment Only-Mandatory-No Exceptions) Thursday, October 22, 2020 (Hours Of Operation: 9:00 a.m. - 11:00 a.m.)</p> <p><b>Location:</b> Channelview Transportation, 1407 Sheldon Rd., Channelview, TX 77530  <a href="#">Driving Directions</a></p> <p><b>Removal:</b> (By Appointment Only-Mandatory-No Exceptions) Wednesday, October 28, 2020/Thursday, October 29, 2020/Friday, October 30, 2020 (Hours Of Operation: 9:00 a.m. - 11:00 a.m.)</p> <p><b>Preview &amp; Removal Contact:</b> Ray Savoie 581-452-8069 email: <a href="mailto:ray.savoie@cvisd.org">ray.savoie@cvisd.org</a></p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>	


<p>1</p>	<p>(1) 2000 International Bluebird School Bus Vin #4333 - Will Need To Be Towed</p>	<p>Will Need To Be Towed  Unit #826  Conventional Style  Passenger: 16 + 3 Wheel Chair  Engine Size/Type: DT466E  Engine In Front  Engine Problems: Engine Needs To Be Overhauled - Will Not Run - Has Been Sitting For Several Years  Diesel  Has Battery, Dead  Does Not Run  Automatic  Brakes: Air  Inspection Sticker Date: December 2020  Approx. Mileage (NOT ACTUAL): 36,453  Has Wheel Chair Lift, Condition Unknown  Interior Condition: Fair  Interior Problems: Floor Soft In Entry - Seats Worn &amp; Some Have Tears  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches  Tires Condition: Fair</p> <p><b>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</b></p> <p><b>All defects and flaws with a vehicle will be the buyers responsibility once purchased by buver. Buver should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
<p>2</p>	<p>(1) 2000 International Thomas School Bus Vin #3363 - Will Need To Be Towed</p>	<p>Will Need To Be Towed  Unit #46  Conventional Style  Passenger: 71  Engine Size/Type: T444E  Engine In Front  Engine Problems: Radiator Needs Replacing &amp; Water Pump Is Leaking - Ran When Last Parked - Has Been Sitting For Several Years  Diesel  Has Battery  Current Condition Unknown  Automatic  Brakes: Air  Inspection Sticker Date: January 2020  Approx. Mileage (NOT ACTUAL): 109,079  Interior Condition: Fair  Interior Problems: Needs Cleaning - Some Torn Seats - Panel Missing - Missing Overpass Wiring  Harness Below Window - Surface Rust  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches - Some Rock Chips On Windshield - Peeling On Hood &amp; Cowl  Tires Condition: Fair</p> <p><b>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</b></p> <p><b>All defects and flaws with a vehicle will be the buyers responsibility once purchased by buver. Buver should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	

3	<p>(1) 1998 International Bluebird School Bus Vin #2342 - Will Need To Be Towed</p>	<p>Will Need To Be Towed  Unit #44  Conventional Style  Passenger: 71  Engine Size/Type: T444E  Engine In Front  Engine Problems: Will Not Run - Has Been Sitting For Several Years  Diesel  Has Battery, Dead  Does Not Run  Automatic  Brakes: Air  Inspection Sticker Date: January 2020  Approx. Mileage (NOT ACTUAL): 137,239  Interior Condition: Fair  Interior Problems: Needs Cleaning - Some Torn Seats  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches - Roof Needs Cleaning  Tires Condition: Fair  Tires Condition: Most Tires Are Fair - The Front Left Tire Is Poor &amp; Replacing Is Recommended</p> <p><b>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</b></p> <p><b>All defects and flaws with a vehicle will be the buyers responsibility once purchased by buver. Buver should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
4	<p>(1) 2001 International Bluebird School Bus Vin #3647 - Will Need To Be Towed</p>	<p>Will Need To Be Towed  Unit #51  Conventional Style  Passenger: 71  Engine Size/Type: T444E  Engine In Front  Engine Problems: Will Not Run - Has Been Sitting For Several Years  Diesel  Has Battery, Dead  Does Not Run  Automatic  Brakes: Air  Inspection Sticker Date: January 2020  Approx. Mileage (NOT ACTUAL): 103,709  Interior Condition: Fair  Interior Problems: Needs Cleaning - Some Torn Seats - Seats Worn - Seats Need Cleaning  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches - Crack On Lower Portion Of Windshield On Drivers Side  Tires Condition: Fair</p> <p><b>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</b></p> <p><b>All defects and flaws with a vehicle will be the buyers responsibility once purchased by buver. Buver should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	

5	<p>(1) 2003 International Bluebird School Bus Vin #6277 - Will Need To Be Towed</p>	<p>Will Need To Be Towed  Unit #53  Conventional Style  Passenger: 71  Engine Size/Type: T444E  Engine In Front  Engine Problems: Has Been Sitting For Several Years  Diesel  Has Battery, Dead  Current Condition Unknown  Automatic  Brakes: Air  Inspection Sticker Date: January 2020  Approx. Mileage (NOT ACTUAL): 112,324  Interior Condition: Fair  Interior Problems: Needs Cleaning - Some Torn Seats  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches - Minor Surface Rust On Rear - Rock Chips On Windshield  Tires Condition: Fair</p> <p><b>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</b></p> <p><b>All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buser should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
6	<p>(1) 2001 International Bluebird School Bus Vin #7476 - Will Need To Be Towed</p>	<p>Will Need To Be Towed  Unit #837  Conventional Style  Passenger: 16 + 3 Wheel Chair  Engine Size/Type: T444E  Engine In Front  Engine Problems: Engine Needs An Overhaul - Has Been Sitting For Several Years  Diesel  Has Battery, Dead  Does Not Run  Automatic  Brakes: Air  Inspection Sticker Date: December 2020  Approx. Mileage (NOT ACTUAL): 180,082  Has Wheel Chair Lift - Condition Unknown  Interior Condition: Fair  Interior Problems: Needs Cleaning - Some Torn Seats - Seats Are Worn  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches - Peeling On Rear Door - Rock Chips On Windshield - Peeling On Cowl &amp; Hood  Tires Condition: Fair</p> <p><b>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</b></p> <p><b>All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buser should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	

7	<p>(1) 2001 International Bluebird School Bus Vin #3646 - Will Need To Be Towed</p>	<p>Will Need To Be Towed  Unit #50  Conventional Style  Passenger: 71  Engine Size/Type: T444E  Engine In Front  Engine Problems: Has Oil Leak - Has Been Sitting For Several Years  Diesel  Has Battery, Dead  Current Condition Unknown  Automatic  Brakes: Air  Inspection Sticker Date: January 2020  Approx. Mileage (NOT ACTUAL): 95,914  Interior Condition: Fair  Interior Problems: Needs Cleaning - Some Torn Seats  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches - Roof Needs Cleaning - Rub On Right Rear Panel - Large Dent/Scratch On Left Lower Panel In Front Of Rear Wheel Well  Tires Condition: Fair</p> <p><b>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</b></p> <p><b>All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buser should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
8	<p>(1) 2001 International Bluebird School Bus Vin #7473 - Will Need To Be Towed</p>	<p>Will Need To Be Towed  Unit #834  Conventional Style  Passenger: 16 + 3 Wheel Chair  Engine Size/Type: DT466E  Engine In Front  Engine Problems: Engine Needs An Overhaul - Has Been Sitting For Several Years  Diesel  Has Battery, Dead  Does Not Run  Automatic  Brakes: Air  Inspection Sticker Date: December 2020  Approx. Mileage (NOT ACTUAL): 211,016  Has Wheel Chair Lift - Condition Unknown  Interior Condition: Fair  Interior Problems: Needs Cleaning - Minor Tears On Seats  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches - Peeling On Cowl &amp; Hood  Tires Condition: Fair</p> <p><b>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</b></p> <p><b>All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buser should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	

9	(1) 2001 International Bluebird School Bus Vin #3648 - Will Need To Be Towed	<p>Will Need To Be Towed  Unit #52  Conventional Style  Passenger: 71  Engine Size/Type: T444E  Engine In Front  Engine Problems: Engine Has No Power - Engine Needs An Overhaul - Has Been Sitting For Several Years  Diesel  Has Battery, Dead  Does Not Run  Automatic  Brakes: Air  Inspection Sticker Date: January 2020  Approx. Mileage (NOT ACTUAL): 113,632  Interior Condition: Fair  Interior Problems: Needs Cleaning - Worn  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches - Peeling On Cowl - Rockchip On Windshield - Needs Cleaning  Tires Condition: Fair</p> <p><b>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</b></p> <p><b>All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buser should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
10	(1) 2000 International Thomas School Bus Vin #3365	<p>Unit #48  Conventional Style  Passenger: 71  Engine Size/Type: T444E  Engine In Front  Engine Problems: Has Oil Leak - Has Been Sitting For Several Years  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Date: January 2020  Approx. Mileage (NOT ACTUAL):128,896  Interior Condition: Fair  Interior Problems: Needs Cleaning - Some Torn Seats - Seats Are Worn  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches - Scratch/Dent On Left Rear Panel - Peeling On Cowl &amp; Hood - Scratches On Windshield From Prior Bad Wiper  Tires Condition: Fair</p> <p><b>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</b></p> <p><b>All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buser should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	

<p>11</p>	<p>(1) 1999 Freightliner Bluebird School Bus Vin #3542 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #45 Conventional Style Passenger: 71 Engine Size/Type: Cummins Engine In Front Engine Problems: Bad Starter - Has Been Sitting For Several Years Diesel Has Battery, Dead Does Not Run Automatic Brakes: Air Inspection Sticker Date: April 2020 Approx. Mileage (NOT ACTUAL): 3,065 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Scratch/Dent On Panel Near Entry Door - Roof Needs Cleaning - 12th Window On Passenger Right Side Is Damaged/Cracked - Rockchips On Windshield Tires Condition: Fair Tire Problems: Front Left Tire Is Flat - Problem Unknown - Remainder Tires Are In Fair Condition With Air - Some May Need Additional Air</p> <p><b>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</b></p> <p><b>All defects and flaws with a vehicle will be the buyers responsibility once purchased by buver. Buver should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
-----------	--	---	---