






Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	<p><b>**All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes**</b></p> <p><b>IMPORTANT NOTICE FOR LA GRANGE ISD AUCTION:</b> <b>**All purchases will be subject to a 14% buver's premium. However, buvers paying by Cash, Cashier's Check, Money Order, Direct Deposit, or Wire Transfer as payment will receive a 3% discount on all purchases**</b></p> <p><b>*Social distancing will be enforced</b>  <b>*Customers will not be allowed inside to use the restrooms. No Exceptions!</b>  <b>*Please schedule an appointment prior to removal. Customers may be turned away without an appointment scheduled.</b>  <b>*We recommend wearing gloves and face mask for personal safety and health while on auction location</b></p> <p><b>Preview:</b> (Appointment Required – No Exceptions) Friday, October 9, 2020 (Hours Of Operation: 9:00 a.m. - 11:00 a.m.)</p> <p><b>Location (Lots T015/T199-T309S):</b> Transportation Facility, 815 S Vail St., La Grange TX 78945 <a href="#">Driving Directions</a></p> <p><b>Removal:</b> (Appointment Required – No Exceptions) Wednesday, October 14, 220 /Thursday, October 15, 2020/Friday, October 16, 2020 (Hours Of Operation: 8:30 a.m. - 2:00 p.m.)</p> <p><b>Preview &amp; Removal Contact:</b> Tammy Kubos 979-968-7020</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>	
T015	(1) 2001 Chevy Silverado 1500 Pickup Vin #6415	<p>Engine Size/Type: 5.3 V8  Engine In Front  Engine Problems: HVAC Works But Has A Freon Leak - Power Steering Pump Leaks - Uses Oil Gas  Has Battery, Dead  Runs  Automatic  Brakes: Hydraulic  Inspection Sticker Date: November 2020  Approx. Mileage (NOT ACTUAL): 231,496  Interior Condition: Fair  Interior Problems: Center Seat Console Is Damaged - Volume Knob Is Missing  Body Condition: Good to Fair  Body Problems: Some Dents &amp; Scratches  Tires Condition: Fair</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	

T199	(1) 1999 International Bluebird School Bus Vin #9931	<p>Unit #20 Conventional Style Passenger: 71 Engine Size/Type: 777E Engine In Front Engine Problems: Unknown Diesel Has Battery Runs Automatic Transmission Type/Condition: Good Brakes: Air Inspection Sticker Month: August 2021 Approx. Mileage (NOT ACTUAL): 110,896 Interior Condition: Fair Interior Problems: Torn Seats Body Condition: Fair Body Problems: Dents &amp; Scratches Tires Condition: Fair Tire Problems: Low</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
T206	(1) 2006 Bluebird School Bus Vin #7598	<p>Unit #3 Conventional Style Passenger: 71 Engine Size/Type: C-7 Engine In Front Engine Problems: Unknown Diesel Has Battery Runs Automatic Transmission Type/Condition: Good Brakes: Air Inspection Sticker Month: August 2021 Approx. Mileage (NOT ACTUAL): 107,369 Interior Condition: Fair Interior Problems: Torn Seats - Holes In Floor Body Condition: Fair Body Problems: Dents &amp; Scratches Tires Condition: Fair Tire Problems: Needs Front Tires</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	

T209	(1) 2009 Bluebird School Bus Vin #4502 - WILL NEED TO BE TOWED	<p>WILL NEED TO BE TOWED Unit #13 Conventional Style Passenger: 71 Engine Size/Type: C-7 CAT Engine In Front Engine Problems: Blowing Oil Diesel Has Battery Runs Automatic Transmission Type/Condition: Good Brakes: Air Inspection Sticker Month: August 2021 Approx. Mileage (NOT ACTUAL): 131,538 Interior Condition: Fair Interior Problems: Needs Cleaning Body Condition: Fair Body Problems: Dents &amp; Scratches Tires Condition: Fair Tire Problems: Needs Front Tires</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
T309S	(1) 2006 Bluebird School Bus Vin #4524 - WILL NEED TO BE TOWED	<p>WILL NEED TO BE TOWED Unit #22 Conventional Style Passenger: 36 Engine Size/Type: C-7 Engine In Front Engine Problems: Blowing Oil Diesel Has Battery Runs Automatic Transmission Type/Condition: Good Brakes: Air Inspection Sticker Month: August 2021 Approx. Mileage (NOT ACTUAL): 155,068 Interior Condition: Fair Interior Problems: Torn Seat Body Condition: Fair Body Problems: Dents &amp; Scratches Tires Condition: Fair Tire Problems: Low Tires</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	