







Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	<p>** All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes**</p> <p>IMPORTANT NOTICE FOR WHITE OAK ISD AUCTION: **All purchases will be subject to a 14% buver's premium. However, buvers paying by Cash, Cashier's Check, Money Order, Direct Deposit, or Wire Transfer as payment will receive a 3% discount on all purchases**</p> <p>*Social distancing will be enforced *Customers will not be allowed inside to use the restrooms. No Exceptions! *Please schedule an appointment prior to removal. Customers may be turned away without an appointment scheduled. *We recommend wearing gloves and face mask for personal safety and health while on auction location</p> <p>Preview Location: (Appointment Required – No Exceptions) Thursday, November 19, 2020 (Hours Of Operation: 8:00 a.m. – 4:30 p.m.)</p> <p>Location: White Oak ISD, 200 S. White Oak Road, White Oak, TX 75693 Driving Directions</p> <p>Removal: (Appointment Required – No Exceptions) Wednesday, December 2, 2020 /Thursday, December 3, 2020/Friday, December 4, 2020 (Hours Of Operation: 8:00 a.m. - 4:30 p.m.)</p> <p>Preview & Removal Contact: Stacy Anderson 903-291-2149</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>	
1	(1) 1999 Crown Victoria Sedan Vin #9103	<p>Passenger: 4 Engine Size/Type: 4.6L - V8 Engine In Front Engine Problems: Runs Rough Cold Gas Has Battery Runs Automatic Transmission Type Or Condition: Automatic - Fair Brakes: Hydraulic Inspection Sticker Date: August 2021 Approx. Mileage (NOT ACTUAL): 244,323 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Seats Have Tears - Rust Noted Throughout Body Condition: Fair Body Problems: Passenger Front Quarter Panel Has A Dent Tires Condition: Fair Tire Problems: Unknown Additional Information: Working Brake On Passenger Side - It Was A Former Driver's Ed Car</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

2	<p>(1) 1991 International School Bus - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #19 Conventional Passenger: 66 Engine Size/Type: 360 International Engine In Front Engine Problems: When Idling It Misses Diesel Has Battery Runs Automatic Transmission Type Or Condition: Automatic - Fair Brakes: Air Inspection Sticker Date: July 2021 Approx. Mileage (NOT ACTUAL): 135,119 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Seats Have Tears - Rust Noted Throughout Body Condition: Fair Body Problems: Needs Cleaning Tires Condition: Fair Tire Problems: Unknown Additional Information: Brakes Are Bad</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
3	<p>(1) 1984 International School Bus - Vin #8506</p>	<p>Unit #15 Conventional Passenger: 71 Engine Size/Type: 360 International Engine In Front Engine Problems: Unknown Diesel Has Battery Runs Automatic Transmission Type Or Condition: Automatic - Fair Brakes: Air Inspection Sticker Date: February 2021 Approx. Mileage (NOT ACTUAL): 119,355 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Seats Have Tears - Rust Noted Throughout Body Condition: Fair Body Problems: Unknown Tires Condition: Fair Tire Problems: Unknown Additional Information: Exhaust Smokes</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

4	(1) 1997 Carpenter School Bus Vin #2977 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #38 Conventional Passenger: 36 Engine Size/Type: 5.9 Cummins Engine In Front Engine Problems: Smokes Diesel Has Battery Runs Automatic Transmission Type Or Condition: Automatic - Fair Brakes: Air Inspection Sticker Date: November 2020 Approx. Mileage (NOT ACTUAL): 58,952 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Seats Have Tears - Rust Noted Throughout Body Condition: Fair Body Problems: Peeling Paint & Rust On Exterior Tires Condition: Fair Tire Problems: Unknown Additional Information: A/C Blows Cold - Has 4 Extra Tires</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
5	(1) 1987 International School Bus Vin #5023	<p>Unit #17 Conventional Passenger: 71 Engine Size/Type: 360 International Engine In Front Engine Problems: Unknown Diesel Has Battery Runs Automatic Transmission Type Or Condition: Automatic - Fair Brakes: Air Inspection Sticker Date: August 2021 Approx. Mileage (NOT ACTUAL): 191,922 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Seats Have Tears - Rust Noted Throughout Body Condition: Fair Body Problems: Surface Scratches Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

6	(1) 1975 Chevrolet Van Vin #6163	<p>Engine Size/Type: 350 Chevy Auto Engine In Front Engine Problems: Unknown Gas Has Battery Runs Automatic Transmission Type Or Condition: Automatic - Fair Brakes: Hydraulic Inspection Sticker Date: July 2018 Approx. Mileage (NOT ACTUAL): 51,018 Interior Condition: Poor Interior Problems: Needs Cleaning - Some Seats Have Tears - Rust Noted Throughout - Lots Of Wear & Tear Body Condition: Poor Body Problems: Rust & Holes Throughout Tires Condition: Poor Tire Problems: Possibly Dry Rot Additional Information: Has Been Sitting For Several Years</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
7	(1) 1990 Chevrolet Pickup Truck Vin #8190 - Will Need To Ne Towed	<p>Will Need To Be Towed Engine Size/Type: 5.7L/V8 Engine In Front Engine Problems: Engine Smokes Gas Has Battery Runs Automatic Transmission Type Or Condition: Automatic - Fair Brakes: Hydraulic Inspection Sticker Date: February 2021 Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Poor Interior Problems: Needs Cleaning - Some Seats Have Tears - Rust Noted Throughout Body Condition: Poor Body Problems: Ding & Dents All Over - Front bumper Rusted - Scratches Tires Condition: Poor Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

8	(1) 1992 Ford E150 Cargo Van Vin #9350	<p> Passenger: 12 Engine Size/Type: 302 5L Engine In Front Engine Problems: Unknown Gas Has Battery Runs Automatic Transmission Type Or Condition: Automatic - Good Brakes: Hydraulic Inspection Sticker Date: August 2021 Approx. Mileage (NOT ACTUAL): 140,384 Interior Condition: Poor Interior Problems: Needs Cleaning - Some Seats Have Tears Body Condition: Fair Body Problems: Windshield Cracked - Bumper Dented - Scratches Tires Condition: Poor Tire Problems: Unknown Additional Information: Front End Needs New Bushings </p> <p> There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. </p> <p> **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** </p> <p>- Current Condition Unknown</p>	
9	(1) Century Campershell	<p>- Current Condition Unknown</p>	