








Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	<p>** All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes**</p> <p>IMPORTANT NOTICE FOR SAN ANTONIO ISD: **There will be a 13% Buyer's Premium Added to All Buyer's Total for Each Item Purchased.**</p> <p>*Social distancing will be enforced *Customers will not be allowed inside to use the restrooms. No Exceptions! *Please schedule an appointment prior to removal. Customers may be turned away without an appointment scheduled. *We recommend wearing gloves and face mask for personal safety and health while on auction location.</p> <p>Preview Location: (By Appointment Only-Mandatory-No Exceptions) Thursday, December 10, 2020 (Hours Of Operation: 9:30 a.m. - 1:30 p.m.)</p> <p>Location: SAISD Transportation, 418 Roland Road, San Antonio, TX 78210 Driving Directions</p> <p>Removal: (By Appointment Only-Mandatory-No Exceptions) Tuesday, December 15, 2020 /Wednesday, December 16, 2020/Thursday, December 17, 2020/Friday, December 18, 2020 (Hours Of Operation: 9:30 a.m. - 1:30 p.m.)</p> <p>Preview & Removal Contact: Richard Cavazos Or Miguel Flores 210-354-9314</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>	


<p>1</p>	<p>(1) 2008 International School Bus Vin #6770 Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #261 Model: Handicap Conventional Style Passenger: 35 + 1 Wheelchair Space Engine Size/Type: Maxx Force DT Engine In Front Engine Problems: Bad Engine Note: Marked Bad Fuel Gauge Diesel Has Battery, Dead Does Not Run Brakes: Hydraulic Inspection Sticker Date: September 2020 Approx. Mileage (NOT ACTUAL): 171,166 Has Wheelchair Lift Condition Unknown Interior Condition: Fair Interior Problems: Needs Cleaning Some Torn Seats Body Condition: Fair Body Problems: Oxidized Paint Surface Scratches Scratch/Dent On Right Rear Side Dent On Rear Bumper Damage On Right Side Wheel Well Scratch/Dent On Lower Panel Left Side Some Peeling On Front Roof Tires Condition: Fair Additional Information: Camera System Is Being Removed Prior To Removal</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Current Condition Unknown</p>	
----------	--	---	---

2	<p>(1) 2007 Chevy Malibu Sedan Vin #7384 Needs To Be Towed</p>	<p>Will Need To Be Towed Unit #4045 Passenger: 4 Engine In Front Engine Problems: Unknown Gas Has Battery Does Not Run Automatic Brakes: Hydraulic Inspection Sticker Date: April 2020 Mileage: Unknown Interior Condition: Fair Interior Problems: Needs Cleaning Body Conditions: Poor Body Problems: Vehicle Has Been Rear Ended - Major Body Damage In Rear - Hail Damage On Hood - Air Bags Are Not Deployed Tires Condition: Fair Tire Problems: Unknown</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Current Condition Unknown</p>	
3	<p>(1) 2004 International School Bus Vin #0558</p>	<p>Unit #256 Model: CE200 Conventional Style Passenger: 71 Engine Size/Type: T444E Engine In Front Engine Problems: Unknown Diesel Has Battery - Recommend Bring Cables To Jump Runs Automatic Brakes: Air Inspection Sticker Date: August 2021 Approx. Mileage (NOT ACTUAL): 196,769 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Scratch On Right Rear - Missing Front Mirrors Tires Condition: Good To Fair</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Current Condition Unknown</p>	

<p>4</p>	<p>(1) 2004 International School Bus Vin #0549</p>	<p>Unit #255 Model: CE200 Conventional Style Passenger: 71 Engine Size/Type: T444E Engine In Front Engine Problems: Unknown Diesel Has Battery - Recommend Bring Cables To Jump Runs Automatic Brakes: Air Inspection Sticker Date: October 2021 Approx. Mileage (NOT ACTUAL): 175,629 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Minor Rub On Right Rear Panel - Black Glue Stuck On Left Rear Panel - Some Peeling - Rock Chip On Windshield Tires Condition: Good To Fair</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Current Condition Unknown</p>	
----------	--	--	---

<p>5</p>	<p>(1) 2009 International School Bus Vin #6010 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #319 Model: CE300 Conventional Style Passenger: 71 Engine Size/Type: Maxx Force DT Engine In Front Engine Problems: Bad Engine - Possibly Missing Parts Diesel Has Battery, Dead Runs Automatic Brakes: Air Inspection Sticker Date: June 2021 Approx. Mileage (NOT ACTUAL): 148,249 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches -Roof Has (6) Wave Appearance Dents On Right Side - (1) Scratch/Dent On Right Side Under #3 Window - Dent On Right Rear Corner Panel Tires Condition: Fair Additional Information: Camera Equipment Will Be Removed Prior To Removal</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Current Condition Unknown</p>	
----------	--	--	---

<p>6</p>	<p>(1) 2009 International School Bus Vin #0611 - Will Need To Be Towed</p>	<p>Will Need To Be Towed - Wrecked Unit #335 Model: CE300 Conventional Style Passenger: 71 Engine Size/Type: Maxx Force DT Engine In Front Engine Problems: Will Turn Over - Damage To Engine Unknown Diesel Has Battery Will Turn Over Automatic Brakes: Air Inspection Sticker Date: July 2021 Approx. Mileage (NOT ACTUAL): 160,988 Interior Condition: Fair Interior Problems: Needs Cleaning - Missing (14) Lower Seat Pads Body Condition: Poor Body Problems: Wrecked On Front Right - Windshield Cracked - (1) Passenger Window Cracked - Some Scratches - Rub Guard's Have Dents On Left Rear = Hood Damaged - Front Bumper Damaged - Right Front Tire Will Need To Be Replaced - Right Front Wheel Well Damaged - Dent/Scratch Right Front Near Entry Door & On Roof Tires Condition: Good To Fair</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Current Condition Unknown</p>	
----------	--	--	---

7	(1) 2008 Ford F350 Pickup Truck Vin #7571	<p>Unit #9993 Model: Super Duty XL Dually Conventional Style Passenger: 6 Engine Size/Type: 6.8L Engine In Front Engine Problems: Unknown Gas Has Battery Runs Automatic Brakes: Hydraulic Inspection Sticker Date: January 2021 Approx. Mileage (NOT ACTUAL): 103,772 Interior Condition: Fair Interior Problems: Needs Cleaning - Normal Wear & Tear - Work Truck Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Small Chip On Right Wheel Well Tires Condition: Good Additional Information: Heavy Duty Front Bumper - Set Up In Bed For Gooseneck - Some Dents On Bumper - Has Headache Rack</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Current Condition Unknown</p>	
---	---	--	---