






Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	<p><b>**All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes**</b></p> <p><b>**All purchases will be subject to a 9% buyer's premium. There Will Be A 3% Administrative Fee For Purchases Not Made By Cash, Cashier's Check, Money Order, Wire Transfer or Direct Deposit.**</b></p> <p><b>*Social distancing will be enforced</b>  <b>*Customers will not be allowed inside to use the restrooms. No Exceptions!</b>  <b>*We recommend wearing gloves and face mask for personal safety and health while on auction location.</b></p> <p><b>Preview:</b> (No Appointment Necessary) Tuesday, November 17, 2020 (Hours Of Operation: 9:00 a.m. – 3:00 p.m.)</p> <p><b>Location:</b>18810 Juergen Rd., Tomball, TX 77377 <a href="#">Driving Directions.</a></p> <p><b>Removal</b>(No Appointment Necessary) Monday, November 23, 2020/Tuesday, November 24, 2020 (Hours Of Operation: 9:30 a.m. – 3:00 p.m.)</p> <p><b>Preview &amp; Removal Contacts:</b> Lemons Auctioneers 281-357-4977</p> <p><b>Anyone Entering The Lemons Auctioneers Premises Is Required To Show A Drivers License, State Issued ID, Passport, Or Equivalent. No merchandise will be released without proper ID and a Letter of Authorization to release merchandise to Buyer's Representative. This form may be found under the Resources Tab of OnlinePros.com. Please email release form to <a href="mailto:lemons@lemonsauctioneers.com">lemons@lemonsauctioneers.com</a> or fax: (281) 357-4974.</b></p>	
1	(1) 2006 Ford Taurus SE Sedan Vin #8096	<p>Unit #S-36  Conventional  Passenger: 5  Engine Size/Type: 3.0L  Engine Problems: Unknown - See Video  Gas  Has Battery, Dead  Runs  Automatic  Brakes: Hydraulic  Inspection Sticker Date: July 2020  Approx. Mileage (NOT ACTUAL): 81,027  Interior Condition: Fair  Interior Problems: Normal Wear - Needs Cleaning - (1) Pane On Passenger Side Needs Reattaching - Back Seat Has Some Wear &amp; Blemishes  Body Condition: Fair  Body Problems: Left Side Rear Door Lock Not Engaged - Oxidized Paint - Surface Scratches - Damage On Front Bumper  Tires Condition: Fair</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	

2	<p>(1) 2008 Chevy 2500 Heavy Duty Crew Cab Pickup Truck Vin #0718</p>	<p>Unit #WW-04  Conventional  Passenger: 6  Engine Size/Type: 6.0L  Engine Problems: Unknown - See Video  Gas  Has Battery, Dead  Runs  Automatic  Brakes: Hydraulic  Inspection Sticker Date: September 2020  Approx. Mileage (NOT ACTUAL): 106,631  Interior Condition: Fair To Poor  Interior Problems: Work Truck - Paint Stains - Needs Cleaning - Upholstery Worn - Crack On Dash  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches  Tires Condition: Good  Additional Information: Has Tool Box - A/C Blew Cool At Time Of Inspection</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
3	<p>(1) 2008 Chevy Silverado Pickup Truck Vin #0325</p>	<p>Unit #MD-02  Conventional  Passenger: 3  Engine Size/Type: 4.8L  Engine Problems: Unknown - See Video  Gas  Has Battery, Dead  Runs  Automatic  Brakes: Hydraulic  Inspection Sticker Date: January 2020  Approx. Mileage (NOT ACTUAL): 113,880  Interior Condition: Poor  Interior Problems: Torn Drivers Seat - Work Truck - Worn Upholstery - Tears On Center Console - Minor Crack On Dash - Needs Cleaning  Body Condition: Fair  Body Problems: Surface Scratches - Minor Dents  Tires Condition: Fair  Additional Information: Has Tool Box</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	

4	(1) 2013 Ford Sedan Vin #4866	<p>Unit #P-33  Model: Police Interceptor  Conventional  Passenger: 5  Engine Size/Type: 3.5L  Engine Problems: Unknown - See Video  Gas  Has Battery, Dead  Runs  Automatic  Brakes: Hydraulic  Inspection Sticker Date: October 2019  Approx. Mileage (NOT ACTUAL): 103,024  Interior Condition: Fair  Interior Problems: Center Console Has Been Removed - Rear Seat Has Been Removed  Body Condition: Fair  Body Problems: Surface Scratches -Peeling On Front Bumper - Oxidized Paint  Tires Condition: Fair</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
5	(1) 2008 Crown Victoria Sedan Vin #2385	<p>Unit #P-78  Conventional  Passenger: 5  Engine Size/Type: 4.6L  Engine Problems: Unknown - See Video  Gas  Has Battery, Dead  Runs  Automatic  Brakes: Hydraulic  Inspection Sticker Date: December 2019  Approx. Mileage (NOT ACTUAL): 78,441  Interior Condition: Fair  Interior Problems: Needs Cleaning - Hole In Dash (Thumb Sized) - Police Seat In Rear  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Rust On Trunk - Surface Scratches - Hole In Roof Where Police Antenna Was Mounted - Some Peeling Paint - Rub On Rear Bumper  Tires Condition: Fair  Additional Information: A/C Worked At Time Of Inspection  Auctioneer Recommends Preview</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	