




| Lot Number | Title | Description | Thumbnail |
|------------|-------------------------------|--|---|
| 0 | Preview & Removal Information | <p>**All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes**</p> <p>IMPORTANT NOTICE FOR THE BEAUMONT ISD AUCTION: **There Will Be No Buyer's Premium Added To The Buyer's Total For Each Item Purchased. However, There Will Be A 3% Convenience Fee On All Credit Card Purchases**</p> <p>*Social distancing will be enforced *Customers will not be allowed inside to use the restrooms. No Exceptions! *Please schedule an appointment prior to removal. Customers may be turned away without an appointment scheduled. *We recommend wearing gloves and face mask for personal safety and health while on auction location.</p> <p>Preview: (By Appointment Only-Mandatory-No Exceptions) Monday, December 14, 2020 (Hours Of Operation: 8:00 A.M. - 4:30 P.M.)</p> <p>Location 1: (Lots 2-84/403A-412A) Transportation Center – North Lot, 1950 Cottonwood, Beaumont, TX 77703 Driving Directions Removal: (By Appointment Only-Mandatory-No Exceptions) Thursday, December 17, 2020 /Friday, December 18, 2020 (Hours Of Operation: 8:00 A.M. - 4:30 P.M.) Preview & Removal Contact: Mack McLendon 409-617-5623 Or Robert McManus 409-617-5631</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>Location 2: (Lots 85 & 413A) Milam Transportation Center, 3255 Milam Street, Beaumont, TX 77701 Driving Directions Removal: (By Appointment Only-Mandatory-No Exceptions) Thursday, December 17, 2020 /Friday, December 18, 2020 (Hours Of Operation: 8:00 A.M. - 4:30 P.M.) Preview & Removal Contact: Mack McLendon 409-617-5623 Or Robert McManus 409-617-5631</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buver should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>Location 3: (Lots 1011-M-123) Maintenance And Operations, 1650 Caldwell, Beaumont, TX 77703 Driving Directions Removal: (By Appointment Only-Mandatory-No Exceptions) Thursday, December 17, 2020 /Friday, December 18, 2020 (Hours Of Operation: 8:00 A.M. - 4:30 P.M.) Preview & Removal Contact: Steve Tatum (LOTS A-2 – M-123 ONLY) 409-617-5676 or Eric Payne (LOTS 1011-1017 ONLY) 409-617-7005</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> |  |




| | | | |
|---|--|--|---|
| | | <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> | |
| 2 | (1) 2008 Thomas School Bus Vin #2914 - Will Need To Be Towed | Will Need To Be Towed Unit #2008 Model: Saf-T-Liner EF Transit Passenger: 54 Engine Size/Type: 5.9 Cummins Engine In Front Engine Problems: Unknown Diesel Does Not Have Battery Runs Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Has Wheelchair Lift - Condition Unknown Interior Condition: Fair Interior Problems: Unknown Body Condition: Good Body Problems: Unknown Tires Condition: Fair Tire Problems: Unknown - Current Condition Unknown |  |
| 4 | (1) 2009 Thomas School Bus Vin #6342 - Will Need To Be Towed | Will Need To Be Towed Unit #2009 Model: Saf-T-Liner EF Transit Passenger: 54 Engine Size/Type: 5.9 Cummins Engine In Front Engine Problems: Unknown Diesel Does Not Have Battery Runs Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Has Wheelchair Lift - Condition Unknown Interior Condition: Fair Interior Problems: Unknown Body Condition: Good Body Problems: Unknown Tires Condition: Fair Tire Problems: Unknown - Current Condition Unknown |  |

| | | | |
|----|---|---|---|
| 7 | (1) 2005 Thomas School Bus Vin #9628 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #7 Model: Saf-T-Liner EF Transit Passenger: 54 Engine Size/Type: Caterpillar Engine In Front Engine Problems: Unknown Diesel Does Not Have Battery Runs Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Has Wheelchair Lift - Condition Unknown Interior Condition: Fair Interior Problems: Unknown Body Condition: Good Body Problems: Unknown Tires Condition: Fair Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |
| 31 | (1) 2006 Thomas School Bus Vin #7086 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #31 Model: Saf-T-Liner EF Transit Passenger: 54 Engine Size/Type: 5.9 Cummins Engine In Front Engine Problems: Unknown Diesel Does Not Have Battery Runs Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Has Wheelchair Lift - Condition Unknown Interior Condition: Fair Interior Problems: Unknown Body Condition: Good Body Problems: Unknown Tires Condition: Fair Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |
| 32 | (1) 2006 Thomas School Bus Vin #7085 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #32 Model: Saf-T-Liner EF Transit Passenger: 54 Engine Size/Type: 5.9 Cummins Engine In Front Engine Problems: Unknown Diesel Does Not Have Battery Runs Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Has Wheelchair Lift - Condition Unknown Interior Condition: Fair Interior Problems: Unknown Body Condition: Good Body Problems: Unknown Tires Condition: Fair Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |

| | | | |
|----|---|--|---|
| 33 | (1) 2006 Thomas School Bus Vin #7084 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #33 Model: Saf-T-Liner EF Transit Passenger: 54 Engine Size/Type: 5.9 Cummins Engine In Front Engine Problems: Unknown Diesel Does Not Have Battery Runs Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Has Wheelchair Lift - Condition Unknown Interior Condition: Fair Interior Problems: Unknown Body Condition: Good Body Problems: Unknown Tires Condition: Fair Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |
| 34 | (1) 2007 Thomas School Bus Vin #0896 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #34 Model: Saf-T-Liner EF Transit Passenger: 54 Engine Size/Type: 5.9 Cummins Engine In Front Engine Problems: Unknown Diesel Does Not Have Battery Runs Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Has Wheelchair Lift - Condition Unknown Interior Condition: Fair Interior Problems: Needs Major Cleaning Body Condition: Good Body Problems: Unknown Tires Condition: Fair Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |
| 35 | (1) 2007 Thomas School Bus Vin #0897 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #35 Model: Saf-T-Liner EF Transit Passenger: 54 Engine Size/Type: 5.9 Cummins Engine In Front Engine Problems: Unknown Diesel Does Not Have Battery Runs Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Has Wheelchair Lift - Condition Unknown Interior Condition: Fair Interior Problems: Needs Major Cleaning Body Condition: Good Body Problems: Unknown Tires Condition: Fair Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |


| | | | |
|----|---|---|---|
| 75 | (1) 2006 Thomas School Bus Vin #3471 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #75 Model: Saf-T-Liner EF Transit Passenger: 35 Engine Size/Type: Caterpillar Engine In Front Engine Problems: Radiator Missing - Parts Bus Diesel Does Not Have Battery Runs Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Has Wheelchair Lift - Condition Unknown Interior Condition: Fair Interior Problems: Needs Major Cleaning Body Condition: Good Body Problems: Unknown Tires Condition: Fair Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |
| 77 | (1) 2006 Thomas School Bus Vin #3474 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #77 Model: FS-65 Conventional Passenger: 35 Engine Size/Type: Caterpillar Engine In Front Engine Problems: Unknown Diesel Does Not Have Battery Runs Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Fair Interior Problems: Unknown Body Condition: Good Body Problems: Unknown Tires Condition: Fair Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |
| 78 | (1) 2006 Thomas School Bus Vin #3472 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #78 Model: FS-65 Conventional Passenger: 35 Engine Size/Type: Caterpillar Engine In Front Engine Problems: Unknown Diesel Does Not Have Battery Runs Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Fair Interior Problems: Unknown Body Condition: Good Body Problems: Unknown Tires Condition: Fair Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |




| | | | |
|----|--|---|---|
| 79 | (1) 2006 Thomas School Bus Vin #3475 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #79 Model: FS-65 Conventional Passenger: 35 Engine Size/Type: Caterpillar Engine In Front Engine Problems: Unknown Diesel Does Not Have Battery Runs Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Fair Interior Problems: Unknown Body Condition: Good Body Problems: Unknown Tires Condition: Fair Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |
| 80 | (1) 2006 Thomas School Bus Vin #3476 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #80 Model: FS-65 Conventional Passenger: 35 Engine Size/Type: Caterpillar Engine In Front Engine Problems: Unknown Diesel Does Not Have Battery Runs Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Fair Interior Problems: Unknown Body Condition: Good Body Problems: Unknown Tires Condition: Fair Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |
| 81 | (1) 2006 Thomas School Bus Vin #3470 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #81 Model: FS-65 Conventional Passenger: 35 Engine Size/Type: Caterpillar Engine In Front Engine Problems: Unknown Diesel Does Not Have Battery Runs Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Fair Interior Problems: Unknown Body Condition: Good Body Problems: Unknown Tires Condition: Fair Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |




| | | | |
|----|---|---|---|
| 82 | (1) 2007 Thomas School Bus Vin #6305 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #82 Model: FS-65 Conventional Passenger: 35 Engine Size/Type: Caterpillar Engine In Front Engine Problems: Unknown Diesel Does Not Have Battery Runs Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Fair Interior Problems: Unknown Body Condition: Good Body Problems: Unknown Tires Condition: Fair Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |
| 83 | (1) 2007 Thomas School Bus Vin #6306 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #83 Model: FS-65 Conventional Passenger: 35 Engine Size/Type: Caterpillar Engine In Front Engine Problems: Unknown Diesel Does Not Have Battery Runs Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Fair Interior Problems: Unknown Body Condition: Good Body Problems: Unknown Tires Condition: Fair Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |
| 84 | (1) 2007 Thomas School Bus Vin #6307 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #84 Model: FS-65 Conventional Passenger: 35 Engine Size/Type: Caterpillar Engine In Front Engine Problems: Unknown Diesel Does Not Have Battery Runs Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Fair Interior Problems: Unknown Body Condition: Good Body Problems: Unknown Tires Condition: Fair Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |




| | | | |
|------|--|--|---|
| 85 | (1) 2008 Thomas School Bus Vin #5348 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #85 Model: FS-65 Conventional Passenger: 35 Engine Size/Type: Mercedes Engine In Front Engine Problems: Unknown Diesel Does Not Have Battery Runs Automatic Transmission Type Or Condition: Allison - Problems With Wiring @ Fuse Box Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Good Interior Problems: Unknown Body Condition: Good Body Problems: Unknown Tires Condition: Fair Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |
| 403A | (1) 2008 Thomas School Bus Vin #3339 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #403A Model: Saf-T-Liner HDX Transit Passenger: 52 Engine Size/Type: Caterpillar Engine In Rear Engine Problems: Unknown Diesel Does Not Have Battery Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Poor Interior Problems: Unknown Body Condition: Fair Body Problems: Unknown Tires Condition: Poor Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |
| 404A | (1) 2008 Thomas School Bus Vin #8679 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #404A Model: Saf-T-Liner HDX Transit Passenger: 44 Engine Size/Type: Mercedes Engine In Rear Engine Problems: Unknown - Towed Diesel Runs Does Not Have Battery Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Poor Interior Problems: Unknown Body Condition: Fair Body Problems: Unknown Tires Condition: Poor Tire Problems: Front Tire Flat</p> <p>- Current Condition Unknown</p> |  |




| | | | |
|------|--|--|---|
| 406A | (1) 2008 Thomas School Bus Vin #8681 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #406A Model: Saf-T-Liner HDX Transit Passenger: 44 Engine Size/Type: Mercedes Engine In Rear Engine Problems: Will Not Start - Needs Power Module @ Back Of Bus Diesel Runs Does Not Have Battery Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Poor Interior Problems: Unknown Body Condition: Fair Body Problems: Unknown Tires Condition: Poor Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |
| 407A | (1) 2008 Thomas School Bus Vin #8682 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #407A Model: Saf-T-Liner HDX Transit Passenger: 44 Engine Size/Type: Mercedes Engine In Rear Engine Problems: Unknown Diesel Runs Does Not Have Battery Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Poor Interior Problems: Unknown Body Condition: Fair Body Problems: Unknown Tires Condition: Poor Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |
| 408 | (1) 2008 Thomas School Bus Vin #8683 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #408A Model: Saf-T-Liner HDX Transit Passenger: 44 Engine Size/Type: Mercedes Engine In Rear Engine Problems: Unknown Diesel Runs Does Not Have Battery Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Poor Interior Problems: Unknown Body Condition: Fair Body Problems: Unknown Tires Condition: Poor Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |




| | | | |
|------|--|--|---|
| 409A | (1) 2008 Thomas School Bus Vin #8684 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #409A Model: Saf-T-Liner HDX Transit Passenger: 44 Engine Size/Type: Mercedes Engine In Rear Engine Problems: Unknown Diesel Runs Does Not Have Battery Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Poor Interior Problems: Unknown Body Condition: Fair Body Problems: Unknown Tires Condition: Poor Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |
| 410A | (1) 2008 Thomas School Bus Vin #8685 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #410A Model: Saf-T-Liner HDX Transit Passenger: 44 Engine Size/Type: Mercedes Engine In Rear Engine Problems: Unknown Diesel Runs Does Not Have Battery Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Poor Interior Problems: Unknown Body Condition: Fair Body Problems: Unknown Tires Condition: Poor Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |
| 411A | (1) 2008 Thomas School Bus Vin #8686 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #411A Model: Saf-T-Liner HDX Transit Passenger: 44 Engine Size/Type: Mercedes Engine In Rear Engine Problems: Unknown - Will Not Start - Needs Power Module @ Rear Of Bus Diesel Runs Does Not Have Battery Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Poor Interior Problems: Unknown Body Condition: Fair Body Problems: Unknown Tires Condition: Poor Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |

| | | | |
|------|--|--|---|
| 412A | (1) 2008 Thomas School Bus Vin #8687 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #412A Model: Saf-T-Liner HDX Transit Passenger: 44 Engine Size/Type: Mercedes Engine In Rear Engine Problems: Unknown Diesel Runs Does Not Have Battery Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Poor Interior Problems: Unknown Body Condition: Fair Body Problems: Unknown Tires Condition: Poor Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |
| 413A | (1) 2008 Thomas School Bus Vin #8688 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #413A Model: Saf-T-Liner HDX Transit Passenger: 44 Engine Size/Type: Mercedes Engine In Rear Engine Problems: Unknown Diesel Runs Does Not Have Battery Automatic Transmission Type Or Condition: Allison Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Poor Interior Problems: Unknown Body Condition: Fair Body Problems: Unknown Tires Condition: Poor Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |
| 1011 | (1) 2009 Ford Crown Victoria Sedan Vin #5902 | <p>Unit #P1011 Passenger: Unknown Engine Size/Type: V-8 Engine In Front Engine Problems: Unknown Gas Runs Has Battery Automatic Transmission Type Or Condition: Automatic Brakes: Hydraulics Inspection Sticker Date: May 2021 Approx. Mileage (NOT ACTUAL): 89,261 Interior Condition: Fair Interior Problems: Needs Cleaning Body Condition: Fair Body Problems: Rust - Scratches Tires Condition: Fair Tire Problems: 50% Tread Left</p> <p>- Current Condition Unknown</p> |  |

| | | | |
|------|---|--|---|
| 1013 | (1) 2009 Ford Crown Victoria Sedan Vin #5900 | Unit #P1013 Passenger: Unknown Engine Size/Type: V-8 Engine In Front Engine Problems: Unknown Gas Runs Has Battery Automatic Transmission Type Or Condition: Automatic Brakes: Hydraulics Inspection Sticker Date: May 2021 Approx. Mileage (NOT ACTUAL): 107,172 Interior Condition: Good Interior Problems: Unknown Body Condition: Fair Body Problems: Dents - Rust - Scratches Tires Condition: Fair Tire Problems: 50% Tread Left - Current Condition Unknown |  |
| 1016 | (1) 2010 Ford Crown Victoria Sedan Vin #8607 | Unit #P1016 Passenger: Unknown Engine Size/Type: V-8 Engine In Front Engine Problems: Unknown Gas Runs Has Battery Automatic Transmission Type Or Condition: Automatic Brakes: Hydraulics Inspection Sticker Date: May 2021 Approx. Mileage (NOT ACTUAL): 77,451 Interior Condition: Fair Interior Problems: Small Rip On Drivers Seat Body Condition: Good Body Problems: Scratches - Minor Damage Tires Condition: Fair Tire Problems: 60% Tread Left - Current Condition Unknown |  |
| 1017 | (1) 2010 Ford Crown Victoria Sedan Vin #8608 | Unit #P1017 Passenger: Unknown Engine Size/Type: V-8 Engine In Front Engine Problems: Unknown Gas Runs Has Battery Automatic Transmission Type Or Condition: Automatic Brakes: Hydraulics Inspection Sticker Date: May 2021 Approx. Mileage (NOT ACTUAL): 96,967 Interior Condition: Good Interior Problems: Unknown Body Condition: Fair Body Problems: Scratches - Rust Tires Condition: Fair Tire Problems: 40% Tread Left - Current Condition Unknown |  |

| | | | |
|------|--|---|---|
| A-2 | (1) 2006 Chevy Pickup Truck Vin #7202 - Will Need To Be Towed | <p>Will Need To Be Towed Unit #A-2 Model: Unknown Passenger: Unknown Engine Size/Type: V-8 Engine In Front Engine Problems: Unknown - Does Not Run Gas Does Not Run Has Battery, Dead Automatic Transmission Type Or Condition: Unknown Brakes: Hydraulics Inspection Sticker Date: March 2020 Approx. Mileage (NOT ACTUAL): 147,958 Interior Condition: Fair Interior Problems: Torn Seats - Needs Cleaning Body Condition: Fair Body Problems: Small Dents - No Tailgate Tires Condition: Good Tire Problems: Unknown</p> <p>- Current Condition Unknown</p> |  |
| M-25 | (1) 2008 Chevy Malibu Sedan Vin #7200 | <p>Unit #M-25 Passenger: Unknown Engine Size/Type: V-6 3.5L Engine In Front Engine Problems: Unknown - Starts & Runs Gas Runs Has Battery Automatic Transmission Type Or Condition: Automatic Brakes: Hydraulics Inspection Sticker Date: July 2021 Approx. Mileage (NOT ACTUAL): 112,995 Interior Condition: Good Interior Problems: Normal Wear & Tear - Some Stains Body Condition: Fair Body Problems: Small Dent On Rear Bumper - Minor Rust Spots On Roof Tires Condition: Good Tire Problems: Unknown Additional Information: Low Brake Fluid Sensor Was Replaced But Indicator Light Is Still On - Some Minor Motor Oil Leaks At Gaskets</p> <p>- Current Condition Unknown</p> |  |
| M-26 | (1) 2003 Chevy Malibu Sedan Vin #2205 | <p>Unit #M-26 Passenger: Unknown Engine Size/Type: V-6 Engine In Front Engine Problems: Unknown - Starts & Runs Gas Runs Has Battery Automatic Transmission Type Or Condition: Automatic Brakes: Hydraulics Inspection Sticker Date: July 2021 Approx. Mileage (NOT ACTUAL): 109,908 Interior Condition: Fair Interior Problems: Normal Wear & Tear - Upholstery Stained - Headliner Torn Body Condition: Fair Body Problems: Scratches - Surface Rust - Small Dent On Right Front Fender Tires Condition: Good Tire Problems: Unknown Additional Information: Will Need Battery Booster To Start</p> <p>- Current Condition Unknown</p> |  |

| | | | |
|-------|--|---|---|
| M-82 | (1) 1991 Chevy Cargo Van Vin #9675 | Unit #M-82 Passenger: Unknown Engine Size/Type: V-8 Engine In Front Engine Problems: Unknown Gas Runs Has Battery Automatic Transmission Type Or Condition: Automatic With O/D Brakes: Hydraulics Inspection Sticker Date: February 2021 Approx. Mileage (NOT ACTUAL): 256,089 Interior Condition: Fair Interior Problems: Needs Cleaning Body Condition: Poor Body Problems: Bad Paint - Surface Rust Tires Condition: Fair Tire Problems: Passenger Front May Need Replacing Soon Additional Information: Roof Has Surface Rust - Runs Good But Cosmetics Are Not Good - Current Condition Unknown |  |
| M-100 | (1) 1997 Ford Ranger Pickup Truck Vin #5860 | Unit #M-100 Passenger: Unknown Engine Size/Type: 2.3L 4 Cylinder Gasoline Engine In Front Engine Problems: Unknown Gas Runs Has Battery Standard Transmission Type Or Condition: Unknown Brakes: Hydraulics Inspection Sticker Date: July 2021 Approx. Mileage (NOT ACTUAL): 162,065 Interior Condition: Fair Interior Problems: Normal Wear & Tear - Roof Liner Coming Loose At Windshield Body Condition: Fair Body Problems: Scratches - Surface Rust - Normal Wear & Tear Tires Condition: Fair Tire Problems: Very Slow Leak In Right Rear Tire Additional Information: A/C Blower Not Working - Current Condition Unknown |  |
| M-110 | (1) 1999 Chevy Cargo Van Vin #2867 | Unit #M-110 Model: Express 3500 Passenger: Unknown Engine Size/Type: V-8 Engine In Front Engine Problems: Unknown Gas Runs Has Battery Automatic Transmission Type Or Condition: Automatic Brakes: Hydraulics Inspection Sticker Date: March 2020 Approx. Mileage (NOT ACTUAL): 266,399 Interior Condition: Poor Interior Problems: Torn Seats - Missing Arm Rests - Door Panels Missing - Door Lever Inside On Driver's Side Is Broken Body Condition: Poor Body Problems: Peeling Paint - Scratches - Dents - Loose Fender Tires Condition: Poor Tire Problems: Front Tires Are Worn /br> Additional Information: Leak At Power Steering Pump - Current Condition Unknown |  |

| | | | |
|-------|---|---|---|
| M-113 | (1) 2002 Chevy Pickup Truck Vin #6777 | Unit #M-113 Passenger: Unknown Engine Size/Type: V-8 Engine In Front Engine Problems: Slight Oil Leak On Engine Gasket Gas Runs Has Battery Automatic Transmission Type Or Condition: Shifts Good Brakes: Hydraulics Inspection Sticker Date: December 2020 Approx. Mileage (NOT ACTUAL): 124,023 Interior Condition: Fair Interior Problems: Seats Worn - Needs New Windshield - Steering Wheel Cover Breaking Down Body Condition: Fair Body Problems: Small Dents & Scratches - Small Tears In Both Sides Of The Bed By Cab Tires Condition: Fair Tire Problems: Rear Tires Are Pretty new - Front Tires Have Lots Of Tread Life Remaining Additional Information: Headache Rack - Sides Boxes & Tool Box Included - Current Condition Unknown |  |
| M-116 | (1) 2003 Chevy Cargo Van Vin #6107 | Unit #M-116 Passenger: Unknown Engine Size/Type: V-8 Engine In Front Engine Problems: Small Leak On Oil Pan Gasket Gas Runs Has Battery Automatic Transmission Type Or Condition: Automatic Brakes: Hydraulics Inspection Sticker Date: December 2020 Approx. Mileage (NOT ACTUAL): 126,829 Interior Condition: Fair Interior Problems: Needs Drivers Side Arm Rest On Door Body Condition: Fair Body Problems: Peeling paint - Scratches Tires Condition: Fair Tire Problems: Unknown Additional Information: Requires Battery Booster To Start - Leak At Power Steering - Current Condition Unknown |  |
| M-123 | (1) 2006 Chevy Pickup Truck Vin #9904 | Unit #M-123 Passenger: Unknown Engine Size/Type: V-8 Engine In Front Engine Problems: Check Engine Light Is On Indicating P 0449 Gas Runs Has Battery Automatic Transmission Type Or Condition: Automatic With O/D Brakes: Hydraulics Inspection Sticker Date: December 2020 Approx. Mileage (NOT ACTUAL): 157,767 Interior Condition: Fair Interior Problems: Drivers Seat Worn - Tears In Vinyl Body Condition: Fair Body Problems: Dent In Lower Bed On Right Side - Front Bumper Dented & Fairing Is Missing - Minor Scrapes On Left Side Of Bed Tires Condition: Fair Tire Problems: Slow Leak In One Rear Tire Additional Information: Has Receiver Hitch - Cold A/C - Good Tread Depth On Tires - Current Condition Unknown |  |