















Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	<p>**All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes**</p> <p>IMPORTANT NOTICE FOR SOUTHSIDE ISD ONLINE AUCTION: **All purchases will be subject to a 14 buver's premium. There Will Be A 3% Fee For All Purchases Not Made By Cash, Cashier's Check, Direct Deposit, Money Order & Wire Transfer*</p> <p>**Lemons Auctioneers LLC and Online Pros conduct their banking with Woodforest National Bank. You may go to any Woodforest location and directly deposit your payment into our account or conduct a wire transfer from your account to ours. (DEPOSIT CASH ONLY) **Please call our office for Bank Information**Phone: 800-243-1113 or 281-357-4977. You will need to call us once this transaction has been made into our account. We will need the amount of the transaction, full name, and auction information. Your paid receipt will be sent to you manually once the transaction has been verified by an auction representative. You may contact the office during our business hours at (800) 243-1113 where a representative will be able to assist you or send us an email at: lemons@lemonsauctioneers.com if you need assistance on a weekend day. **</p> <p>CDC COVID-19 GUIDELINES WILL BE OBSERVED – WEAR A MASK AND STAY AT LEAST 6 FT. APART.</p> <p>Preview: (By Appointment Only-Mandatory-No Exceptions) Thursday, January 28, 2021 (Hours Of Operation: 8:00 A.M. - 2:30 P.M.) Location: Southside ISD Warehouse, 3223 S. Loop 1604 E., San Antonio, TX, 78264 Driving Directions Removal Dates & Times: (By Appointment Only-Mandatory-No Exceptions) Wednesday, February 3, 2021/Thursday, February 4, 2021/Friday, February 5, 2021 (Hours Of Operation: 8:00 A.M. - 2:30 P.M.) Preview & Removal Contact: Robert Garcia 210-529-1797 email: Roberto.garcia@southsideisd.org</p> <p>Lifting Equipment Available For Lot #'s (1-21/61-75)</p> <p>Lot #'s (22/34-60) <i>There Will Be No Manpower, No Employee Assistance Or Equipment Available For Removal. Buyer Must Remove All Lots In Their Entirety. Buyer Is Solely Responsible For Loading & Unloading, Bring Own Manpower, Equipment, Dollies Or Other Adequate Moving Devices or Equipment, Etc. To Remove Items. Buyer Must Have Adequate Transportation To Move Purchased Items.</i></p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buver's responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracv of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p>	


1	(1) Gravely 272Z Riding Zero Turn Lawn Mower	Model: 992053 Gas (Approx. 72" Cut) Does Not Run Tires Need Air No Key *Recommend Preview* - Current Condition Unknown	
2	(1) Rhino TW60 Mower Deck	(Approx. 60" Cut) Some Rust Possible Parts Missing *Recommend Preview* - Current Condition Unknown	
3	(1) Ford New Holland 3430 Front End Loader Tractor	Bucket (Approx. 60" x 23") 3 Point PTO Diesel Some Rust & Dents Does Not Work - No Key - Needs Repair Tag #4441 Both Tires Needs To Be Replaced On Left Front Rim Is Bad *Recommend Preview* - Current Condition Unknown	
4	(1) Rhino Batwing Mower	(Approx. 70" x 128") Some Rust Has Extra Auger Possible Parts Missing *Recommend Preview* - Current Condition Unknown	
5	(1) Gravely 160 Zero Turn Riding Lawn Mower - Recommend Parts Unit	(Approx. 60" Cut) (1) Tire & Wheel Loose On Unit All Tires Are Flat Missing Parts Needs Repair No Key Gas - Current Condition Unknown	
6	(Lot) Tractor Implements	(1) Disc (Approx. 60" Wide) (1) Scoop - Current Condition Unknown	
7	(Lot) A/C Equipment Parts	Type & Qty Of Items Unknown Mfg. Puron, Rheem & Carrier - Current Condition Unknown	
8	(Lot) A/C Equipment	Payne A/C Unit Possible Parts Missing Mfg. (Approx. 2) Carrier - Puron - A/C Heat Pump - Current Condition Unknown	
9	(1) A/C Unit	Mfg. Rheem - Current Condition Unknown	


10	(Lot) A/C Units	(Approx. 2) Trane XL16i Model #'s Located In Pictures - Current Condition Unknown	
11	(Lot) Heat Package	(Approx. 2) Mfg. Unknown Model: FV4BNF003 - Current Condition Unknown	
12	(Lot) A/C Units & Parts	(Approx. 2) Carrier Puron A/C Unit High Efficiency Heat Pumps (1) Rudd A/C Components Misc. A/C Parts - Current Condition Unknown	
13	(1) Trane Odyssey A/C Unit	Model: TTA240F400BA Complete Unknown Manufactured 06/2013 - Current Condition Unknown	
14	(Lot) Mower & Drag Mats	(1) Pro Reel Mower (Approx. 2) Metal Drag Mats (Baseball Fields) - Some Rust - Current Condition Unknown	
15	(Lot) A/C Unit & Blower	(1) Mc Quay A/C Unit (1) Greenheck Fan Blower - Missing Side Cover - Model: SCE3-24-615-A2-0-X - Current Condition Unknown	
16	(Lot) Metal Fence Panels	(Approx. 15) (Approx. 7'8" Tall x 67" Wide) Possible Other Sizes - Current Condition Unknown	
17	(1) Scoreboard	Mfg. Spectrum Disassembled Football - Current Condition Unknown	
18	(1) Metal Panels	Qty Unknown Various Sizes - Current Condition Unknown	
19	(1) John Deere Lawn Spreader	Model: LPBS3WD - Current Condition Unknown	
20	(Lot) Reel Mower Parts W/Cart	 - Current Condition Unknown	
21	(Lot) Welding Carts	(Approx. 2) - Current Condition Unknown	
22	(Lot) McQuay A/C Units - Parts Units Only	(1) McQuay A/C Unit - Parts Missing (1) McQuay A/C Unit - Copeland Compressor - Parts Missing - Model: ACZ045AS27 *Recommend Preview* - Buyer's Responsibility For Removal - Easy Access - Current Condition Unknown	


23	(1) 2011 Chevy Malibu Vin #7604	<p> Passenger: 4 Engine Problems: Unknown Gas Has Battery Runs Automatic Hydraulic Brakes Inspection Sticker Date: December 2020 Approx. Mileage (NOT ACTUAL): 120,064 Interior Condition: Fair Interior Problems: Needs Minor Cleaning Body Condition: Fair Body Problems: Surface Scratches - Scratches On Left Passenger Door - Tint Has Bubbles In Back Rear Window Tires Condition: Fair Tire Problems: Unknown </p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyer's responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>- Current Condition Unknown</p>	
24	(1) 2008 Ford Crown Victoria Vin #9321	<p> Unit #310 Passenger: 4 Engine Size/Type: 4.6L Engine Problems: Unknown Gas Has Battery Runs Automatic Hydraulic Brakes Inspection Sticker Date: July 2021 Approx. Mileage (NOT ACTUAL): 26,296 Interior Condition: Fair Interior Problems: Torn Drivers Seat - Middle Console Missing - Needs Cleaning Body Condition: Fair Body Problems: Peeling Paint - Dents On Drivers Side Back Corner Panel - Minor Rust Tires Condition: Fair Tire Problems: Unknown </p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyer's responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>- Current Condition Unknown</p>	


25	(1) 2009 Dodge Charger Vin #6993	<p>Unit #313 Model: Police Interceptor Passenger: 4 Engine Size/Type: 3.5 V6 Engine Problems: Unknown Gas Has Battery, Dead Runs Automatic Hydraulic Brakes Inspection Sticker Date: April 2020 Approx. Mileage (NOT ACTUAL): 167,861 Interior Condition: Fair Interior Problems: Center Console Missing - Exposed Wires - Torn Drivers Seat - Needs Cleaning Body Condition: Fair Body Problems: Surface Scratches - Hole In Panel On Drivers Door Where Spotlight Was Mounted - Minor Oxidized Paint On Door Panels - Damage On Front Bumper Where Bumper Guard Was Mounted Tires Condition: Fair Tire Problems: Unknown</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyer's responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>- Current Condition Unknown</p>	
26	(1) 2009 Dodge Charger Vin #9203	<p>Unit #314 Model: Police Interceptor Passenger: 4 Engine Size/Type: 3.5 V6 Engine Problems: Unknown Gas Has Battery Runs Automatic Hydraulic Brakes Inspection Sticker Date: February 2021 Approx. Mileage (NOT ACTUAL): 89,921 Interior Condition: Fair Interior Problems: Center Console Missing - Needs Cleaning Body Condition: Fair Body Problems: Hole In Panel On Drivers Door Where Spotlight Was Mounted - Some Scratches Where Decals Were Removed - Broken & Scratched Blinker Light Cover On Passenger Front Side - Minor Surface Rust Tires Condition: Fair Tire Problems: Unknown</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyer's responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>- Current Condition Unknown</p>	








27	(1) 2008 Ford Ranger Pickup Truck Vin #4270	<p> Passenger: 2 Engine Size/Type: 2.3L Engine Problems: Unknown Gas Has Battery Runs Automatic Hydraulic Brakes Inspection Sticker Date: February 2020 Approx. Mileage (NOT ACTUAL): 126,507 Interior Condition: Fair Interior Problems: Needs Cleaning - Torn Drivers Seat - Rock Chip In Windshield Body Condition: Fair Body Problems: Rust On Driver & Passenger Side Where Magnets Were Tires Condition: Fair Tire Problems: Unknown </p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyer's responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>- Current Condition Unknown</p>	
28	(1) 2014 Ford F150 4x4 Pickup Truck Vin #3005	<p> Unit #320 Passenger: 2 Engine Size/Type: 3.7L Engine Problems: Bad Alternator Gas Has Battery Runs Automatic Hydraulic Brakes Inspection Sticker Date: December 2020 Approx. Mileage (NOT ACTUAL): 143,178 Interior Condition: Fair Interior Problems: Needs Cleaning - Torn Drivers Seat Steering Wheel Worn Body Condition: Fair Body Problems: Front Bumper Dented & Coming Off - Dent & Scratches On Passenger Door - Deep Scratches On Rear Bumper - Rear Drivers Side Tail Light Broken @ Bottom Tires Condition: Fair Tire Problems: Unknown </p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyer's responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>- Current Condition Unknown</p>	

29	(1) 2004 Thomas Freightliner School Bus Vin #4227 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #34 Conventional Passenger: 77 Engine In Front Engine Size/Type: Inline 6 Engine Problems: Unknown Engine Problems - Will Not Run Diesel Has Battery, Dead Does Not Run Automatic Air Brakes Inspection Sticker Date: March 2020 Approx. Mileage (NOT ACTUAL): 209,088 Interior Condition: Fair To Poor Interior Problems: Drivers Seat In Poor Condition - Most Seats Are Worn & Need Cleaning - Some Seats Are Patched Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Rock Chip On Windshield Tires Condition: Fair Tire Problems: Unknown</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyer's responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>- Current Condition Unknown</p>	
----	---	---	---

30	(1) 2010 International School Bus Vin #6157	<p>Unit #16 Conventional Passenger: 77 Engine In Front Engine Size/Type: Maxx Force 7 Engine Problems: Ran When Last Parked - Needs Batteries Diesel Does Not Have Batteries Current Running Condition Unknown Automatic Air Brakes Inspection Sticker Date: April 2020 Approx. Mileage (NOT ACTUAL): Unable To Read Interior Condition: Fair Interior Problems: Needs Cleaning - Normal Wear & Tear - Some Seats Torn Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Dent/Scratch On Right Rear - Stop Sign Removed On Left Rear - Scratches On Left Side Lower Panel Tires Condition: Fair Tire Problems: Unknown</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyer's responsibility once purchased by buver. Buver should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracv of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>- Current Condition Unknown</p>	
----	--	---	---

31	(1) 2010 International School Bus Vin #6151	<p>Will Need To Be Towed Unit #24 Conventional Passenger: 77 Engine In Front Engine Size/Type: Maxx Force 7 Engine Problems: Will Need Repair - Missing Air Brake Compressor Diesel Has Battery, Dead Does Not Run Automatic Air Brakes Inspection Sticker Date: April 2020 Approx. Mileage (NOT ACTUAL): Unable To Read Interior Condition: Fair Interior Problems: Needs Cleaning - Normal Wear & Tear - Some Seats Torn Body Condition: Fair Body Problems: Oxidized Paint - Slight Indention On Rear Bumper - Stop Sign Removed On Left Side Tires Condition: Fair Tire Problems: Unknown</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyer's responsibility once purchased by buver. Buver should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>- Current Condition Unknown</p>	
----	--	---	---

32	(1) 2012 International School Bus Vin #5882 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #7 Conventional Passenger: 27 Passenger + 2 Wheelchair Engine In Front Engine Size/Type: Maxx Force 7 Engine Problems: Has Fuel Issue Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: February 2021 Approx. Mileage (NOT ACTUAL): 175,857 Has Wheel Chair Lift - Condition Unknown Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats Body Condition: Fair Body Problems: Oxidized Paint - Stop Sign Removed On Left Side Tires Condition: Fair Tire Problems: Unknown</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyer's responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>- Current Condition Unknown</p>	
----	---	--	---

33	(1) 2012 International School Bus Vin #5885	<p>Will Need To Be Towed Unit #6 Conventional Passenger: 27 Passenger + 2 Wheelchair Engine In Front Engine Size/Type: Maxx Force 7 Engine Problems: Unknown Diesel Has Battery. Dead Runs Automatic Air Brakes Inspection Sticker Date: March 2020 Approx. Mileage (NOT ACTUAL): Unable To Read Has Wheel Chair Lift - Condition Unknown Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Stop Sign Removed On Left Rear & Front Tires Condition: Poor Tire Problems: Unit Has Been Sitting - Possibly Has Dry Rot</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyer's responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>- Current Condition Unknown</p>	
34	(Lot) Double Sided Bookcases & Cubbies	<p>(Approx. 2) Portable & Stationary</p> <p>- Current Condition Unknown</p>	
35	(Lot) Double Sided Cubbies	<p>(Approx. 4) Portable & Stationary</p> <p>- Current Condition Unknown</p>	
36	(Lot) Cubbies	<p>(Approx. 3) Single Sided (1) Double Sided</p> <p>- Current Condition Unknown</p>	
37	(1) Double Sided Cubby	<p>Portable</p> <p>- Current Condition Unknown</p>	
38	(1) Portable Cold Storage	<p>Mfg. Ranserve By Randell (Approx. 60") W/Tray Racks No Sneeze Guard</p> <p>- Current Condition Unknown</p>	
39	(1) 5 Well Steam Table W/Tray Racks & Understorage	<p>Mfg. Ranserve By Randell (Approx. 72") Model Unknown</p> <p>- Current Condition Unknown</p>	

40	(Lot) Copiers & Misc.	(1) Xerox Work Center 5890 (1) Xerox Work Center 5335 (1) Xerox Collator - Current Condition Unknown	
41	(Lot) Dry Racks On Portable Cart	(Approx. 13) Plastic - Current Condition Unknown	
42	(Lot) Student & Pre-K Furniture	Includes: Plastic Chairs - Tumble Forms - Sofa (Damaged) - (Approx. 2) Teachers Chairs - Open Front Student Desk (Metal) - Current Condition Unknown	
43	(1) Carter Hoffman 2 Door Warming Cabinet	Model: PH183-0351 Marked "Does Not Work" Bottom Door Does Not Close 120V - Current Condition Unknown	
44	(Lot) Computer Table & Hutch	(1) Computer Table (1) Hutch - Current Condition Unknown	
45	(1) Computer Table W /Hutch	Hutch Is Missing Doors - Current Condition Unknown	
46	(1) Wood Bookcase	Portable - Current Condition Unknown	
47	(Lot) Bookcase & Cabinet	(1) Double Sided Bookcase - Portable (1) Cabinet - Mfg. Reynolds - Current Condition Unknown	
48	(Lot) Office Chairs	(Approx. 16) Various Types & Colors - Current Condition Unknown	
49	(Lot) Portable Tray Racks	(Approx. 2) Mfg. Maxrack (Approx. 26" Opening) - Current Condition Unknown	
50	(1) Round Table	Pre-K Sized - Current Condition Unknown	
51	(Lot) Rectangle Computer Tables	(Approx. 3) - Current Condition Unknown	
52	(Lot) Computer Tables	(Approx. 9) Square - Current Condition Unknown	
53	(1) Hutch Top	 - Current Condition Unknown	

54	(Lot) Rectangle Tables	(Approx. 2) - Current Condition Unknown	
55	(Lot) Rectangle Tables	(Approx. 2) - Current Condition Unknown	
56	(Lot) Square Tables	(Approx. 5) - Current Condition Unknown	
57	(1) Portable Partition	- Current Condition Unknown	
58	(1) Metal Shipping Container	(Approx. 8' x 35') Contents Are NOT Included Single Entry Damage On Entry Door Wood Floor Decking May Have Roof Leak Gashed On Side Of Unit Roof Condition Unknown *Preview Recommended* Must Have Flex Loader Or Other Vehicle To Properly Remove Container. Buyer Solely Responsible For Removal. - Current Condition Unknown	
59	(1) Metal Shipping Container	Mfg. Fruehauf (Approx. 8' x 40') Contents Are NOT Included Single Entry Damage On Entry Doors Wood Floor Decking - Will Need Some Floor Repair Unable To Inspect Roof - Possible Leaks Damage On Front Panel *Preview Recommended* Must Have Flex Loader Or Other Vehicle To Properly Remove Container. Buyer Solely Responsible For Removal. - Current Condition Unknown	
60	(1) Metal Shipping Container	Mfg. Fruehauf (Approx. 8' x 40') Contents Are NOT Included Wood Floor Decking - Some Damage - Will Need Repair Unable To Inspect Roof - Possible Leaks *Preview Recommended* Must Have Flex Loader Or Other Vehicle To Properly Remove Container. Buyer Solely Responsible For Removal. - Current Condition Unknown	
61	(Lot) Floor Machines	(1) Chariot Windsor iScrub20 Floor Machine (1) Power-Flite Super High Performance Carpet Machine (1) Minuteman Floor Buffer - Current Condition Unknown	
62	(Lot) Bathroom Stall Partitions	Disassembled Qty Unknown New In Box - Current Condition Unknown	
63	(Lot) Haws Water Fountains	(Approx. 3) New In Box Model: 1409 (Approx. 55" x 18") - Current Condition Unknown	

64	(1) Garland Double Convection Oven	Model: The Master Stationary Gas - Current Condition Unknown	
65	(1) Garland Double Convection Oven	Model: The Master Stationary Gas - Current Condition Unknown	
66	(1) Carter Hoffmann 5 Well Steam Table	(Approx.. 76-1/2" x 29") Portable Missing (2) Knobs Model: CC5761CB76S 208V - 60hz - Single Phase - Current Condition Unknown	
67	(1) Carter Hoffmann 5 Well Steam Table	(Approx.. 76-1/2" x 29") Portable Has All Knobs On Unit Model: CC5761CB76S 208V - 60hz - Single Phase - Current Condition Unknown	
68	(1) Carter Hoffmann Cold Storage Cabinet	Portable Model: CC45RF 120V - 60hz - Single Phase - Current Condition Unknown	
69	(1) Carter Hoffmann Cold Storage Cabinet	Portable Model: CC45RF 120V - 60hz - Single Phase - Current Condition Unknown	
70	(Lot) Floor Tile	(Approx. 8" x 8") Mfg. Quarry Tile Company Various Colors Qty Unknown - Current Condition Unknown	
71	(Lot) Gymnasium Flooring Remnants	(Approx. 1 Pallet) (Approx. 39-1/2" x 15-1/2") - Current Condition Unknown	
72	(Lot) Assorted Tile & Misc.	(Approx. 2 Pallets) Rubber Base Various Sizes & Colors Ceramic Tile Misc. - Current Condition Unknown	
73	(Lot) Assorted Tile & Misc.	(Approx. 17 Boxes) Rubber Base Standard Excelon (Approx. 12" x 12") Various Colors Cat #57518031 Mfg. Armstrong Flooring Commercial - Current Condition Unknown	
74	(Lot) Shelving & Misc.	(Approx. 2 Pallets) Shelving - Particle Board (1 Roll) Rubber Padding - Current Condition Unknown	

75	(Lot) Indoor- Outdoor Carpet Remnants	(1 Roll) (Approx. 12' Wide) Length Unknown - Current Condition Unknown	
----	--	---	--