







Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	<p>**All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes**</p> <p>IMPORTANT NOTICE FOR CY-FAIR ISD ONLINE AUCTION: **All purchases will be subject to a 14% buver's premium. There Will Be A 3% Fee For All Purchases Not Made By Cash, Cashier's Check, Direct Deposit, Money Order & Wire Transfer*</p> <p>**Lemons Auctioneers LLC and Online Pros conduct their banking with Woodforest National Bank. You may go to any Woodforest location and directly deposit your payment into our account or conduct a wire transfer from your account to ours. (DEPOSIT CASH ONLY) **Please call our office for Bank Information**Phone: 800-243-1113 or 281-357-4977. You will need to call us once this transaction has been made into our account. We will need the amount of the transaction, full name, and auction information. Your paid receipt will be sent to you manually once the transaction has been verified by an auction representative. You may contact the office during our business hours at (800) 243-1113 where a representative will be able to assist you or send us an email at: lemons@lemonsauctioneers.com if you need assistance on a weekend day. **</p> <p>CDC COVID-19 GUIDELINES WILL BE OBSERVED – WEAR A MASK AND STAY AT LEAST 6 FT. APART.</p> <p>Preview: (By Appointment Only-Mandatory-No Exceptions) Thursday, March 4, 2021 (Hours Of Operation: 9:30 A.M. - 12:30 P.M.) Location: Charlotte Davis Burns Science Resource Center, 11206 Telge Road, Cypress, TX 77429 Driving Directions Removal Dates & Times: (By Appointment Only-Mandatory-No Exceptions) Wednesday, March 10, 2021/Thursday, March 11, 2021/Friday, March 12, 2021 (Hours Of Operation: 9:30 A.M. - 12:30 P.M.) *No Cash Payments On Site* Preview & Removal Contact: Stephanie Burke 281-517-6367</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buvers responsibility once purchased by buver. Buver should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p>	


<p>1</p>	<p>(1) 1998 International Bluebird School Bus Vin #1495</p>	<p>Unit #703 Model: 3800 Passenger: 71 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): 172,726 Interior Condition: Fair Interior Problems: Needs Cleaning - Drivers Seat Starting To Tear - Some Seats Are Torn Body Condition: Fair Body Problems: Peeling & Oxidized Paint - Some Chipped Paint - Some Rust - Surface Scratches, Dents & Rust - Scratches On Rear Bumper - Rear Emergency Door Damaged Above Hinge Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
----------	---	--	---


<p>2</p>	<p>(1) 1998 International Bluebird School Bus Vin #1490</p>	<p>Unit #683 Model: 3800 Passenger: 71 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: February 2021 Approx. Mileage (NOT ACTUAL): 151,302 Interior Condition: Fair Interior Problems: Needs Cleaning - Drivers Seat Torn - Some Torn Seats - Some Rust On Floorboard Body Condition: Fair Body Problems: Peeling & Oxidized Paint - Stop Sign Faded - Surface Scratches, Dents & Rust - Some Minor Scratches On Rear Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
----------	---	--	---


<p>3</p>	<p>(1) 1998 International Bluebird School Bus Vin #1498</p>	<p>Unit #709 Model: 3800 Passenger: 71 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: February 2021 Approx. Mileage (NOT ACTUAL): 115,007 Interior Condition: Fair Interior Problems: Needs Cleaning - Drivers Seat Torn - Some Torn Seats - Soft Spot In Aisle @ Seat #6 Body Condition: Fair Body Problems: Peeling & Oxidized Paint - Surface Scratches, Dents & Rust - Minor Rust & Scratches On Front & Rear Bumper - Some Scratches @ "Diesel" Gas Door Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
----------	---	--	---


<p>4</p>	<p>(1) 1998 International Bluebird School Bus Vin #1471</p>	<p>Unit #694 Model: 3800 Passenger: 71 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery, Dead Runs Automatic Air Brakes Inspection Sticker Date: December 2020 Approx. Mileage (NOT ACTUAL): 162,869 Interior Condition: Fair Interior Problems: Needs Cleaning - Drivers Seat Torn - Some Torn Seats - Soft Spot In Aisle @ Seat #6 Body Condition: Fair Body Problems: Peeling & Oxidized Paint - Surface Scratches, Dents & Rust - Minor Dent On Drivers Side Between Bus # & "School Bus" - Minor Scratches On Drivers Side Rear Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
----------	---	---	---


<p>5</p>	<p>(1) 1998 International Bluebird School Bus Vin #1484</p>	<p>Unit #684 Model: 3800 Passenger: 71 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: November 2021 Approx. Mileage (NOT ACTUAL): 129,298 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats - Some Rust On Floorboard Body Condition: Fair Body Problems: Peeling & Oxidized Paint - Small Crack On Windshield Under Wiper Blade - Minor Rust On Front Bumper - Small Dent, Rust & Scratches On Passenger Side Rear Bumper - Damage To Passenger Side Rear Corner Panel Close To Back Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
----------	---	---	---


<p>6</p>	<p>(1) 1998 International Bluebird School Bus Vin #1496</p>	<p>Unit #705 Model: 3800 Passenger: 71 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: February 2021 Approx. Mileage (NOT ACTUAL): 155,394 Interior Condition: Fair Interior Problems: Needs Cleaning - Torn Drivers Seat - Some Torn Seats - Rust On Floorboard Body Condition: Fair Body Problems: Peeling & Oxidized Paint - Scratches Under "Diesel" Door - Minor Rust & Scratches On Front & Rear Bumper - Damage To Passenger Side Rear Corner Panel In Front Of Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
----------	---	--	---


<p>7</p>	<p>(1) 1998 International Bluebird School Bus Vin #1493</p>	<p>Unit #695 Model: 3800 Passenger: 71 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: September 2021 Approx. Mileage (NOT ACTUAL): 167,786 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats Body Condition: Fair Body Problems: Peeling & Oxidized Paint - Surface Scratches, Dents & Rust - Minor Rust On Rear Bumper - Minor Damage On Passenger Side Rear Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
----------	---	--	---


<p>8</p>	<p>(1) 1998 International Bluebird School Bus Vin #1499</p>	<p>Unit #698 Model: 3800 Passenger: 71 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: December 2020 Approx. Mileage (NOT ACTUAL): 167,967 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats - Drivers Seat Torn Body Condition: Fair Body Problems: Peeling & Oxidized Paint - Surface Scratches, Dents & Rust - Minor Rust & Scratches On Rear Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
----------	---	--	---


<p>9</p>	<p>(1) 1998 International Bluebird School Bus Vin #1474</p>	<p>Unit #679 Model: 3800 Passenger: 71 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: February 2021 Approx. Mileage (NOT ACTUAL): 139,660 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats - Drivers Seat Starting To Tear Body Condition: Fair Body Problems: Peeling & Oxidized Paint - Surface Scratches, Dents & Rust - Minor Rust & Scratches On Front & Rear Bumper - Damage To Passenger Side Corner Panel Near Back Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
----------	---	---	---


<p>10</p>	<p>(1) 1998 International Bluebird School Bus Vin #1482</p>	<p>Unit #702 Model: 3800 Passenger: 71 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: October 2021 Approx. Mileage (NOT ACTUAL): 174,571 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats - Very Small Tear In Drivers Seat Body Condition: Fair Body Problems: Peeling & Oxidized Paint - Surface Scratches, Dents & Rust - Minor Rust & Scratches On Rear Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>11</p>	<p>(1) 1998 International Bluebird School Bus Vin #1481 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #697 Model: 3800 Passenger: 71 Engine Size/Type: DT466E Engine Problems: Bad Starter Diesel Has Battery Does Not Run Automatic Air Brakes Inspection Sticker Date: February 2021 Approx. Mileage (NOT ACTUAL): 159,639 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats - Torn Drivers Seat - Soft Spot In Aisle # Seat #6 Body Condition: Fair Body Problems: Peeling & Oxidized Paint - Surface Scratches, Dents & Rust - Minor Rust & Scratches On Front & Rear Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	--	---


<p>12</p>	<p>(1) 2005 IC School Bus Vin #5843</p>	<p>Unit #923 Model: CE300 Passenger: 71 Engine Size/Type: Maxx Force Engine Problems: Unknown Diesel Has Battery, Dead Runs Automatic Air Brakes Inspection Sticker Date: March 2020 Approx. Mileage (NOT ACTUAL): 167,413 Interior Condition: Fair Interior Problems: Needs Cleaning Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches, Dents & Rust Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>13</p>	<p>(1) 2005 IC School Bus Vin #5842</p>	<p>Unit #924 Model: CE300 Passenger: 71 Engine Size/Type: Maxx Force Engine Problems: Unknown Diesel Has Battery, Dead Runs Automatic Air Brakes Inspection Sticker Date: July 2020 Approx. Mileage (NOT ACTUAL): Panel Missing Interior Condition: Fair Interior Problems: Torn Drivers Seat - Odometer Panel Is Missing - Part Of Panel Covering A/C Cords Is Off But In Unit Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches, Dents & Rust - Small Dent In Middle Of Rear Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>14</p>	<p>(1) 2000 International Bluebird School Bus Vin #5512</p>	<p>Unit #757 Model: 3800 Passenger: 71 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: March 2021 Approx. Mileage (NOT ACTUAL): 188,484 Interior Condition: Fair Interior Problems: Needs Cleaning - Soft Spot All Down Aisle Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches, Dents & Rust - Minor Scratches & Rust On Rear Bumper - Minor Damage On Passenger Side Of Rear Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>15</p>	<p>(1) 2005 IC School Bus Vin #5848</p>	<p>Unit #931 Model: CE300 Passenger: 12 + 2 Wheelchair Spaces Engine Size/Type: 7.6L Engine Problems: Unknown Diesel Has Battery, Dead Runs Automatic Air Brakes Inspection Sticker Date: February 2020 Approx. Mileage (NOT ACTUAL): 79,798 Wheel Chair Lift: Yes - Condition: Unknown Interior Condition: Fair Interior Problems: Needs Cleaning Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches, Dents & Rust - IC Emblem Missing On Hood Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>16</p>	<p>(1) 2005 IC School Bus Vin #5837</p>	<p>Unit #900 Model: CE300 Passenger: 71 Engine Size/Type: Maxx Force Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: October 2020 Approx. Mileage (NOT ACTUAL): 183,891 Interior Condition: Fair Interior Problems: Needs Cleaning - Part Of Dash Cover Missing Close To Entry Door But Is In Unit Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches, Dents & Rust - Some Peeling Paint On Front Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	--	---


<p>17</p>	<p>(1) 1998 International Bluebird School Bus Vin #1494</p>	<p>Unit #708 Model: 3800 Passenger: 71 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: July 2021 Approx. Mileage (NOT ACTUAL): 125,949 Interior Condition: Fair Interior Problems: Needs Cleaning - Driver Seat Tearing - Seat In Back Are Worn And Some Have Tears Body Condition: Fair Body Problems: Peeling & Oxidized Paint - Surface Scratches, Dents & Rust Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>18</p>	<p>(1) 1997 International Bluebird School Bus Vin #9787</p>	<p>Unit #669 Model: 3800 Passenger: 71 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: May 2021 Approx. Mileage (NOT ACTUAL): 21,698 Interior Condition: Fair Interior Problems: Needs Cleaning - Driver Seat Tearing Body Condition: Fair Body Problems: Peeling, Chipped & Oxidized Paint - Surface Scratches, Dents & Rust - Scratches & Rust On Back Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>19</p>	<p>(1) 1998 International Bluebird School Bus Vin #1470</p>	<p>Unit #696 Model: 3800 Passenger: 71 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: April 2021 Approx. Mileage (NOT ACTUAL): 154,274 Interior Condition: Fair Interior Problems: Needs Cleaning - Driver Seat Tearing Body Condition: Fair Body Problems: Peeling & Oxidized Paint - Surface Scratches, Dents & Rust - Minor Scratches & Rust On Rear Bumper - Rear Emergency Door Does Not Close All The Way Tires Condition: Fair Tire Problems: Unknown Additional Information: Radio Works</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>20</p>	<p>(1) 1998 International Bluebird School Bus Vin #1473</p>	<p>Unit #690 Model: 3800 Passenger: 71 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: March 2021 Approx. Mileage (NOT ACTUAL): 146,641 Interior Condition: Fair Interior Problems: Needs Cleaning - Driver Seat Torn - Minor Damage To Seats In Back Body Condition: Fair Body Problems: Peeling & Oxidized Paint - Surface Scratches, Dents & Rust - Scratches & Rust On Rear Bumper - Damage To Passenger Side Rear Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	--	---


<p>21</p>	<p>(1) 1998 International Bluebird School Bus Vin #1497</p>	<p>Unit #701 Model: 3800 Passenger: 71 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: October 2021 Approx. Mileage (NOT ACTUAL): 185,367 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats Body Condition: Fair Body Problems: Peeling & Oxidized Paint - Surface Scratches, Dents & Rust - Minor Scratches & Rust On Rear Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	--	---


<p>22</p>	<p>(1) 1998 International Bluebird School Bus Vin #1472</p>	<p>Unit #700 Model: 3800 Passenger: 71 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: May 2021 Approx. Mileage (NOT ACTUAL): 179,522 Interior Condition: Fair Interior Problems: Needs Cleaning - Minor Tears In Some Seats In Back Body Condition: Fair Body Problems: Peeling & Oxidized Paint - Surface Scratches, Dents & Rust - Damage To Drivers Side Rear Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	--	---


<p>23</p>	<p>(1) 2000 International Bluebird School Bus Vin #5490</p>	<p>Unit #740 Model: 3800 Passenger: 71 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: January 2021 Approx. Mileage (NOT ACTUAL): 154,686 Interior Condition: Fair Interior Problems: Needs Cleaning - Torn Drivers Seat - Some Torn Seats Body Condition: Fair Body Problems: Peeling & Oxidized Paint - Surface Scratches, Dents & Rust - Minor Rust & Scratches On Rear Bumper - Some Paint Is Chipped Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>24</p>	<p>(1) 2000 International Bluebird School Bus Vin #0143</p>	<p>Unit #785 Model: 3800 Passenger: 71 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: March 2021 Approx. Mileage (NOT ACTUAL): 168,314 Interior Condition: Fair Interior Problems: Needs Cleaning - Floorboard Bad @ Drivers Seat - Some Torn Seats Body Condition: Fair Body Problems: Minor Oxidized Paint - Surface Scratches, Dents & Rust - Indention In Rear Bumper On Drivers & Passenger Side Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>25</p>	<p>(1) 2000 International Thomas School Bus Vin #0151</p>	<p>Unit #790 Model: 3800 Passenger: 71 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: April 2021 Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Fair Interior Problems: Needs Cleaning - Minor Tears In Drivers Seat Body Condition: Fair Body Problems: Minor Peeling Paint - Surface Scratches, Dents & Rust - Indention In Rear Bumper On Drivers & Passenger Side - Rear Emergency Door Does Not Close All The Way Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	--	---


<p>26</p>	<p>(1) 2000 International Bluebird School Bus Vin #5503</p>	<p>Unit #743 Model: 3800 Passenger: 71 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: February 2021 Approx. Mileage (NOT ACTUAL): 155,576 Interior Condition: Fair Interior Problems: Needs Cleaning -Soft Spot In Aisle @ Seat #9 Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches, Dents & Rust - Minor Rust & Scratches On Rear Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	--	---


<p>27</p>	<p>(1) 2000 International Bluebird School Bus Vin #5519</p>	<p>Unit #742 Model: 3800 Passenger: 71 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: March 2021 Approx. Mileage (NOT ACTUAL): 140,319 Interior Condition: Fair Interior Problems: Needs Cleaning -Soft Spot In Aisle @ Seat #9 - Minor Damage On A Few Seats In Back Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches, Dents & Rust - Minor Rust & Scratches On Rear Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>28</p>	<p>(1) 1997 International Bluebird School Bus Vin #9782</p>	<p>Unit #668 Model: 3800 Passenger: 71 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: September 2020 Approx. Mileage (NOT ACTUAL): 27,967 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Seats Missing In Back - Drivers Seat Rusted & Torn Body Condition: Fair Body Problems: Peeling & Oxidized Paint - Surface Scratches, Dents & Rust - Damage To Driver Side Wheel Well Above Front Tire - Rust & Scratches On Rear Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	--	---


<p>29</p>	<p>(1) 2006 IC School Bus Vin #5534</p>	<p>Unit #989 Passenger: 16 + (1) Wheelchair Space Engine Size/Type: 7.6L Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: February 2021 Approx. Mileage (NOT ACTUAL): 197,212 Has Wheel Chair Lift - Condition: Unknown Interior Condition: Fair Interior Problems: Needs Cleaning Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches, Dents & Rust Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>30</p>	<p>(1) 2001 International Bluebird School Bus Vin #7472</p>	<p>Unit #833 Model: 3800 Passenger: 16 + (1) Wheelchair Space Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: June 2021 Approx. Mileage (NOT ACTUAL): 186,705 Has Wheel Chair Lift - Condition: Unknown Interior Condition: Fair Interior Problems: Needs Cleaning - Torn Drivers Seat - Crack In Windshield Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches, Dents & Rust - Minor Scratches On Rear Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	--	---


<p>31</p>	<p>(1) 2001 International Bluebird School Bus Vin #7474</p>	<p>Unit #835 Model: 3800 Passenger: 9 + (2) Wheelchair Space Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: September 2021 Approx. Mileage (NOT ACTUAL): 137,134 Has Wheel Chair Lift - Condition: Unknown Interior Condition: Fair Interior Problems: Needs Cleaning Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches, Dents & Rust - Minor Scratches & Rust On Rear Bumper - Stop Sign Faded Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	--	---


<p>32</p>	<p>(1) 2001 International Bluebird School Bus Vin #0186</p>	<p>Unit #896 Model: 3800 Passenger: 13 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: June 2021 Approx. Mileage (NOT ACTUAL): 121,801 Interior Condition: Fair Interior Problems: Needs Cleaning Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches, Dents & Rust - Rust On Front Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	--	---


<p>33</p>	<p>(1) 2001 International Bluebird School Bus Vin #0187</p>	<p>Unit #891 Model: 3800 Passenger: 11 + (1) Wheelchair Space Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: March 2021 Approx. Mileage (NOT ACTUAL): 201,715 Interior Condition: Fair Interior Problems: Needs Cleaning - Torn Drivers Seat Body Condition: Fair Body Problems: Peeling & Oxidized Paint - Surface Scratches, Dents & Rust Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>34</p>	<p>(1) 2001 International Bluebird School Bus Vin #0190</p>	<p>Unit #894 Model: 3800 Passenger: 11 Engine Size/Type: DT466E Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: June 2021 Approx. Mileage (NOT ACTUAL): 158,266 Interior Condition: Fair Interior Problems: Needs Cleaning - Drivers Seat Tearing Body Condition: Fair Body Problems: Peeling & Oxidized Paint - Surface Scratches, Dents & Rust - Rust On Rear & Front Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>35</p>	<p>(1) 2012 Chevrolet Tahoe Vin #4234 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #4201 Passenger: 5 Conventional Engine In Front Engine Size/Type: 4.2L Engine Problems: ABS/Brakes - Engine Overheats Gas Has Battery, Dead Does Not Run Automatic Hydraulic Brakes Transmission Type Or Condition: Good Inspection Sticker Date: October 2020 Approx. Mileage (NOT ACTUAL): Unable To Read, Dead Battery Interior Condition: Fair Interior Problems: Needs Cleaning - Torn Seats - Torn Floor Liner - Missing Center Console Body Condition: Fair Body Problems: Missing Rear Brake Lights Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>36</p>	<p>(1) 2013 Ford Explorer Vin #0581</p>	<p>Unit #4214 Passenger: 5 Engine In Front Engine Size/Type: V6 3.7 DOHC Engine Problems: Unknown Gas Has Battery, Dead Runs Automatic Hydraulic Brakes Transmission Type Or Condition: Good Inspection Sticker Date: December 2020 Approx. Mileage (NOT ACTUAL): 93,757 Interior Condition: Fair Interior Problems: Needs Cleaning - Torn Seats - Damage On Drivers Door Panel - Missing Center Console Body Condition: Good Body Problems: Minor Scratches & Dents - Hole Where Spotlight Used To Be Tires Condition: Fair Tire Problems: Needs Air Additional Information: ABS Front Suspension</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>37</p>	<p>(1) 2013 Ford Explorer Vin #0585</p>	<p>Unit #4221 Passenger: 5 Engine In Front Engine Size/Type: V6 3.7 DOHC Engine Problems: Unknown Gas Has Battery, Dead Runs Automatic Hydraulic Brakes Transmission Type Or Condition: Good Inspection Sticker Date: December 2020 Approx. Mileage (NOT ACTUAL): 96,938 Interior Condition: Fair Interior Problems: Needs Cleaning - Damage On Drivers Door Panel - Missing Center Console Body Condition: Good Body Problems: Minor Scratches & Dents - Large Gash On Rear Hatch Door - Large Scratches On Hood & Bumper Tires Condition: Fair Tire Problems: Needs Air Additional Information: Front Suspension Brakes</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	--	---


<p>38</p>	<p>(1) 2012 Chevrolet Tahoe Vin #5300</p>	<p>Unit #4200 Passenger: 5 Engine In Front Engine Size/Type: 4.2L Engine Problems: Unknown Gas Has Battery Runs Automatic Hydraulic Brakes Transmission Type Or Condition: Good Inspection Sticker Date: June 2020 Approx. Mileage (NOT ACTUAL): 85,575 Interior Condition: Fair Interior Problems: Needs Cleaning - Damage On Drivers Door Panel - Missing Center Console Body Condition: Fair Body Problems: Minor Scratches & Dents - Some Deep Scratches - Missing Rear Lights Tires Condition: Fair Tire Problems: Needs Air</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>39</p>	<p>(1) 2013 Ford Explorer Vin #0576</p>	<p>Unit #4223 Passenger: 5 Engine In Front Engine Size/Type: V6 3.7 DOHC Engine Problems: Unknown Gas Has Battery, Dead Runs Automatic Hydraulic Brakes Transmission Type Or Condition: Good Inspection Sticker Date: September 2021 Approx. Mileage (NOT ACTUAL): 93,917 Interior Condition: Fair Interior Problems: Needs Cleaning - Missing Center Console Body Condition: Good Body Problems: Minor Scratches & Dents - Hole Front Spotlight - Large Scratch On Hatch Door Tires Condition: Fair Tire Problems: Needs Air Additional Information: Front Suspension Brakes</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	--	---


<p>40</p>	<p>(1) 2013 Ford Taurus Sedan Vin #4723 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #4008 Passenger: 5 Engine In Front Engine Size/Type: V6 3.5 DOHC Engine Problems: Unknown Gas Has Battery, Dead Runs Automatic Hydraulic Brakes Transmission Type Or Condition: Good Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): 65,520 Interior Condition: Fair Interior Problems: Needs Cleaning - Missing Center Console Body Condition: Good Body Problems: Fading Paint - Minor Scratches & Dents Tires Condition: Fair Tire Problems: Needs Air Additional Information: Steering Box Needs Replacing</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>41</p>	<p>(1) 2008 Ford Sedan Vin #3070</p>	<p>Unit #403 Passenger: 5 Conventional Engine In Front Engine Size/Type: 4.6L Engine Problems: Unknown Gas Has Battery Runs Automatic Hydraulic Brakes Inspection Sticker Date: April 2020 Approx. Mileage (NOT ACTUAL): 116,442 Interior Condition: Fair Interior Problems: Needs Cleaning Body Condition: Fair Body Problems: Minor Scratches & Dents - Peeling Paint On Hood & Body Tires Condition: Fair Tire Problems: Needs Air</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	--	---	---


<p>42</p>	<p>(1) 1998 Chevrolet Cargo Van Vin #8773</p>	<p>Unit #1830 Model: 3500 Passenger: 2 Conventional Engine In Front Engine Size/Type: 5.7L Engine Problems: Unknown Gas Has Battery, Dead Runs Automatic Hydraulic Brakes Inspection Sticker Date: February 2021 Approx. Mileage (NOT ACTUAL): 184,205 Interior Condition: Fair Interior Problems: Needs Cleaning Body Condition: Fair Body Problems: Peeling & Oxidized Paint - Rusted Top Panel Tires Condition: Fair Tire Problems: Needs Air</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	--	---


<p>43</p>	<p>(1) 2007 Chevrolet Cargo Van Vin #6431</p>	<p>Unit #1879 Passenger: 2 Engine In Front Engine Size/Type: 6.0L Engine Problems: Unknown Gas Has Battery, Dead Runs Automatic Hydraulic Brakes Inspection Sticker Date: February 2021 Approx. Mileage (NOT ACTUAL): 138,543 Interior Condition: Fair Interior Problems: Needs Cleaning - Seats Torn Body Condition: Fair Body Problems: Minor Rust On Top Panel - Peeling Paint - Minor Scratches & Dents Tires Condition: Fair Tire Problems: Needs Air</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>44</p>	<p>(1) 2002 Chevrolet Pickup Truck Vin #4359</p>	<p>Unit #1326 Model: 3500 Flatbed Passenger: 3 Engine In Front Engine Size/Type: 6.0L Engine Problems: Unknown Gas Has Battery, Dead Runs Automatic Hydraulic Brakes Inspection Sticker Date: March 2021 Approx. Mileage (NOT ACTUAL): 157,875 Interior Condition: Fair Interior Problems: Needs Cleaning - Faded Seats Body Condition: Fair Body Problems: Minor Scratches & Dents - Rust On Bed Tires Condition: Fair Tire Problems: Needs Air</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	--	---	---


<p>45</p>	<p>(1) 2008 Chevrolet Utility Van Vin #3267</p>	<p>Unit #1899 Passenger: 2 Engine In Front Engine Size/Type: 6.0L Engine Problems: Unknown Gas Has Battery, Dead Runs Automatic Hydraulic Brakes Inspection Sticker Date: January 2021 Approx. Mileage (NOT ACTUAL): 124,283 Interior Condition: Fair Interior Problems: Needs Cleaning - Torn Seats - Windshield Has Large Scratches Body Condition: Fair Body Problems: Peeling & Oxidized Paint - Rust On Roof - Dent On Bumper Tires Condition: Fair Tire Problems: Needs Air Additional Information: Mfg. Body: Knapheide</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>46</p>	<p>(1) 2000 Chevrolet Pickup Truck Vin #3226 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #1314 Model: 2500 Passenger: 3 Engine In Front Engine Size/Type: 5.7L Engine Problems: Unknown Gas Has Battery, Dead Does Not Run Automatic Transmission Type Or Condition: Good Hydraulic Brakes Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): 104,182 Interior Condition: Poor Interior Problems: Needs Cleaning - Torn Seats Body Condition: Poor Body Problems: Rust All Over - Scratches Tires Condition: Fair Tire Problems: Needs Air Additional Information: Lift Gate Works - (Approx. 3) Tool Boxes - Headache Rack</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	--	--	---


<p>47</p>	<p>(1) 1997 Chevrolet Pickup Truck Vin #9287 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #1398 Model: 1500 1/2 Ton Passenger: 2 Engine In Front Engine Size/Type: 5.0L Engine Problems: Unknown Gas Has Battery, Dead Does Not Run Automatic Hydraulic Brakes Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): 180,399 Interior Condition: Fair Interior Problems: Needs Cleaning - Torn Seats - Windshield Cracked Body Condition: Fair Body Problems: Minor Scratches & Dents Tires Condition: Fair Tire Problems: Needs Air</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	--	---	---


<p>48</p>	<p>(1) 1984 Chevrolet Utility Box Truck Vin #1195</p>	<p>Unit #1556 Passenger: 2 Engine In Front Engine Size/Type: 5.7L Engine Problems: Unknown Gas Has Battery Runs Automatic Inspection Sticker Date: May 2020 Approx. Mileage (NOT ACTUAL): 1,535 Interior Condition: Fair Interior Problems: Needs Cleaning - Worn - Dash Is Cracked - Missing Horn Body Condition: Fair Body Problems: Damage To Step Platform On Drivers Side Door - Box Roll Up Door Is Peeling Paint - Dent In Box On Passenger Side - Surface Rust - Dent On Drivers Door - Some Damage On Hood Tires Condition: Fair Tire Problems: Unknown Additional Information: GVW 19,200 - Has Lift Gate, Condition: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>49</p>	<p>(1) 1995 International Stakebed Truck Vin #1598 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #1578 Model: 4700 Passenger: 2 Engine In Front Engine Size/Type: DT466E 7.6L Engine Problems: Unknown Diesel Does Not Have Battery Does Not Run Automatic Air Brakes Inspection Sticker Date: May 2020 Approx. Mileage (NOT ACTUAL): 75,968 Interior Condition: Fair Interior Problems: Needs Cleaning Body Condition: Fair Body Problems: Peeling Paint On Roof - Rust On Front Bumper - Bed Is Rusted - Oxidized Paint Tire Problems: Unknown Additional Information: Single Axle - (1) Fuel Tank - Steel Bed - Gooseneck & Pin Pull Hitches - (Approx. 12' x 8') Bed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	--	---	---


<p>50</p>	<p>(1) 1998 GMC Bucket Truck Vin #6975</p>	<p>Unit #1599 Model: C7500 Passenger: 2 Engine In Front Engine Size/Type: CAT 3126 Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Fair Interior Problems: Needs Cleaning - Normal Wear & Tear Body Condition: Fair Body Problems: Surface Scratches, Rust & Dents - Dent & Rust On Drivers Side Above Rear Wheel - Dent & Rust On Rear Platform - Dent On Steps In Rear Up To Platform - Rust On Front Bumper - Rust On Platform Tires Condition: Fair Tire Problems: Unknown Additional Information: Bucket Mfg. Hi-Ranger, Model: 5FB-55 - Platform Height (Approx. 55') - Max Capacity: 550 lbs. - Bucket Mat Have To Be Safety Certified, Bucket Condition Unknown - Has Outriggers</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	--	---	---


<p>51</p>	<p>(1) 1997 International Refrigeration Box Van Vin #4761</p>	<p>Unit #1580 Model: 4700 Passenger: 2 Engine In Front Engine Size/Type: DT466E 7.3L/V8 Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: September 2020 Approx. Mileage (NOT ACTUAL): 164,599 Interior Condition: Fair Interior Problems: Needs Cleaning - Molding Loose Around Passenger Door Body Condition: Fair Body Problems: Surface Scratches, Rust & Dents - Cab Dented Behind Drivers Door - Peeling Paint - Gas Tank Rusted - Hole In Box On Passenger Side @ Bottom - Box Is Dented On Passenger Side @ Top - Rust On Front Bumper - Dent On Metal Part Of Box Behind Drivers Side Cab Tires Condition: Fair Tire Problems: Unknown Additional Information: Box Mfg. Cold King XL - Refrigerator Mfg. Thermo Kin KDII - Box Is High Cube - Has Lift, Condition: Unknown, Mfg. Maxon</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>52</p>	<p>(1) 1995 International Refrigeration Box Van Vin #1603</p>	<p>Unit #1575 Model: 4700 Passenger: 3 Engine In Front Engine Size/Type: DT466E 7.6L Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: May 2020 Approx. Mileage (NOT ACTUAL): 238,664 Interior Condition: Fair Interior Problems: Needs Cleaning - Molding Loose Around Passenger Door - Seat Is Tearing & Worn - Part Of Dash Is Missing Under Steering Wheel Body Condition: Fair Body Problems: Surface Scratches, Rust & Dents - Peeling Paint - Rust On Gas Tank Tires Condition: Fair Tire Problems: Unknown Additional Information: Refrigerator Mfg. Cold King XL - Box Is High Cube - Has Lift, Condition: Unknown, Mfg. Maxon - (Approx. 22') Box - Single Axle - (1) Gas Tank</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>53</p>	<p>(1) 1997 International Refrigeration Box Van Vin #4763</p>	<p>Unit #1582 Model: 4700 Passenger: 3 Engine In Front Engine Size/Type: DT466E 7.6L/V8 Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): 199,969 Interior Condition: Fair Interior Problems: Needs Cleaning - Molding Loose Around Passenger Door Body Condition: Fair Body Problems: Peeling Paint - Rust On Steps Up Into Truck - Major Damage To Hood - Some Damage To Drivers Side Box In Middle Tires Condition: Fair Tire Problems: Unknown Additional Information: Refrigerator Mfg. Cold King Thermo King KDII SR - Box Is High Cube - Has Lift, Condition: Unknown, Mfg. Maxon - (Approx. 22') Box - Single Axle - (1) Gas Tank</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	--	---


<p>54</p>	<p>(1) 1999 International Refrigeration Box Van Vin #8043</p>	<p>Unit #1585 Model: 4700 Passenger: 3 Engine In Front Engine Size/Type: DT466E 7.6L Engine Problems: Unknown Diesel Has Battery Runs Automatic Air Brakes Inspection Sticker Date: May 2021 Approx. Mileage (NOT ACTUAL): 134,922 Interior Condition: Fair Interior Problems: Needs Cleaning - Cover Is Missing On Dash Next To Radio Body Condition: Fair Body Problems: Damage On Top Passenger Side On Refrigeration Box - Rust On Steps Up Into Truck - Rust On Front Bumper - Lift Is Rusted - Rock Chip In Windshield Tires Condition: Fair Tire Problems: Unknown Additional Information: Refrigerator Mfg. Cold King Thermo King KDII SR - Damage On Refrigerator Unit - Has Lift, Condition: Unknown, Mfg. Maxon - (Approx. 22') Box - Single Axle - (1) Gas Tank</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>55</p>	<p>(1) 1995 International Refrigeration Box Van Vin #1600 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #1574 Model: 4700 Passenger: 3 Engine In Front Engine Size/Type: DT466E Engine Problems: Bad Engine - Will Not Start Diesel Unknown If It Has Battery Does Not Run Automatic Air Brakes Inspection Sticker Date: October 2020 Approx. Mileage (NOT ACTUAL): 115,980 Interior Condition: Fair Interior Problems: Needs Cleaning - Normal Wear - Drivers Seats Needs Repair Body Condition: Fair Body Problems: Scratches & Dents On Box - Oxidized Paint - Surface Scratches On Cab Tires Condition: Fair Tire Problems: Unknown Additional Information: Refrigerator Mfg. Cold King Thermo King KDII - Box Is High Cube - Has Lift, Condition: Unknown, Mfg. Maxon - (Approx. 22') Box - Dual Wheel Single Axle In Rear - (1) Gas Tank - Box By Supreme Corp</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	--	---


<p>56</p>	<p>(1) 2001 International Refrigeration Box Van Vin #2767 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #1597 Model: 4700 Passenger: 2 Engine In Front Engine Size/Type: DT466E Engine Problems: Bad Engine - Will Not Start Diesel Unknown If It Has Battery Does Not Run Automatic Air Brakes Inspection Sticker Date: March 2019 Approx. Mileage (NOT ACTUAL): 114,198 Interior Condition: Fair Interior Problems: Needs Cleaning - Normal Wear Body Condition: Fair Body Problems: Oxidized Paint - Scratches, Dents & (1) Gash On Box Tires Condition: Fair Tire Problems: Unknown Additional Information: Refrigerator Mfg. Cold King Thermo King KDII SR - Box Is High Cube - Has Lift, Condition: Unknown, Mfg. Waltco - (Approx. 22') Box - Dual Wheel Single Axle In Rear - (1) Gas Tank - Box Bed: Kold King XL, Mfg. Supreme Corp - Refrigeration Unit Needs Repair - Has Been Sitting For Several Years</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>57</p>	<p>(1) 2009 International School Bus Vin #6235 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #6024 Model: CE300 Conventional Passenger: 71 Engine In Front Engine Size/Type: Maxx Force DT Engine In Front Engine Problems: Bad Engine - Possibly Missing Parts Diesel Does Not Have Battery Does Not Run Automatic Air Brakes Inspection Sticker Date: August 2020 Approx. Mileage (NOT ACTUAL): 103,649 Interior Condition: Fair To Poor Interior Problems: Needs Cleaning - Parts Missing & Loose On Bus - Entry Door Loose & Inside Unit Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Light Missing On Rear - Dent To Reflector Disc Missing On Rear - Missing (1) Mirror On Front - Hole In Fiberglass Hood - Missing Mirror On Right Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	--	--	---


<p>58</p>	<p>(1) 2009 International School Bus Vin #6234 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #6038 Model: CE300 Conventional Passenger: 71 Engine In Front Engine Size/Type: Maxx Force DT Engine In Front Engine Problems: Bad Engine - Possibly Missing Parts Diesel Has Battery, Dead Does Not Run Automatic Air Brakes Inspection Sticker Date: August 2020 Approx. Mileage (NOT ACTUAL): Unable To Read, Dead Battery Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Missing Light On Rear - Rub On Windshield From Wiper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	--	--	---


<p>59</p>	<p>(1) 2005 International School Bus Vin #5815 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #926 Model: CE300 Conventional Passenger: 71 Engine In Front Engine Size/Type: Maxx Force DT Engine In Front Engine Problems: Bad Engine - Possibly Missing Parts - Loose Parts Diesel Has Battery, Dead Does Not Run Automatic Air Brakes Inspection Sticker Date: April 2020 Approx. Mileage (NOT ACTUAL): Unable To Read, Dead Battery Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches Tires Condition: Fair To Poor Tire Problems: Poor On Right & Left Rear</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	--	--	---


60	(1) 2002 International School Bus Vin #6866 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #859 Model: Integrated Conv. S Conventional Passenger: 71 Engine In Front Engine Size/Type: 7.6L Engine In Front Engine Problems: Bad Engine - Possibly Missing Parts Diesel Has Battery, Dead Does Not Run Automatic Air Brakes Inspection Sticker Date: October 2020 Approx. Mileage (NOT ACTUAL): 160,110 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats - Normal Wear Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
----	---	---	---


<p>61</p>	<p>(1) 2009 International School Bus Vin #6186 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #1192 Model: CE300 Conventional Passenger: 71 Engine In Front Engine Size/Type: 6.4L Engine In Front Engine Problems: Bad Engine - Possibly Missing Parts Diesel Has Battery, Dead Does Not Run Automatic Air Brakes Inspection Sticker Date: July 2021 Approx. Mileage (NOT ACTUAL): Unable To Read, Dead Battery Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Dent On Right Rear - Light Missing In Right Rear Tires Condition: Fair To Poor Tire Problems: Right Rear Questionable</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	--	--	---


<p>62</p>	<p>(1) 2010 International School Bus Vin #6754 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #6157 Model: CE300 Conventional Passenger: 71 Engine In Front Engine Size/Type: Maxx Force DT Engine In Front Engine Problems: Bad Engine - Possibly Missing Parts Diesel Has Battery, Dead Does Not Run Automatic Air Brakes Inspection Sticker Date: July 2021 Approx. Mileage (NOT ACTUAL): Unable To Read, Dead Battery Interior Condition: Fair Interior Problems: Needs Cleaning - Possible Parts Missing - Missing (1) Passenger Seat Cover Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Broken Front Mirror - Missing Light In Rear - Rub On Left Rear Panel Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	--	--	---


<p>63</p>	<p>(1) 2008 International School Bus Vin #1483 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #1110 Model: CE300 Conventional Passenger: 71 Engine In Front Engine Size/Type: Maxx Force DT Engine In Front Engine Problems: Bad Engine - Possibly Missing Parts Diesel Has Battery, Dead Does Not Run Automatic Air Brakes Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unable To Read, Dash Missing Interior Condition: Fair To Poor Interior Problems: Needs Cleaning - Possible Parts Dash Missing - Seats Worn & Some Torn Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Broken Front Mirror - Rock Chips On Windshield - Rub On Windshield From Wiper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	--	--	---


<p>64</p>	<p>(1) 2009 International School Bus Vin #6151 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #1158 Model: CE300 Conventional Passenger: 71 Engine In Front Engine Size/Type: Maxx Force DT Engine In Front Engine Problems: Bad Engine - Possibly Missing Parts Diesel Has Battery, Dead Does Not Run Automatic Air Brakes Inspection Sticker Date: July 2021 Approx. Mileage (NOT ACTUAL): Unable To Read, Dead Battery Interior Condition: Fair Interior Problems: Needs Cleaning - Some Seats Torn - Missing (1) Seat Cover Body Condition: Fair Body Problems: Surface Scratches - Rock Chips On Windshield - Rub On Right Rear - Light Missing On Rear Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	--	--	---


<p>65</p>	<p>(1) 2002 International School Bus Vin #6864 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #862 Model: Integrated Conv. S 254 Conventional Passenger: 71 Engine In Front Engine Size/Type: 7.6L Engine In Front Engine Problems: Bad Engine - Possibly Missing Parts Diesel Has Battery, Dead Does Not Run Automatic Air Brakes Inspection Sticker Date: October 2020 Approx. Mileage (NOT ACTUAL): 164,145 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Seats Torn - Normal Wear Body Condition: Fair Body Problems: Surface Scratches - Roof Needs Cleaning Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	--	--	---


<p>66</p>	<p>(1) 2013 International School Bus Vin #9358 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #6191 Model: CE300 Conventional Passenger: 71 Engine In Front Engine Size/Type: Maxx Force DT Engine In Front Engine Problems: Bad Engine - Possibly Missing Parts Diesel Has Battery, Dead Does Not Run Automatic Air Brakes Inspection Sticker Date: April 2021 Approx. Mileage (NOT ACTUAL): Unable To Read, Dead Battery Interior Condition: Fair Interior Problems: Needs Cleaning - Some Seats Torn Body Condition: Fair Body Problems: Surface Scratches - Some Scratches Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	--	---	---


<p>67</p>	<p>(1) 2001 International Bluebird School Bus Vin #0196 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #880 Model: 3800 Conventional Passenger: 36 Engine In Front Engine Size/Type: DT466E Engine In Front Engine Problems: Bad Engine - Possibly Missing Parts Diesel Has Battery, Dead Does Not Run Automatic Air Brakes Inspection Sticker Date: April 2021 Approx. Mileage (NOT ACTUAL): 200,763 Interior Condition: Fair Interior Problems: Normal Wear - Some Torn Seats - Has Some Seat Belts - Drivers Seat Torn Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Peeling On Cowl & Hood Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---


<p>68</p>	<p>(1) 2009 International School Bus Vin #6232 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #6002 Model: CE300 Conventional Passenger: 71 Engine In Front Engine Size/Type: Maxx Force DT Engine In Front Engine Problems: Bad Engine - Possibly Missing Parts Diesel Has Battery, Dead Does Not Run Automatic Air Brakes Inspection Sticker Date: August 2021 Approx. Mileage (NOT ACTUAL): Unable To Read, Dead Battery Interior Condition: Fair Interior Problems: Needs Cleaning - Parts Loose & Missing Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	--	--	---


<p>69</p>	<p>(1) 2008 International School Bus Vin #1458 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #1108 Model: CE300 Conventional Passenger: 71 Engine In Front Engine Size/Type: Maxx Force DT Engine In Front Engine Problems: Bad Engine - Possibly Missing Parts Diesel Has Battery, Dead Does Not Run Automatic Air Brakes Inspection Sticker Date: March 2020 Approx. Mileage (NOT ACTUAL): Unable To Read, Dead Battery Interior Condition: Fair Interior Problems: Needs Cleaning - Parts Loose & Missing - Dash Loose Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	--	--	---

<p>70</p>	<p>(1) 1998 International Bluebird School Bus Vin #1486 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #707 Model: 3800 Conventional Passenger: 71 Engine In Front Engine Size/Type: DT466E Engine In Front Engine Problems: Bad Engine - Possibly Missing Parts Diesel Has Battery, Dead Does Not Run Automatic Air Brakes Inspection Sticker Date: October 2020 Approx. Mileage (NOT ACTUAL): 157,955 Interior Condition: Fair Interior Problems: Seats Are Worn & Some Are Torn - Floor Needs Some Future Repairs Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Rub On Left Middle Panel In Front Of Wheel Well Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---

71	(1) 2008 International School Bus Vin #1474 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #1117 Model: CE300 Conventional Passenger: 71 Engine In Front Engine Size/Type: Maxx Force DT Engine In Front Engine Problems: Bad Engine - Possibly Missing Parts Diesel Has Battery, Dead Does Not Run Automatic Air Brakes Inspection Sticker Date: August 2020 Approx. Mileage (NOT ACTUAL): Unable To Read, Dead Battery Interior Condition: Fair Interior Problems: Parts Loose & Parts Missing Body Condition: Fair Body Problems: Surface Scratches Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
----	---	--	---

<p>73</p>	<p>(1) 2006 International School Bus Vin #9825 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #951 Model: CE300 Conventional Passenger: 71 Engine In Front Engine Size/Type: 7.6L Engine In Front Engine Problems: Bad Engine - Possibly Missing Parts Diesel Has Battery, Dead Does Not Run Automatic Air Brakes Inspection Sticker Date: May 2020 Approx. Mileage (NOT ACTUAL): Unable To Read, Dead Battery Interior Condition: Fair Interior Problems: Needs Cleaning - Missing Engine Cover - Parts Missing Body Condition: Fair Body Problems: Surface Scratches - Scratches On Windshield From Wipers Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	--	---	---

<p>74</p>	<p>(1) 2008 International School Bus Vin #1480 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #1113 Model: CE300 Conventional Passenger: 71 Engine In Front Engine Size/Type: Maxx Force DT Engine In Front Engine Problems: Bad Engine - Possibly Missing Parts Diesel Has Battery, Dead Does Not Run Automatic Air Brakes Inspection Sticker Date: January 2021 Approx. Mileage (NOT ACTUAL): Unable To Read, Dead Battery Interior Condition: Fair Interior Problems: Missing (2) Bus Seat Covers - Needs Cleaning - Missing Dash Cover & Other Interior Components Body Condition: Fair Body Problems: Surface Scratches - Missing (1) Light On Rear - Rock Chip On Windshield Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	--	--	---

<p>75</p>	<p>(1) 1982 International Wrecker Vin #7172 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #1551 Engine Size/Type: Unknown Engine In Front Engine Problems: Unknown Does Not Run Automatic Hydraulic Brakes Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Fair Interior Problems: Dash Is Cracked Body Condition: Fair Body Problems: Wrecked In Rear, Possible Rear End Damage - Front Roof Missing Lights, Some Loose - Surface Rust Tires Condition: Fair Tire Problems: Unknown Additional Information: Heavy Duty Front Bumper - W/Winch - *RECOMMEND PREVIEW*</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
-----------	---	--	---