







Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	<p><b>**All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes**</b></p> <p><b>IMPORTANT NOTICE FOR LA VERNIA ISD ONLINE AUCTION: **All purchases will be subject to a 14% buyer's premium. There Will Be A 3% Fee For All Purchases Not Made By Cash, Cashier's Check, Direct Deposit, Money Order &amp; Wire Transfer*</b></p> <p><b>CDC COVID-19 GUIDELINES WILL BE OBSERVED – WEAR A MASK AND STAY AT LEAST 6 FT. APART.</b></p> <p><b>Preview:</b> (By Appointment Only-Mandatory-No Exceptions) Monday, April 19, 2021 (Hours Of Operation: 8:00 A.M. - 2:00 P.M.)  <b>Location:</b> 89 Acres Transportation Storage, 823 FM 1346, La Vernia, TX 78121  <a href="#">Driving Directions</a></p> <p><b>Removal Dates &amp; Times:</b> (By Appointment Only-Mandatory-No Exceptions) Thursday, April 22, 2021/Friday, April 23, 2021/Monday, April 26, 2021 (Hours Of Operation: 8:00 A.M. - 2:00 P.M.)  <b>Preview &amp; Removal Contact:</b> Nancy Harrison 830-779-6610 <a href="mailto:nancy.harrison@lvisd.org">nancy.harrison@lvisd.org</a></p> <p><b><i>There Will Be No Manpower, No Employee Assistance Or Equipment Available For Removal. Buyer Must Remove All Lots In Their Entirety. Buyer Is Solely Responsible For Loading &amp; Unloading, Bring Own Manpower, Equipment, Dollies Or Other Adequate Moving Devices or Equipment, Etc. To Remove Items. Buyer Must Have Adequate Transportation To Move Purchased Items.</i></b></p> <p><b>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</b></p> <p><b><i>**All defects and flaws with a vehicle will be the buvers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></b></p> <p><b>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</b></p>	

1	(1) 1993 Ford B700 School Bus Vin #6831 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #93B Passenger: 71 Engine Size/Type: 5.9L Engine Problems: Unknown Diesel Has Battery - Inside Unit Does Not Run Automatic Inspection Sticker Date: September 2018 Approx. Mileage (NOT ACTUAL): 58,517 Interior Condition: Fair Interior Problems: Needs Cleaning - Control Panel Open - Wires Exposed Body Condition: Poor Body Problems: Roof Needs Cleaning - Oxidized Paint - Damage To Hood On Drivers Side Above Headlight - Stop Sign Hanging Down - Damage To Hood Under Windshield - Surface Scratches, Rust &amp; Dents Tires Condition: Fair Tire Problems: Tires Dry Rotted Additional Information: Has Been Sitting For Several Years</p> <p><b>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed. Buyers Will Not Be Allowed To Work On Or Fix Vehicles On La Vernia ISD's Premises.</b></p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></b></p> <p>- Current Condition Unknown</p>	
2	(1) 1993 Ford B700 Carpenter School Bus Vin #6830 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #93A Passenger: 71 Engine Size/Type: 5.9L Engine Problems: Unknown Diesel Has Battery - Inside Unit Does Not Run Automatic Air Brakes Inspection Sticker Date: September 2018 Approx. Mileage (NOT ACTUAL): 73,659 Interior Condition: Fair Interior Problems: Needs Cleaning - Drivers Seat Not Original Seat Body Condition: Fair Body Problems: Roof Needs Cleaning - Oxidized Paint - Rust On Hood Under Windshield - Stop Sign Missing - Peeling Paint - Surface Scratches, Rust &amp; Dents Tires Condition: Fair Tire Problems: Tires Dry Rotted Additional Information: Has Been Sitting For Several Years</p> <p><b>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed. Buyers Will Not Be Allowed To Work On Or Fix Vehicles On La Vernia ISD's Premises.</b></p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></b></p> <p>- Current Condition Unknown</p>	

<p>8</p>	<p>(1) 1999 Freightliner Crown By Carpenter School Bus Vin #0647 - Will Need To Be Towed</p>	<p>Will Need To Be Towed  Unit #99A  Conventional  Passenger: 71  Engine Size/Type: Cummins Campaign 0504  Engine In Front  Engine Problems: Unknown  Diesel  Does Not Have Battery  Runs - Engine Will Turn Over  Automatic  Air Brakes  Inspection Sticker Date: September 2018  Approx. Mileage (NOT ACTUAL): 103,866  Interior Condition: Fair  Interior Problems: Needs Cleaning - Some Tears In Seats  Body Condition: Poor  Body Problems: Faded &amp; Oxidized Paint - Some Rust - Needs Cleaning - Scratches - Hood Missing Front  Grill - Some Damage  Tires Condition: Fair  Tire Problems: Tires Dry Rotted  Additional Information: Has Been Sitting For Several Years</p> <p><b>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed. Buyers Will Not Be Allowed To Work On Or Fix Vehicles On La Vernia ISD's Premises.</b></p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></b></p> <p>- Current Condition Unknown</p>	
----------	--	---	---

<p>9</p>	<p>(1) 1998 Ford Crown By Carpenter School Bus Vin #1070 - Will Need To Be Towed</p>	<p>Will Need To Be Towed  Unit #98  Conventional  Passenger: 24  Engine Size/Type: 7.3L  Engine In Front  Engine Problems: Unknown  Diesel  Does Not Have Battery  Runs - Engine Will Turn Over  Automatic  Air Brakes  Inspection Sticker Date: August 2005  Approx. Mileage (NOT ACTUAL): 60,331  Has Wheel Chair Lift - Condition Unknown  Interior Condition: Fair  Interior Problems: Needs Cleaning - Some Tears In Seats  Body Condition: Poor  Body Problems: Faded &amp; Oxidized Paint - Rust - Needs Cleaning - Scratches - Some Cracks In Hood  Tires Condition: Fair  Tire Problems: Unknown  Additional Information: Has Been Sitting For Several Years</p> <p><b>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed. Buyers Will Not Be Allowed To Work On Or Fix Vehicles On La Vernia ISD's Premises.</b></p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></b></p> <p>- Current Condition Unknown</p>	
----------	--	---	---

<p>10</p>	<p>(1) 2002 International T444E School Bus Vin #8349 - Will Need To Be Towed</p>	<p>Will Need To Be Towed  Unit #02  Conventional  Passenger: 47  Engine Size/Type: 7.3L  Engine In Front  Engine Problems: Parts Missing  Diesel  Does Not Have Battery  Runs - Engine Will Turn Over  Automatic  Air Brakes  Inspection Sticker Date: October 2019  Approx. Mileage (NOT ACTUAL): Unknown - Missing Panel  Has Wheel Chair Lift - Condition Unknown  Interior Condition: Poor  Interior Problems: Needs Cleaning - Back Ceiling Hatch Missing - Some Tears In Seats - Front Drivers  Panel Missing Parts  Body Condition: Fair  Body Problems: Faded &amp; Oxidized Paint - Some Rust - Needs Cleaning - Scratches - Paint Chips  Tires Condition: Fair  Tire Problems: Unknown  Additional Information: Has Been Sitting For Several Years</p> <p><b>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed. Buyers Will Not Be Allowed To Work On Or Fix Vehicles On La Vernia ISD's Premises.</b></p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b><i>**All defects and flaws with a vehicle will be the buvers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warrantv or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracv of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></b></p> <p>- Current Condition Unknown</p>	
-----------	--	--	---

<p>11</p>	<p>(1) 1999 Freightliner Crown By Carpenter School Bus Vin #0646 - Will Need To Be Towed</p>	<p>Will Need To Be Towed  Unit #99B  Conventional  Passenger: 71  Engine Size/Type: 5.9 Cummins  Engine In Front  Engine Problems: Missing Injector Lines  Diesel  Does Not Have Battery  Does Not Run  Automatic  Air Brakes  Inspection Sticker Date: September 2018  Approx. Mileage (NOT ACTUAL): 22,645  Interior Condition: Fair  Interior Problems: Needs Cleaning - Missing Some Parts On Dash  Body Condition: Poor  Body Problems: Faded &amp; Oxidized Paint - Some Rust - Scratches - Peeling &amp; Chipped Paint  Tires Condition: Fair  Tire Problems: Unknown  Additional Information: Has Been Sitting For Several Years</p> <p><b>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed. Buyers Will Not Be Allowed To Work On Or Fix Vehicles On La Vernia ISD's Premises.</b></p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b><i>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></b></p> <p>- Current Condition Unknown</p>	
-----------	--	--	---