		·	
Lot Number	Title	Description	Thumbnail
		All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes	
		IMPORTANT NOTICE FOR SPRING BRANCH ISD ONLINE AUCTION: **All purchases will be subject to a 14% buyer's premium. There Will Be A 3% Fee For All Purchases Not Made By Cash, Cashier's Check, Direct Deposit, Money Order & Wire Transfer*	
		CDC COVID-19 GUIDELINES WILL BE OBSERVED – WEAR A MASK AND STAY AT LEAST 6 FT. APART.	
		Preview: (By Appointment Only-Mandatory-No Exceptions) Thursday, April 15, 2021 (Hours Of Operation: 9:00 A.M 11:00 A.M./1:00 P.M. – 3:00 P.M.) Location 1 (Lot 412): Spring Branch ISD Transportation, 1066 Gessner Road, Houston, TX 77055 Driving Directions Removal Dates & Times: (By Appointment Only-Mandatory-No Exceptions) Wednesday, April 21, 2021/Thursday, April 22, 2021/Friday, April 23, 2021 (Hours Of Operation: 9:00 A.M 11:00 A.M./1:00 P.M. – 3:00 P.M.) Preview & Removal Contact: Bob Lipkind 713-251-1068 or 832-372-4834 robert.lipkind@springbranchisd.com	
		There Will Be No Manpower, No Employee Assistance Or Equipment Available For Removal. Buyer Must Remove All Lots In Their Entirety. Buyer Is Solely Responsible For Loading & Unloading, Bring Own Manpower, Equipment, Dollies Or Other Adequate Moving Devices or Equipment, Etc. To Remove Items. Buyer Must Have Adequate Transportation To Move Purchased Items.	
		There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.	
		** All defects and flaws with a vehicle will be the buvers responsibility once purchased by buver. Buver should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **	TATTENTION
0	Preview & Removal Information	Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.	Read Me
		Location 2 (Lot 413-419): Spring Woods High School, 2045 Gessner Road, Houston, TX 77080 Driving Directions Removal Dates & Times: (By Appointment Only-Mandatory-No Exceptions) Wednesday, April 21, 2021/Thursday, April 22, 2021/Friday, April 23, 2021 (Hours Of Operation: 9:00 A.M 11:00 A.M./1:00 P.M. – 3:00 P.M.) Preview & Removal Contact: Bob Lipkind 713-251-1068 or 832-372-4834 robert.lipkind@springbranchisd.com	
		Dates Are Strictly Enforced. Spring Branch ISD Will No Be Giving Extensions For Removal. Bring Printed Copy Of Paid Receipt With You In Hand At Time Of Removal. Only A Hard Copy Of Your Paid Receipt Will Be Acceptable At The Seller's Location.	
		There Will Be No Manpower, No Employee Assistance Or Equipment Available For Removal. Buyer Must Remove All Lots In Their Entirety. Buyer Is Solely Responsible For Loading & Unloading, Bring Own Manpower, Equipment,	
		© 2021 Lemons Auctioneers LLC 04/08/2021 12:35 PM	

		Dollies Or Other Adequate Moving Devices or Equipment, Etc. To Remove Items. Buyer Must Have Adequate Transportation To Move Purchased Items.	
		There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.	
		** All defects and flaws with a vehicle will be the buvers responsibility once purchased by buver. Buver should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **	
		Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.	
Je M Pt 412 Ve #8 W To	eep CJ5 Iulti urpose ehicle Vin	 Will Need To Be Towed Passenger 2 Engine Size/Type:300 6 Cylinder Gas Does Not Run Approx. Mileage (NOT ACTUAL) 27,615 Interior Condition: Fair to Poor Interior Problems: Torn Driver & Passenger Seat - Needs Cleaning - Rust Around Interior Edge Of Roof Body Condition: Fair Body Problems: Oxidized & Peeling Paint - Crack On Right Rear Tail Light - Lens Cover Missing On Left Rear Tire Problems: Possible Try Rot Additional Information: GAWR Front = 2200 - GVWR Rear =2700 - Total GVWR =3750 Needs To Be Refurbished RECOMMEND PREVIEW Additional Information: Unit Was Used For Pushing & Jumping Vehicles Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And /Or Removed. Buyers Will Not Be Allowed To Work On Or Fix Vehicles On Spring Branch ISD's Premises. There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. 	
413 Si 413 Gi #0 W To	l) 2007 uzuki lotorcycle Z250 Vin 0964 - /ill Need o Be owed	Must Have Trailer Or Other Vehicle To Transport Lot Unit #8 Engine Size/Type: Suzuki 250 Gas Does Not Run Actual Mileage: 3642 Body Condition: Fair Body Problems: Dent On Fuel Tank - Surface Scratches - Missing Left Rear Turn Signal Tires Condition: Fair Tire Problem: Possible Dry Rot There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.	
		- Current Condition Unknown	

415	(1) 2007 Suzuki Motorcycle GZ250 Vin #0449 - Will Need To Be Towed	Must Have Trailer Or Other Vehicle To Transport Lot Unit #6 Engine Size/Type: Suzuki 250 Engine Problems: Fuel Supply Valve Leaks Gas Does Not Run Actual Mileage: 3423 Body Condition: Fair Body Problems: Scratches & Dents On Fuel Tank - Scratches On Front Wheel Well Tires Condition: Fair Tire Problem: Possible Dry Rot There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **	
416	(1) 2007 Suzuki Motorcycle GZ250 Vin #0437	Must Have Trailer Or Other Vehicle To Transport Lot Unit #11 Engine Size/Type: Suzuki 250 Engine Problems: Fuel Supply Valve Leaks Gas Does Not Run Actual Mileage: 2816 Body Condition: Fair Body Problems: Scratches & Dents On Fuel Tank - Scratches On Front Wheel Well - Scratches On Plastic Battery Cover Tires Condition: Fair Tire Problem: Possible Dry Rot There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **	
417	(1) 2007 Suzuki Motorcycle GZ250 Vin #1639	Must Have Trailer Or Other Vehicle To Transport Lot Unit #5 Engine Size/Type: Suzuki 250 Engine Problems: Unknown Gas Does Not Run Actual Mileage: 3707 Body Condition: Fair Body Problems: Scratches On Fuel Tank & Front Wheel Well - Large Dent On Left Front Of Fuel Tank - Left Turn Signal Missing Tires Condition: Fair Tires Condition: Fair Tire Problem: Possible Dry Rot There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **	
418	(Lot) Motorcycle Helmets	(Approx. 11) Various Sizes USED - Current Condition Unknown	

<i>4</i> 19	Motorcycle Parts &	 (1) Handle Bar (Approx. 3) Levers (Approx. 3) Turn Signals (Approx. 5) Air Cleaners (Approx. 2) Mirrors (1) Box Miscellaneous Tools 	
		- Current Condition Unknown	

