













Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	<p><b>**All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes**</b></p> <p><b>IMPORTANT NOTICE FOR CY-FAIR ISD ONLINE AUCTION: **All purchases will be subject to a 14% buyer's premium. There Will Be A 3% Fee For All Purchases Not Made By Cash, Cashier's Check, Direct Deposit, Money Order &amp; Wire Transfer*</b></p> <p><b>CDC COVID-19 GUIDELINES WILL BE OBSERVED – WEAR A MASK AND STAY AT LEAST 6 FT. APART.</b></p> <p><b>Preview:</b> (By Appointment Only-Mandatory-No Exceptions) Thursday, May 13, 2021 (Hours Of Operation: 9:30 A.M. - 12:30 P.M.)  <b>Location:</b> Charlotte Davis Burns Science Resource Center, 11206 Telge Road, Cypress, TX 77429 <a href="#">Driving Directions</a>  <b>Removal Dates &amp; Times:</b> (By Appointment Only-Mandatory-No Exceptions) Wednesday, May 19, 2021/Thursday, May 20, 2021/Friday, May 21, 2021 (Hours Of Operation: 9:30 A.M. - 12:30 P.M.) <b>*No Cash Payments On Site*</b>  <b>Preview &amp; Removal Contact:</b> Stephanie Burke 281-517-6367</p> <p><b>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</b></p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</b></p> <p><b>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</b></p>	
1	(1) 2000 International Bluebird School Bus Vin #5521	<p>Unit #758  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: June 2021  Approx. Mileage (NOT ACTUAL): 151,640  Interior Condition: Fair  Interior Problems: Needs Cleaning - Driver &amp; Passenger Seats Have Cracks  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</b></p> <p>- Current Condition Unknown</p>	

2	(1) 2000 International Bluebird School Bus Vin #5505	<p>Unit #744  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: April 2021  Approx. Mileage (NOT ACTUAL): 171,024  Interior Condition: Fair  Interior Problems: Needs Cleaning - Driver Seat Torn - Some Seats In Back Are Cracking - Soft Spot In Aisle Next To Seat #9 &amp; 11  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Rust On Front Bumper - Scratches On Driver Side Rear Bumper - Some Reflectors Are Peeling  Tires Condition: Fair  Tire Problems: Unknown  Additional Information: A/C Seems To be Working</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
3	(1) 2000 International Bluebird School Bus Vin #5511	<p>Unit #763  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: Unknown  Approx. Mileage (NOT ACTUAL): 179,156  Interior Condition: Fair  Interior Problems: Needs Cleaning - Soft Spot In Aisle Behind Passenger Seat &amp; At End Of Aisle Next To Seat #9 &amp; 12  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Some Peeling On Yellow Reflectors On Rear Drivers Side &amp; Emergency Door  Tires Condition: Fair  Tire Problems: Unknown  Additional Information: A/C Seems To be Working</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	



4	(1) 2000 International Bluebird School Bus Vin #5513	<p>Unit #756  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: Unknown  Approx. Mileage (NOT ACTUAL): 132,752  Interior Condition: Fair  Interior Problems: Needs Cleaning - Soft Spot In Aisle At Seat #5 - Crack In Floorboard Under Motor Case  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Rust On Front Bumper - Minor Scratches &amp; Rust On Rear Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
5	(1) 2000 International Bluebird School Bus Vin #5510	<p>Unit #732  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: May 2021  Approx. Mileage (NOT ACTUAL): 156,376  Interior Condition: Fair  Interior Problems: Needs Cleaning - Soft Spot In Aisle Behind Drivers Seat  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Rust On Front Bumper - Peeling Paint On Hood  Tires Condition: Fair  Tire Problems: Unknown  Additional Information: A/C Seems To Be Working</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	



6	(1) 2000 International Bluebird School Bus Vin #5517	<p>Unit #736  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: May 2021  Approx. Mileage (NOT ACTUAL): 82,567  Interior Condition: Fair  Interior Problems: Needs Cleaning - Soft Spot In Aisle Next To Seat #12 - Drivers Seat Torn - Minor Tears In Back Seats  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Rust On Front Bumper - Peeling Paint On Hood  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
7	(1) 2000 International Thomas School Bus Vin #0155	<p>Unit #784  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: Unknown  Approx. Mileage (NOT ACTUAL): 167,537  Interior Condition: Fair  Interior Problems: Needs Cleaning - Soft Spot In Aisle Between Two Front Seats &amp; Between Seats #3 &amp; 4  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Peeling Paint On Hood &amp; Cowl - Dent In Rear Bumper On Driver &amp; Passenger Side - Rust &amp; Dent On Panel Piece On Left Side Of Rear Entry  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	

8	(1) 2000 International Bluebird School Bus Vin #5504	<p>Unit #733  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: March 2021  Approx. Mileage (NOT ACTUAL): 151,743  Interior Condition: Fair  Interior Problems: Needs Cleaning - Soft Spot In Aisle At Seat #11 - Minor Wear To Some Seats In Back  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Minor Dent &amp; Scratches On Rear  Driver Side Bumper - Yellow Reflector Peeling Paint  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</b></p> <p>- Current Condition Unknown</p>	
9	(1) 2000 International Bluebird School Bus Vin #5496	<p>Unit #750  Model: 3800  Passenger: 71  Engine Size/Type: 7.6L/DT466E-HT  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: March 2021  Approx. Mileage (NOT ACTUAL): 158,580  Interior Condition: Fair  Interior Problems: Needs Cleaning - Soft Spot In Aisle Behind Drivers Seat, Seat #2, #3, #4, #7, #8, #10 &amp; #11 - Some Back Seats Have Tears &amp; Are Worn  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Rust On Front Bumper - Dent In Rear Bumper - Scratch On Panel In Front Of Passenger Tire - Rust &amp; Scratches On Rear Passenger Side Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</b></p> <p>- Current Condition Unknown</p>	



10	(1) 2000 International Bluebird School Bus Vin #5500	<p>Unit #730  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: March 2021  Approx. Mileage (NOT ACTUAL): 124,927  Interior Condition: Fair  Interior Problems: Needs Cleaning - Soft Spot At Seat #9 - Driver Seat Torn - Minor Wear On Seats In Back  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Minor Peeling Paint On Hood - Minor Rust Spots On Passenger Side Rear &amp; Front Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p><b>Vin Number On Title Is Not Correct. There Will Be An Affidavit From Cy-Fair ISD That Accompanies The Title Paperwork.</b></p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</b></p> <p>- Current Condition Unknown</p>	
11	(1) 2000 International Thomas School Bus Vin #0153	<p>Unit #791  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: March 2021  Approx. Mileage (NOT ACTUAL): 155,376  Interior Condition: Fair  Interior Problems: Needs Cleaning - Soft Spot In Floor At Driver Seat - Rust On Dash - Soft Spots &amp; Rubber Damage In Aisle - Some Seats Have Tears  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Peeling Paint On Hood - Minor Rust On Front Bumper - Dent In Rear Bumper On Driver &amp; Passenger Side  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</b></p> <p>- Current Condition Unknown</p>	







12	(1) 2000 International Thomas School Bus Vin #0137	<p>Unit #792  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: May 2021  Approx. Mileage (NOT ACTUAL): 170,855  Interior Condition: Fair  Interior Problems: Needs Cleaning - Soft Spot In Aisle At Seat #3, 8, 9 &amp; 10 - Minor Wear On Seats In Back  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Peeling Paint On Hood &amp; Cowl - Dents On Rear Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
13	(1) 2000 International Thomas School Bus Vin #0172	<p>Unit #787  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: March 2021  Approx. Mileage (NOT ACTUAL): 151,369  Interior Condition: Fair  Interior Problems: Needs Cleaning - Soft Spot In Aisle At Seat #4, 5, 6, 9, 10 &amp; 11 - Driver Seat Starting To Tear - Minor Wear On Rear Seats  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Peeling Paint On Hood - Dent On Passenger &amp; Driver Side Rear Bumper  Tires Condition: Fair  Tire Problems: Unknown  Additional Information: A/C Seems To Be Working</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	



14	(1) 2000 International Thomas School Bus Vin #0142	<p>Unit #807  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: May 2021  Approx. Mileage (NOT ACTUAL): 148,749  Interior Condition: Fair  Interior Problems: Needs Cleaning - Soft Spot In Aisle At Seat #7 &amp; 10 - Minor Wear On Rear Seats  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Peeling Paint On Hood &amp; Cowl - Dent On Passenger &amp; Driver Side Rear Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
15	(1) 2007 International School Bus Vin #1520	<p>Unit #1007  Model: CE300  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: November 2021  Approx. Mileage (NOT ACTUAL): 142,123  Interior Condition: Fair  Interior Problems: Needs Cleaning - Minor Wear On Rear Seats  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	







16	(1) 2006 International School Bus Vin #9832	<p>Unit #961  Model: CE300  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Automatic  Air Brakes  Inspection Sticker Date: September 2021  Approx. Mileage (NOT ACTUAL): 161,878  Interior Condition: Fair  Interior Problems: Needs Cleaning - Minor Wear On Rear Seats  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
17	(1) 2006 International School Bus Vin #5545	<p>Unit #992  Model: CE300  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: March 2021  Approx. Mileage (NOT ACTUAL): 136,001  Interior Condition: Fair  Interior Problems: Needs Cleaning - Minor Wear On Rear Seats - A/C Cover Off A/C But Is Inside Unit  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	

18	(1) 2005 International School Bus Vin #5814	<p>Unit #916  Model: CE300  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: October 2021  Approx. Mileage (NOT ACTUAL): 154,696  Interior Condition: Fair  Interior Problems: Needs Cleaning - Minor Wear On Rear Seats  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Minor Rust &amp; Scratches On Front Bumper - Minor Peeling On Yellow Reflector Paint  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
19	(1) 2005 International School Bus Vin #5838	<p>Unit #925  Model: CE300  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: August 2021  Approx. Mileage (NOT ACTUAL): 169,415  Interior Condition: Fair  Interior Problems: Needs Cleaning - Minor Wear On Rear Seats  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	



20	(1) 2000 International Bluebird School Bus Vin #5487	<p>Unit #748  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Exhaust Smokes When Running  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: May 2021  Approx. Mileage (NOT ACTUAL): 152,743  Interior Condition: Fair  Interior Problems: Needs Cleaning - Wear On Rear Seats  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Scratches &amp; Dents On Front Bumper  Tires Condition: Fair  Tire Problems: Unknown  Additional Information: A/C Blows Cold Air</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
21	(1) 2000 International Bluebird School Bus Vin #5499	<p>Unit #739  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: March 2022  Approx. Mileage (NOT ACTUAL): 171,876  Interior Condition: Fair  Interior Problems: Needs Cleaning - Minor Wear On Rear Seats - Minor Rip On Driver Seat  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Rust On Rear Bumper  Tires Condition: Fair  Tire Problems: Unknown  Additional Information: A/C Blows Cold Air</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	



22	(1) 2000 International School Bus Vin #5495	<p>Unit #738  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: April 2021  Approx. Mileage (NOT ACTUAL): 168,305  Interior Condition: Fair  Interior Problems: Needs Cleaning - Driver Seat Torn - Soft Spot In Aisle At Seat #2, 4, 6, 9, &amp; 10  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Peeling Paint On Hood - Dent &amp; Rust On Rear Bumper - Rust On Front Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
23	(1) 2000 International Bluebird School Bus Vin #5498	<p>Unit #749  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: March 2021  Approx. Mileage (NOT ACTUAL): 164,904  Interior Condition: Fair  Interior Problems: Needs Cleaning - Wear On Rear Seats - Soft Spot In Aisle At Seat #6  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Rust &amp; Peeling Paint On Front Bumper - Dent On Passenger Side Corner Above Bumper - Minor Rust On Rear Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	



24	(1) 2000 International Thomas School Bus Vin #0171	<p>Unit #789  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: March 2021  Approx. Mileage (NOT ACTUAL): 141,014  Interior Condition: Fair  Interior Problems: Needs Cleaning - Driver Seat Tearing - Soft Spot In Floor Next To Driver Seat &amp; All Down Aisle - Minor Wear On Seats In Back  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Peeling Paint On Hood - Dents On Passenger &amp; Driver Side Rear Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
25	(1) 2000 International Thomas School Bus Vin #0156	<p>Unit #795  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: March 2021  Approx. Mileage (NOT ACTUAL): 79,361  Interior Condition: Fair  Interior Problems: Needs Cleaning - Driver Seat Tearing - Soft Spot In Aisle At Seat #2, 3, 6, 7 &amp; 10  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Peeling Paint On Cowl - Dent On Driver &amp; Passenger Side Rear Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	



26	(1) 2000 International Thomas School Bus Vin #0147	<p>Unit #781  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: December 2021  Approx. Mileage (NOT ACTUAL): 144,231  Interior Condition: Fair  Interior Problems: Needs Cleaning - Driver Seat Tearing - Soft Spot In In Floor Next To Driver Seat &amp; Seat #7, 8 &amp; 9 - Seats Worn In Back  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
27	(1) 2006 International School Bus Vin #9842	<p>Unit #959  Model: CE300  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: August 2021  Approx. Mileage (NOT ACTUAL): 157,147  Interior Condition: Fair  Interior Problems: Needs Cleaning - Driver Seat Tearing - Seats Worn In Back  Body Condition: Fair  Body Problems: Minor Oxidized Paint - Minor Scratch &amp; Rust On Rear Bumper  Tires Condition: Fair  Tire Problems: Unknown  Additional Information: A/C Works &amp; Blows Cold</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	







28	(1) 2000 International Bluebird School Bus Vin #5494	<p>Unit #747  Model: 3800  Passenger: 71  Engine Size/Type:DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: March 2021  Approx. Mileage (NOT ACTUAL): 188,199  Interior Condition: Fair  Interior Problems: Needs Cleaning - Driver Seat Tearing - Duct Tape On Part Of Control Panel Holding It Together - Front Panel Behind Driver Seat Is Tearing - Back Seats Worn - Soft Spot In Aisle Behind Driver Seat &amp; Seat #1, 5 &amp; 9  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Rust On Front Bumper - Minor Peeling Paint On Hood - Minor Rust On Rear Bumper - Hood Is Bad, Loose On Unit, Cracked On Bottom  Tires Condition: Fair  Tire Problems: Unknown  Additional Information: A/C Works &amp; Blows Cold</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
29	(1) 2000 International School Bus Vin #5502	<p>Unit #735  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Inspection Sticker Date: April 2021  Approx. Mileage (NOT ACTUAL): 151,908  Interior Condition: Fair  Interior Problems: Needs Cleaning - Driver Seat Tearing - Minor Tears In Back Seats - Soft Spot In Aisle At Seat #6 &amp; 9  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Peeling Paint &amp; Rust On Front Bumper - Minor Paint Peeling On Hood - Minor Rust On Rear Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	

30	(1) 2000 International Thomas School Bus Vin #0166	<p>Unit #780  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: August 2021  Approx. Mileage (NOT ACTUAL): 153,706  Interior Condition: Fair  Interior Problems: Needs Cleaning - Driver Seat Tearing - Minor Wear On Back Seats - Soft Spot In Aisle At Seat #3, 4, 5, 8 &amp; 9  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Peeling Paint On Hood &amp; Cowl - Minor Rust On Front Bumper - Dent On Passenger &amp; Driver Side Of Rear Bumper - Small Dent On Passenger Side Wheel Well At Rear Tire  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
31	(1) 2000 International Bluebird School Bus Vin #5520	<p>Unit #752  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: April 2021  Approx. Mileage (NOT ACTUAL): 172,501  Interior Condition: Fair  Interior Problems: Needs Cleaning - Minor Tears In Drivers Seat - Minor Wear In Back Seats - Soft Spot In Aisle @ Seat #4, 5 &amp; 9  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Rust &amp; Scratches On Rear Bumper On Driver &amp; Passenger Side - Scratches On Passenger Side Wheel Well By Back Tire  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	



32	(1) 2000 International Bluebird School Bus Vin #5489	<p>Unit #746  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: May 2021  Approx. Mileage (NOT ACTUAL): 151,776  Interior Condition: Fair  Interior Problems: Needs Cleaning - Floorboard Is Damaged Under Drivers Seat - Soft Spot In Aisle At Seat #6 - Rubber Molding Coming Off Of Mirror Above Driver Seat  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Rust On Front Bumper  Tires Condition: Fair  Tire Problems: Unknown  Additional Information: A/C Works - Air Does Not Seem Cold</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
33	(1) 2000 International Thomas School Bus Vin #0144	<p>Unit #779  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: May 2021  Approx. Mileage (NOT ACTUAL): 116,769  Interior Condition: Fair  Interior Problems: Needs Cleaning - Drivers Seat Starting To Tear - Soft Spot In Aisle At Seat #2, 3, 9 &amp; 10 - Minor Wear In Back Seats  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Peeling Paint On Hood &amp; Cowl - Rust On Front Bumper - Dents On Driver &amp; Passenger Side Rear Bumper - Minor Rust On Rear Bumper - Dent &amp; Scratch On Passenger Wheel Well At Back Tire  Tires Condition: Fair  Tire Problems: Unknown  Additional Information: A/C Works - Blows Cold</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	



34	(1) 2000 International Bluebird School Bus Vin #5506	<p>Unit #741  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: August 2021  Approx. Mileage (NOT ACTUAL): 130,889  Interior Condition: Fair  Interior Problems: Needs Cleaning - Drivers Seat Starting To Tear  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Minor Rust On Front Bumper - Minor Scratches &amp; Rust On Rear Bumper  Tires Condition: Fair  Tire Problems: Unknown  Additional Information: A/C Works - Does Not Seem To Be Cooling</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
35	(1) 2000 International School Bus Vin #5509	<p>Unit #727  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: February 2022  Approx. Mileage (NOT ACTUAL): 134,894  Interior Condition: Fair  Interior Problems: Needs Cleaning - Minor Wear In Back Seats  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Dent, Scratches &amp; Rust On Front Bumper - Minor Scratches &amp; Rust On Rear Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	



36	(1) 2000 International Thomas School Bus Vin #0165	<p>Unit #794  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: March 2021  Approx. Mileage (NOT ACTUAL): 173,496  Interior Condition: Fair  Interior Problems: Needs Cleaning - Minor Wear In Back Seats  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Rust On Front Bumper - Dent On Driver &amp; Passenger Side Of Rear Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
37	(1) 2000 International Bluebird School Bus Vin #5515	<p>Unit #751  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: August 2021  Approx. Mileage (NOT ACTUAL): 180,936  Interior Condition: Fair  Interior Problems: Needs Cleaning - Back Seats Worn  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	



38	(1) 2000 International Bluebird School Bus Vin #5492	<p>Unit #745  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Air Brakes  Inspection Sticker Date: June 2021  Approx. Mileage (NOT ACTUAL): 111,635  Interior Condition: Fair  Interior Problems: Needs Cleaning - Driver Seat Tearing - Minor Wear On Seats In Back  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Rust On Rear Bumper - Scratch On Hood On Passenger Side Close To Mirror Bracket  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
39	(1) 2006 International School Bus Vin #5530 - Will Need To Be Towed	<p>Will Need To Be Towed  Unit #975  Model: CE300  Passenger: 16  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery, Dead  Does Not Run  Automatic  Air Brakes  Inspection Sticker Date: February 2022  Approx. Mileage (NOT ACTUAL): 156,725  Has Wheel Chair Lift - Condition: Unknown  Interior Condition: Fair  Interior Problems: Needs Cleaning  Body Condition: Fair  Body Problems: Oxidized Paint - Reflectors Peeling On Front Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	






40	(1) 2000 International Thomas School Bus Vin #0167 - Will Need To Be Towed	<p>Will Need To Be Towed  Unit #788  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery, Dead  Does Not Run  Automatic  Inspection Sticker Date: May 2021  Approx. Mileage (NOT ACTUAL): 144,136  Interior Condition: Fair  Interior Problems: Needs Cleaning - Minor Tears In Driver Seat - Soft Spot In Aisle At Seat #3 - Seats In Back Need Cleaning  Body Condition: Fair  Body Problems: Oxidized Paint - Peeling Paint On Hood - Dent On Passenger &amp; Driver Side Rear Bumper - Peeling Paint Above Passenger Rear Wheel Well  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
41	(1) 2000 International Bluebird School Bus Vin #5507 - Will Need To Be Towed	<p>Will Need To Be Towed  Unit #761  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery, Dead  Does Not Run  Automatic  Air Brakes  Inspection Sticker Date: May 2019  Approx. Mileage (NOT ACTUAL): 158,803  Interior Condition: Fair  Interior Problems: Needs Cleaning - Back Seat Needs Major Cleaning  Body Condition: Fair  Body Problems: Oxidized Paint - Front Driver Side Headlight Is Cracked - Peeling Paint On Hood - Glass Cracked On Entry Door - Dent &amp; Scratches On Driver Side On The "School Bus" Decal  Tires Condition: Fair  Tire Problems: Unknown  Additional Information: Has Been Sitting For Several Years</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	

42	(1) 2007 International School Bus Vin #1567 - Will Need To Be Towed	<p>Will Need To Be Towed  Unit #1049  Model: CE300  Passenger: 71  Engine Size/Type: DT466E/7.6L  Engine Problems: Unknown  Diesel  Has Battery, Dead  Does Not Run  Automatic  Air Brakes  Inspection Sticker Date: July 2021  Approx. Mileage (NOT ACTUAL): Unable To Read  Interior Condition: Fair  Interior Problems: Needs Cleaning - Driver Seat Starting To Tear - Part Of Dashboard Missing  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Minor Scratches &amp; Rust On Front Bumper - Dent &amp; Scratches On Passenger Side Rear Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
43	(1) 2006 International School Bus Vin #5542 - Will Need To Be Towed	<p>Will Need To Be Towed  Unit #995  Model: CE300  Passenger: 71  Engine Size/Type: DT466E/7.6L  Engine Problems: Unknown  Diesel  Has Battery, Dead  Does Not Run  Automatic  Air Brakes  Inspection Sticker Date: May 2021  Approx. Mileage (NOT ACTUAL): Unable To Read  Interior Condition: Fair  Interior Problems: Needs Cleaning - Minor Damage To Driver Seat - Crack In Plastic Cover Of Dashboard  Body Condition: Fair  Body Problems: Oxidized Paint -Front Passenger Side Fender Damaged - Scratches &amp; Dents On Passenger Side Rear Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	

44	(1) 2008 International School Bus Vin #1473 - Will Need To Be Towed	<p>Will Need To Be Towed  Unit #1130  Model: CE300  Passenger: 71  Engine Size/Type: 7.6L/MaxxForce DT  Engine Problems: Unknown  Diesel  Has Battery, Dead  Does Not Run  Automatic  Air Brakes  Inspection Sticker Date: January 2021  Approx. Mileage (NOT ACTUAL): Unable To Read  Interior Condition: Fair  Interior Problems: Needs Cleaning - A/C Cover Off Of A/C But Is Inside Unit - Panel Loose In Back On Passenger Side  Body Condition: Fair  Body Problems: Oxidized Paint - Rust &amp; Scratches On Front Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
45	(1) 2009 International School Bus Vin #6119 - Will Need To Be Towed	<p>Will Need To Be Towed  Unit #6124  Model: CE300  Passenger: 14 + 2 Wheel Chairs  Engine Size/Type: 7.6L MaxxForce DT  Engine Problems: Unknown  Diesel  Has Battery, Dead  Does Not Run  Automatic  Air Brakes  Inspection Sticker Date: January 2021  Approx. Mileage (NOT ACTUAL): Unable To Read  Interior Condition: Fair  Interior Problems: Needs Cleaning - Minor Tears In Drivers Seat - Motor Cover Missing On Floorboard  Body Condition: Fair  Body Problems: Oxidized Paint - Minor Rust On Front Bumper  Tires Condition: Fair  Tire Problems: Unknown  Additional Information: Has 3rd Door</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	

46	(1) 2006 International School Bus Vin #9843 - Will Need To Be Towed	<p>Will Need To Be Towed  Unit #966  Model: CE300  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery, Dead  Does Not Run  Automatic  Air Brakes  Inspection Sticker Date: September 2020  Approx. Mileage (NOT ACTUAL): 170,411  Interior Condition: Fair  Interior Problems: Needs Cleaning  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Minor Dent In Rear Bumper - Paint Worn On Rear Emergency Door  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
47	(1) 2006 International School Bus Vin #9833 - Will Need To Be Towed	<p>Will Need To Be Towed  Unit #952  Model: CE300  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery, Dead  Does Not Run  Automatic  Air Brakes  Inspection Sticker Date: October 2021  Approx. Mileage (NOT ACTUAL): 147,651  Interior Condition: Fair  Interior Problems: Needs Cleaning - Driver Seat Starting To Tear - Minor Wear On Back Seats  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Minor Hood Damage On Passenger Side Above Head Light - Minor Scratches &amp; Rust On Rear Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	

48	(1) 2000 International Bluebird School Bus Vin #5523 - Will Need To Be Towed	<p>Will Need To Be Towed  Unit #755  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Will Not Run - Engine Problems Unknown  Diesel  Has Battery, Dead  Does Not Run  Automatic  Air Brakes  Inspection Sticker Date: April 2020  Approx. Mileage (NOT ACTUAL): 161,104  Interior Condition: Fair  Interior Problems: Some Torn Seats  Body Condition: Fair  Body Problems: Oxidized Paint - Surface Scratches  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</b></p> <p>- Current Condition Unknown</p>	
49	(1) 2000 International Bluebird School Bus Vin #5493 - Will Need To Be Towed	<p>Will Need To Be Towed  Unit #753  Model: 3800  Passenger: 71  Engine Size/Type: DT466E  Engine Problems: Will Not Run - Engine Problems Unknown  Diesel  Has Battery, Dead  Does Not Run  Automatic  Air Brakes  Inspection Sticker Date: May 2021  Approx. Mileage (NOT ACTUAL): 151,314  Interior Condition: Fair  Interior Problems: Some Torn Seats  Body Condition: Fair  Body Problems: Oxidized Paint - Minor Scratches - Dent On Left Rear  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</b></p> <p>- Current Condition Unknown</p>	

50	(1) 2005 International School Bus Vin #5840 - Will Need To Be Towed	<p>Will Need To Be Towed  Unit #919  Model: CE300  Passenger: 71  Engine Size/Type: 7.6L  Engine Problems: Missing Parts  Diesel  Has Battery, Dead  Does Not Run  Automatic  Air Brakes  Inspection Sticker Date: October 2019  Approx. Mileage (NOT ACTUAL): Unknown  Interior Condition: Fair  Interior Problems: Needs Cleaning - Some Tears In Seats - Driver Dashboard Area Missing - Some Rust  Body Condition: Good  Body Problems: Scratches - Missing Stop Sign - Missing Hood Grill - Missing Front Headlights - Missing Left Top Blinker  Tires Condition: Fair  Tire Problems: Unknown  Additional Information: Has Been Sitting For Several Years</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	
51	(1) 2000 International Bluebird School Bus Vin #5488	<p>Unit #798  Model: 3800  Passenger: 72  Engine Size/Type: DT466E  Engine Problems: Unknown  Diesel  Has Battery, Dead  Does Not Run  Automatic  Air Brakes  Inspection Sticker Date: June 2021  Approx. Mileage (NOT ACTUAL): 178,495  Interior Condition: Fair  Interior Problems: Needs Cleaning - Minor Wear On Back Seats - Back Seats Need Cleaning - Soft Spot &amp; Tear In Rubber In Aisle At Seat #9  Body Condition: Good  Body Problems: Oxidized Paint - Surface Scratches, Dents &amp; Rust - Minor Rust On Front Bumper - Scratch &amp; Dent On Driver Side Rear Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	