














Lot Number	Title	Description	Thumbnail
1	(1) 2014 Ford Explorer Police Interceptor Vin #5084	Unit #2569 Passengers: 4 Engine Size: 3.7L Engine Problems: Unknown Gas Has Battery Runs Automatic Hydraulic Brakes Inspection Sticker Date: May 2021 Approx. Mileage (NOT ACTUAL): 106,513 Interior Condition: Fair Interior Problems: Driver Seat Torn - Driver Side Door Panel Is Ripped - Needs Cleaning - Middle Console Is Missing Exterior Condition: Fair Exterior Problems: Surface Rust, Scratches & Dents - Holes In Roof Where Lightbar Was Mounted (Holes Do Not Go All The Way Through) - Rubber On Driver Side Windshield Is Torn Tires Condition: Fair Tires Problems: Unknown  - Current Condition Unknown	
2	(1) 2014 Ford Explorer Police Interceptor Vin #5080	Unit #2565 Passengers: 4 Engine Size: 3.7L Engine Problems: Unknown Gas Has Battery Runs Automatic Hydraulic Brakes Inspection Sticker Date: April 2021 Approx. Mileage (NOT ACTUAL): 115,401 Interior Condition: Fair Interior Problems: Driver Seat Torn - Needs Cleaning - Middle Console Is Missing Exterior Condition: Fair Exterior Problems: Surface Rust, Scratches & Dents - Scratches & Holes In Roof Where Lightbar Was Mounted (Holes Do Not Go All The Way Through) - Minor Paint Peeling Tires Condition: Fair Tires Problems: Unknown  - Current Condition Unknown	
3	(1) 2014 Ford Explorer Police Interceptor Vin #5085	Unit #2570 Passengers: 4 Engine Size: 3.7L Engine Problems: Unknown Gas Has Battery Runs Automatic Hydraulic Brakes Inspection Sticker Date: May 2021 Approx. Mileage (NOT ACTUAL): 87,978 Interior Condition: Fair Interior Problems: Driver Seat Torn - Needs Cleaning - Middle Console Is Missing Exterior Condition: Fair Exterior Problems: Surface Rust, Scratches & Dents - Scratches & Holes In Roof Where Lightbar Was Mounted (Holes Do Not Go All The Way Through) - Minor Paint Peeling - Dent & Paint Damage On Driver Side Next To Windshield - Dent On Driver Side Door @ Opening - Front Driver Side Wheel Well Is Loose Tires Condition: Fair Tires Problems: Unknown  - Current Condition Unknown	

4	(1) 2014 Ford Explorer Police Interceptor Vin #5082	<p>Unit #2567  Passengers: 4  Engine Size: 3.7L  Engine Problems: Unknown  Gas  Has Battery  Runs  Automatic  Hydraulic Brakes  Inspection Sticker Date: May 2021  Approx. Mileage (NOT ACTUAL): 94,921  Interior Condition: Fair  Interior Problems: Driver Seat Torn - Needs Cleaning - Middle Console Is Missing - Rubber Molding On Passenger Back Door Is Loose  Exterior Condition: Fair  Exterior Problems: Surface Rust, Scratches &amp; Dents - Scratches &amp; Holes In Roof Where Lightbar Was Mounted (Holes Do Not Go All The Way Through) - Minor Paint Peeling - Dent &amp; Paint Damage On Driver Side Next To Windshield - Scratches On Driver Side Front Bumper - Molding Is Loose On Driver Side Windshield  Tires Condition: Fair  Tires Problems: Unknown</p> <p>- Current Condition Unknown</p>	
5	(1) 2015 Ford Explorer Police Interceptor Vin #9931	<p>Unit #2534  Passengers: 4  Engine Size: 3.7L  Engine Problems: Unknown  Gas  Has Battery  Runs  Automatic  Hydraulic Brakes  Inspection Sticker Date: December 2021  Approx. Mileage (NOT ACTUAL): 100,568  Interior Condition: Fair  Interior Problems: Driver Seat Torn - Needs Cleaning - Middle Console Is Missing  Exterior Condition: Fair  Exterior Problems: Surface Rust, Scratches &amp; Dents - Scratches &amp; Holes In Roof Where Lightbar Was Mounted (Holes Do Not Go All The Way Through) - Scratches &amp; Dents On Passenger Door - Dent On Passenger Side Wheel Well Behind Back Tire  Tires Condition: Fair  Tires Problems: Unknown</p> <p>- Current Condition Unknown</p>	
6	(1) 2012 Chevy Tahoe Vin #5339	<p>Unit #2558  Passengers: 4  Engine Size: 5.3L  Engine Problems: Unknown  Gas  Has Battery  Runs  Automatic  Hydraulic Brakes  Inspection Sticker Date: November 2021  Approx. Mileage (NOT ACTUAL): 96,999  Interior Condition: Fair  Interior Problems: Driver Seat Torn - Needs Cleaning - Middle Console Is Missing - Middle Console Is Missing - Dashboard Is Cracked - Exposed Wires Under The Dashboard - Driver Seat Is Starting To Tear - Molding On Driver Side Is Coming Loose  Exterior Condition: Fair  Exterior Problems: Surface Rust, Scratches &amp; Dents - Dent On Driver Side Front Wheel Well Above The Tire  Tires Condition: Fair  Tires Problems: Unknown  Additional Information: Has Running Boards</p> <p>- Current Condition Unknown</p>	

7	(1) 2012 Chevy Tahoe Vin #7814	Unit #2561 Passengers: 4 Engine Size: 5.3L Engine Problems: Unknown Gas Has Battery Runs Automatic Hydraulic Brakes Inspection Sticker Date: January 2021 Approx. Mileage (NOT ACTUAL): 95,337 Interior Condition: Fair Interior Problems: Driver Seat Torn - Needs Cleaning - Middle Console Is Missing - Dashboard Is Cracked - Driver Side Floor Board Is In Poor Condition Exterior Condition: Fair Exterior Problems: Surface Rust, Scratches & Dents - Hole On Driver Side Door Where Spot Light Was Mounted Tires Condition: Fair Tires Problems: Unknown  - Current Condition Unknown	
8	(1) 2009 Ford Escape Vin #9618	Unit #3173 Passengers: 4 Engine Size: 2.5L Engine Problems: Unknown Gas Has Battery Runs Automatic Hydraulic Brakes Inspection Sticker Date: February 2022 Approx. Mileage (NOT ACTUAL): 99,233 Interior Condition: Fair Interior Problems: Needs Cleaning Exterior Condition: Fair Exterior Problems: Surface Rust, Scratches & Dents - Rust & Dent On Driver Side - Back Window Has Bubbles In The Tint - Small Panel Of Passenger Side Window Is Missing Tires Condition: Fair Tires Problems: Unknown  - Current Condition Unknown	
9	(1) 2002 Chevrolet S10 Pickup Vin #7774 Will Need To Be Towed	Will Need to Be Towed Unit #4216 Passengers: 2 Engine Size: 4.3L Engine Problems: Has Bad Gas & Has Been Sitting For A Few Years Gas Has Battery Does Not Run Automatic Hydraulic Brakes Inspection Sticker Date: February 2022 Approx. Mileage (NOT ACTUAL): 37,809 Interior Condition: Fair Interior Problems: Needs Cleaning Exterior Condition: Fair Exterior Problems: Tailgate Is Missing - Front Bumper Is Faded - Dent In Passenger Side Wheel Well - Minor Damage To Rear Bumper - Surface Rust, Scratches & Dents Tires Condition: Fair Tires Problems: Unknown  - Current Condition Unknown	

10	(1) 1998 Freightliner Dump Truck Vin #8829	<p>Model: FL80 Unit #4296 Passengers: 2 Engine Size: 8.3L Engine Problems: Unknown Diesel Has Battery Runs Automatic Inspection Sticker Date: November 2021 Approx. Mileage (NOT ACTUAL): 47,713 Interior Condition: Fair Interior Problems: Needs Cleaning - Driver Seat Is Torn - Steering Wheel Is Worn - (1) Panel On Dashboard Is Missing - Knob On Driver Side Window Crank Is Missing Exterior Condition: Fair Exterior Problems: Surface Rust, Scratches &amp; Dents - Rust &amp; Dents On Back Gate - Minor Peeling Paint - Loose Headlight - Tires Problems: Unknown Additional Information: (Approx. 12 Cubic Yards) - Has Wench On Front Bumper, Rusted - Unknown If Wench Is Operational</p> <p>- Current Condition Unknown</p>	
11	(1) 2008 Ford F250 Super Duty XL Extended Cab Pickup Vi #2335	<p>Unit #5306 Passengers: 2 Engine Size: 5.4L Engine Problems: Unknown Gas Has Battery Runs Automatic Hydraulic Brakes Inspection Sticker Date: April 2021 Approx. Mileage (NOT ACTUAL): 99,768 Interior Condition: Fair Interior Problems: Needs Cleaning - Minor Damage on Front Floorboard - Steering Wheel Is Worn - Flaw In Rearview Mirror Exterior Condition: Fair Exterior Problems: Surface Rust, Scratches &amp; Dents - Rust &amp; Damage To Back Passenger Wheel Well Behind Tire - Dent In Driver Side Rear Wheel Well Behind Tire Tires Condition: Fair Tires Problems: Unknown Additional Information: Tailgate Has Hydraulic Lift, MFG: Matco, Unknown If Lift Is Operable - Has Toolbox In Bed</p> <p>- Current Condition Unknown</p>	
12	(1) 2011 Ford Crown Victoria Police Interceptor Vin #6804	<p>Unit #2557 Passengers: 4 Engine Size: 4.6L Engine Problems: Unknown Gas Has Battery Runs Automatic Hydraulic Brakes Inspection Sticker Date: September 2021 Approx. Mileage (NOT ACTUAL): 69,089 Interior Condition: Fair Interior Problems: Needs Cleaning - Driver Side Seat Is Tearing - Middle Console Is Missing - Rear Window Tint Has Bubbles In Tint - Scratches On Back Seat Exterior Condition: Fair Exterior Problems: Surface Rust, Scratches &amp; Dents - Hole Filled In On Trunk Where Antennas Were Mounted Tires Condition: Fair Tires Problems: Unknown</p> <p>- Current Condition Unknown</p>	

13	(1) 2010 Ford Crown Victoria Vin #0068	Unit #2404 Passengers: 4 Engine Size: 4.6L Engine Problems: Unknown Gas Has Battery Runs Automatic Hydraulic Brakes Inspection Sticker Date: November 2021 Approx. Mileage (NOT ACTUAL): 97,305 Interior Condition: Fair Interior Problems: Needs Cleaning - Crack In Windshield - Steering Wheel Is Worn - Dashboard Has Oxidation From Sun Exterior Condition: Fair Exterior Problems: Surface Rust, Scratches & Dents -Peeling Paint On Hood - Plastic Molding On Passenger & Driver Side Is Cracked Tires Condition: Fair Tires Problems: Unknown  - Current Condition Unknown	
14	(1) 2008 Ford F150 Extended Cab Pickup XLT Triton Vin #9532	Unit #3202 Passengers: 4 Engine Size: 4.6L Engine Problems: Unknown Gas Has Battery Runs Automatic Hydraulic Brakes Inspection Sticker Date: September 2021 Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Fair Interior Problems: Needs Cleaning - Driver Seat Is Starting To Tear - Minor Bubbles In Tint In Driver Side Window Exterior Condition: Fair Exterior Problems: Surface Rust, Scratches & Dents -Oxidized Paint On Hood & Front Bumper - Dents & Paint Missing On Passenger Side Bed Behind Rear Door Tires Condition: Fair Tires Problems: Unknown Additional Information: Has Bed Cover  - Current Condition Unknown	
15	(1) 2005 Terex Front End Loader /Backhoe	Model: 760B S/N: SMFH44TR05BFM6699 Horse Power: 68.5 KW Runs Diesel Closed Cab Hour Meter Reading: 02856 Running Condition: Operable Tires Condition: Fair Has 2007 (Year) Outriggers Has TX 760B Backhoe Has 9 Terex TXH1400S Attachment Working Pressure: 1781 PSI  - Current Condition Unknown	
16	(1) Done Right (DR) Field & Brush Mower	Model: PRO XL30 All Terrain Coil Is Removed & Battery Is Bad Has Key  - Current Condition Unknown	
17	(1) Done Right (DR) Field & Brush Mower	Model: PRO XL30 All Terrain Worked At Time Of Removal Has Key  - Current Condition Unknown	

18	(1) Western Products Tornado Spreader	1/2V DC Motor MFG Date: 2014 2.5 Cubic Feet  - Current Condition Unknown	
19	(1) HTC Inc. 96" Conveyor	Unit #42159 Model: 1800 Some Damage Has Been Sitting Up  - Current Condition Unknown	
20	(1) H.D. Lawn Roller	(Approx. 24" Diameter X 36" Wide") Dry Weight 110 Lbs. Has Rust  - Current Condition Unknown	
21	(1) Toro Bumper Pull Cement Mixer	Model: CM-958H Engine Will Pull Gas Honda GX240 Motor  - Current Condition Unknown	
23	(Lot) Safety Cone Bases	MFG: Zephyr Stand & Possible Others Quantity Unknown (3) Poles NOT INCLUDED  - Current Condition Unknown	
24	(Lot) A/C Units	(Approx. 6) MFG: Trane Model: XL16I Some Are Missing Panels  - Current Condition Unknown	
25	(Lot) Heavy Duty Railing	(Approx. 4) (Approx. 24' 11") & Possible Other Sizes  - Current Condition Unknown	
26	(Lot) Plastic Safety Barriers	MFG: Barco Model: Map 1500 Various Sizes & Types  - Current Condition Unknown	
27	(1) Spool Of Hose	MFG: Feet Dura-Line Smooth Wall 1 1/4 IPS Quantity Unknown  - Current Condition Unknown	
28	(1) Dump Truck Protective Shield	(Approx. 84" X 105")  - Current Condition Unknown	
29	(Lot) Chain Link Fence Panels & Misc. Fence Parts	(Approx. 7) Various Sizes  - Current Condition Unknown	



30	(Lot) Ford Pickup Bumpers	Models Unknown - Current Condition Unknown	
31	(Lot) Intersection Development Corp. Light Enclosures	(Approx. 20) Metal W/Plastic Lid Empty - Current Condition Unknown	
32	(Lot) Intersection Development Corp. Light Enclosures	(Approx. 24) Metal W/Plastic Lid Empty - Current Condition Unknown	
33	(Lot) Office Chairs	(Approx. 20) Need Cleaning Various Types Have Been Stored In Connex Container - Current Condition Unknown	
34	(Lot) Plastic Round Tables W/Cart	(Approx. 7) 60" MFG: Palmer-Snyder Need Cleaning Have Been Stored In Connex Container - Current Condition Unknown	
35	(Lot) Straight Back Chairs	(Approx. 17) Most Are Peeling Poor Condition Have Been Stored In Conned Container - Current Condition Unknown	
36	(Lot) Pump Hoses	MFG: Unknown (Approx. 26'3" X 6") - Current Condition Unknown	
37	(Lot) Traffic Channelizers & Misc.	MFG: Davidson Traffic Control Products Model: FG 300 Quantity Unknown - Current Condition Unknown	
38	(Lot) Plastic & Metal Culverts	(1) 30' Metal (1) 19 1/2' Metal (1) 9'11" Metal - Damaged (Approx. 2) 20' Metal - Damaged (1) Plastic 9'2" (1) 20' Plastic - Damaged On One End - Current Condition Unknown	
39	(Lot) Concrete Culverts	(Approx. 14) (Approx. 48" X 24") - Current Condition Unknown	

40	(1) Concrete Manway	(Approx. 9'4" X 5'3") Some Damage - Current Condition Unknown	
41	(Lot) Rubber Flooring Squares	(Approx. 30" X 24") Large Quantity Located Outside - Current Condition Unknown	
42	(LoT) Traffic Management Fiberglass Manholes	(Approx. 7) (Approx. 48" X 32") Located Outside - Current Condition Unknown	
43	(1) Portable Genie Personnel Man Lift	Model: PLC19 Platform Height - 19 FT. 115V - 60HZ - 8.2 AMPS 300 Lb. Capacity - Current Condition Unknown	
44	(Lot) Metal Cargo Area Cabinets	MFG: Adrian Steel Various Types - Current Condition Unknown	
45	(Lot) Metal Parts Cabinets & Misc.	(Approx. 2) Metal Parts Cabinets - MFG: Cole - 36 Drawers Per Cabinet ISC Roller (Approx. 6) Jamar Technologies Inc. Sign Controllers - Model: TRAX1 - Some Have Solar Panels - Current Condition Unknown	
46	(Lot) Foam Gym Flooring & Exercise Equipment	(Approx. 3 Rolls) Sizes Per Roll Unknown Barbells & Exercise Ball (Deflated) - Punching Bag - Current Condition Unknown	
47	(1) Bauer Compressors Breathing Air Unit For Life Support	MFG: BF150 - Current Condition Unknown	
48	(Lot) Plastic Culverts	(Approx. 6) 20' (1) 9'9" - Current Condition Unknown	



**\*\*All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes\*\***

**IMPORTANT NOTICE FOR CITY OF MISSOURI CITY ONLINE AUCTION: \*\*All purchases will be subject to a (14%) buyer's premium. There Will Be A 3% Fee For All Purchases Not Made By Cash, Cashier's Check, Direct Deposit, Money Order & Wire Transfer\***

**CDC COVID-19 GUIDELINES WILL BE OBSERVED – WEAR A MASK AND STAY AT LEAST 6 FT. APART.**

**Preview:** (By Appointment Only-Mandatory-No Exceptions) Thursday, May 20, 2021 (Hours Of Operation: 8:00 A.M. - 11:00 A.M./1:00 P.M. – 3:00 P.M.)

**Location:** Fleet Services, 1919 Scanlin Rd, Missouri City, TX 77489 [Driving Directions](#)

**Removal Dates & Times:** (By Appointment Only-Mandatory-No Exceptions) Wednesday, May 26, 2021/Thursday, May 27, 2021/Friday, May 28, 2021 (Hours Of Operation: 8:00 A.M. - 11:00 A.M./1:00 P.M. – 3:00 P.M.)

**Preview & Removal Contact:** Fleet Superintendent, Mike Tubbs or Shop Foreman, Hung Hoang, 281-403-8583

"Forklift Will Be Available For Removal"

**There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.**

***\*\*All defects and flaws with a vehicle will be the buyer's responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. \*\****

**Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And /or Removed.**

***Removal Note: There Will Be No Manpower, No Employee Assistance Or Equipment Available For Removal. Buyer Must Remove All Lots In Their Entirety. Buyer Is Solely Responsible For Loading & Unloading, Bring Own Manpower, Equipment, Dollies Or Other Adequate Moving Devices or Equipment, Etc. To Remove Items. Buyer Must Have Adequate Transportation To Move Purchased Items.***

0

Preview &  
Removal  
Information

