










| Lot Number | Title | Description | Thumbnail |
|------------|-------------------------------|--|---|
| 0 | Preview & Removal Information | <p>IMPORTANT NOTICE FOR NORTH ZULCH ISD ONLINE AUCTION: <i>**All purchases will be subject to a (14%) buyer's premium. There Will Be A 3% Fee For All Purchases Not Made By Cash, Cashier's Check, Direct Deposit, Money Order & Wire Transfer*</i></p> <p>Preview: (By Appointment Only-Mandatory-No Exceptions) Thursday, June 24, 2021 (Hours Of Operation: 9:00 A.M. - 11:00 A.M. AND 1:00 P.M. - 3:00 P.M.)</p> <p>Location: Transportation & Maintenance Department, 11390 5th Street, North Zulch, TX, 77872</p> <p>Removal Dates & Times: (By Appointment Only-Mandatory-No Exceptions) Wednesday, June 30, 2021/Thursday, July 1, 2021/Monday, July 7, 2021 (Hours Of Operation: 9:00 A.M. - 11:00 A.M. AND 1:00 P.M. - 3:00 P.M.)</p> <p>Preview & Removal Contact: Harold Sapp (936) 349-5959 or Jill Max (936) 241-7100 x 1701</p> <p>Removal Note: <i>There Will Be No Manpower And No Employee Assistance Available For Removal. Lifting Equipment Available By Appointment. Buyer Must Remove All Lots In Their Entirety. Buyer Is Solely Responsible For Loading & Unloading, Bring Own Manpower, Dollies Or Other Adequate Moving Devices or Equipment, Etc. To Remove Items. Buyer Must Have Adequate Transportation To Move Purchased Items.</i></p> <p>Note For Vehicles: <i>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</i></p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</p> <p>Removal Note For Vehicles: <i>Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</i></p> |  |

| | | | |
|---|--|---|---|
| 1 | (1) 2004 Chev Suburban VIN #1154 | <p>Will Not Need To Be Towed Conventional Style Passenger: 8 Engine Size & Type: 5.3 L Engine In Front Engine Problems: Unknown Gas Battery: Yes Runs: Yes Automatic Brakes: Hydraulic Inspection Sticker: N/A Mileage Reads: 133,623 (Not Actual) Interior Condition: Fair Interior Problems: Normal Wear - Needs Cleaning - Carpet Needs Cleaning Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Rock Chip On Windshield - Surface Rust on Roof - Peeling On Hood And Other Locations On Vehicle Tires Condition: Fair Tire Problems: Rear Right Is Questionable - Remainder Tires Are Fair Additional Information: N/A Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p> |  |
| 2 | (1) 2009 International /Thomas School Bus CE 200 VIN #3943 | <p>Will Not Need To Be Towed Bus # 09-2 Conventional Style Passenger: 65 Engine Size & Type: Maxx Force 7 Engine In Front Engine Problems: Ran When Parked - Current Condition Unknown Has Sat For Approx. 3 Years And Has Not Been Used In That Timeframe Diesel Battery: Yes - Dead Runs: No Automatic Inspection: 01/18 Mileage Reads: N/A - Dash Removed Interior Condition: Fair Interior Problems: Dash Removed - Seats Worn & Torn - Needs Cleaning Body Condition: Fair Body Problems: Needs Cleaning - Roof Need Cleaning - Slight Indentation In Right Rear Lower Panel - Front Mirror Removed - Right Front Headlight Removed - Stop Sign Motor Removed Tires Condition: Fair Tire Problems: N/A Additional Information: N/A</p> <p>- Current Condition Unknown</p> |  |
| 3 | (1) 2000 Hanover Gooseneck Livestock Trailer VIN #8536 | <p>Manufacturer: Hanover Trailer By Trailite, Inc. Problems: Unknown Dual Axle Has Minor Surface Rust Interior Condition: Fair Body Condition: Fair Tires Condition: Fair Overall Length: 30 Ft Long 8 Ft 6 In Wide Enclosed Area: 24 Ft Long 8 Ft 6 In Wide</p> <p>- Current Condition Unknown</p> |  |

| | | | |
|----|---|---|---|
| 4 | (1) Sliding Window | Manufacturer: Quikserv Model: 180 In Box (Approx.) Size: 48" x 48" - Current Condition Unknown |  |
| 5 | (1) Wilder Mfg. Co., Inc Shear | Belt Driven Salinas California Works 6 Gauge Mild Steel Model: 1?2 (Middle Number Unreadable) - Current Condition Unknown |  |
| 6 | (1) Hydraulic Pipe With Attachments | Brand: Jet Bender Max Bending Capacity: 3" Schedule 40 Model: JHPB-30 Works - Current Condition Unknown |  |
| 7 | (1) Miller Thunderbolt XL Electric Welder | (1) Lead Cut/Will Need Repair 225/150 Amp CC AC/DC Welding Power Source - Current Condition Unknown |  |
| 8 | (1) Evolution Cut Off Saw | 1800 Watt Bad Electric Motor 20" Abrasive Disc D145S0303 - Current Condition Unknown |  |
| 9 | (1) Horizontal Metal Cut Board Saw | 4.5" Cutting Capacity Motor: 120V/60 Hz 3/4 HP Single Phase No Blade Portable Works Belt Driven Needs Belts - No Belt Included - Current Condition Unknown |  |
| 10 | (1) Miller Dialasc Electric Welder | 250-AC/DC Electric Welder Needs Repair Arc Welding Power Source Small Cart Included - Current Condition Unknown |  |
| 11 | (1) Miller Millermatic 251 Electric Wire Welder | Needs Repair Will Not Work Portable Stock: 9033868 Volts 200/230 Phase 1 KW: 7.5, Hz: 60 - Current Condition Unknown |  |
| 12 | (1) Delta Shopmaster Drill Press | Model: DP350 Type 1 Needs Repair - Current Condition Unknown |  |

| | | | |
|----|--|--|---|
| 14 | (1) Datamatron Laptop Storage Cart | Metal Portable With Key (Approx.) Size: 52" Wide x 19" Depth x 48" Tall - Current Condition Unknown |  |
| 15 | (1) Datamatron Tablet Storage Cart | Portable (Approx.) Size: 36" Wide x 23" Depth x 30" Tall - Current Condition Unknown |  |
| 16 | (1) Datamatron Tablet Storage Cart | Portable (Approx.) Size: 36" Wide x 23" Depth x 30" Tall - Current Condition Unknown |  |
| 17 | (1) Datamatron Tablet Storage Cart | Portable (Approx.) Size: 36" Wide x 23" Depth x 30" Tall - Current Condition Unknown |  |
| 18 | (1) Datamatron Tablet Storage Cart | Portable (Approx.) Size: 36" Wide x 23" Depth x 30" Tall - Current Condition Unknown |  |
| 19 | (1) Anthro Mobile Device Charging Cabinet | Table Top Style (Approx.) Size: 21" Wide x 12" Depth x 24" Tall - Current Condition Unknown |  |
| 20 | (1) Electric Projection Screen | 110 Volt AC 60 Hz YM1434694 In Box (Approx.) Size: 117" Long Mustang, SC-E120D169R - Current Condition Unknown |  |
| 21 | (Lot) iPad Table Top Charger & Charging Cart | (1) Bretford iPad Table Top Charger Fan Needs Replacing (1) Lap Top Charging Cart Portable - Current Condition Unknown |  |
| 22 | (1) Anchor Beacon 8000 Speaker System | Anchor Audio, Inc. Volume Control Needs Repair Portable Can Use With BlueTooth And Wireless Mic Has Wireless Mics - Current Condition Unknown |  |