












Lot Number	Title	Description	Thumbnail
0	Coming Soon	<p>**All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes**</p> <p>IMPORTANT NOTICE FOR Leander ISD ONLINE AUCTION: **All purchases will be subject to a (14%) buyer's premium. There Will Be A 3% Fee For All Purchases Not Made By Cash, Cashier's Check, Direct Deposit, Money Order & Wire Transfer*</p> <p>CDC COVID-19 GUIDELINES WILL BE OBSERVED – WEAR A MASK AND STAY AT LEAST 6 FT. APART.</p> <p>Preview: (By Appointment Only-Mandatory-No Exceptions) Wednesday, June 23, 2021 (Hours Of Operation: 7:00 A.M. - 3:00 P.M.) Location: Transportation North Terminal, 2332 Sage Ranch Dr, Leander, TX 78641 Driving Directions Removal Dates & Times: (By Appointment Only-Mandatory-No Exceptions) Monday, June 28, 2021/Tuesday, June 29, 2021/Wednesday, June 30, 2021 (Hours Of Operation: 7:00 A.M. - 3:00 P.M.) Preview & Removal Contact: David Ishman, 512-536-0961/ Darrell Volkert, 512-570-0627</p> <p>Note: All Lot Items are AS IS Leander I.S.D. Does Not Guarantee the Condition of Any Lot Item</p> <p>Removal Note: <i>There Will Be No Manpower, No Employee Assistance Or Equipment Available For Removal. Buyer Must Remove All Lots In Their Entirety. Buyer Is Solely Responsible For Loading & Unloading, Bring Own Manpower, Equipment, Dollies Or Other Adequate Moving Devices or Equipment, Etc. To Remove Items. Buyer Must Have Adequate Transportation To Move Purchased Items.</i></p> <p>Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</p> <p>Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p>	



1	(1) 2002 B /B IH School Bus 3800 VIN #2319	<p>Will Need To Be Towed Unit #8 Conventional Style Passenger: 48 Engine Size & Type: IH T444E Engine Located In The Front Engine Problems: Yes (Unknown) Diesel Battery: Dead Runs: No Automatic Transmission Type: Allison Transmission Condition: Good Brakes: Air Inspection: 12/21 Mileage Reads: 18,644 Hub Reads: N/A Wheel Chair Lift: Yes Wheel Chair Lift Condition: Needs Work Interior Condition: Fair Interior Problems: In Line With Age Of Bus Exterior Condition: Fair Exterior Problems: In Line With Age Of Bus Tires Condition: Fair Tire Problems: None Additional Information: N/A Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed</p> <p>- Current Condition Unknown</p>	
2	(1) 2001 B /B IH School Bus 3800 VIN #1982	<p>Will Not Need To Be Towed Unit #9 Conventional Passenger: 16 Engine Size: IH T444E Engine Located In Front Engine Problems: No Diesel Battery: Dead Runs: Yes Automatic Transmission Type: Allison Transmission Condition: Good Brakes: Hydraulic Inspection: 09/21 Mileage Reads: 169,866 Hub Reads: N/A Wheel Chair Lift: Yes Wheel Chair Lift Condition: Good Interior Condition: Fair Interior Problems: In Line With Age Of Bus Exterior Condition: Fair Exterior Problems: In Line With Age Of Bus Tires Condition: Fair Tire Problems: None Additional Information: N/A Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed</p> <p>- Current Condition Unknown</p>	



3	<p>(1) 2007 Thomas FL School Bus TC2000 VIN #0811</p>	<p>Will Not Need To Be Towed Unit #23 Conventional Style Passenger: 32 Engine Size & Type: Cat C-7 Engine Located In Front Engine Problems: No Diesel Battery: Dead Runs: Yes Automatic Transmission Type: Allison Transmission Condition: Good Brakes: Air Inspection: 03/22 Mileage Reads: 159,209 Hub Reads: N/A Wheel Chair Lift: Yes Wheel Chair Lift Condition: Good Interior Condition: Fair Interior Problems: In Line With Age Of Bus Exterior Condition: Fair Exterior Problems: In Line With Age Of Bus Tires Condition: Fair Tire Problems: None Additional Information: N/A Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed</p> <p>- Current Condition Unknown</p>	
4	<p>(1) 2000 Blue Bird School Bus TC2000 VIN #4826</p>	<p>Will Need To Be Towed Unit #32 Transit Style Passenger: 32 Engine Size & Type: Cummins ISB 5.9 Engine Located In Front Engine Problems: Yes (Unknown) Diesel Battery: Dead Runs: No Automatic Transmission Type: Allison Transmission Condition: Good Brakes: Air Inspection: 02/20 Mileage Reads: 154,407 Hub Reads: N/A Wheel Chair Lift: Yes Wheel Chair Lift Condition: Good Interior Condition: Fair Interior Problems: In Line With Age Of Bus Exterior Condition: Fair Exterior Problems: In Line With Age Of Bus Tires Condition: Fair Tire Problems: None Additional Information: N/A Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed</p> <p>- Current Condition Unknown</p>	



5	<p>(1) 2000 Blue Bird School Bus TCFE2708 VIN #4827</p>	<p>Will Not Need To Be Towed Unit #33 Transit Style Passenger: 32 Engine Size & Type: Cummins ISB 5.9 Engine Located In Front Engine Problems: No Diesel Battery: Dead Runs: Yes Automatic Transmission Type: Allison Transmission Condition: Good Brakes: Air Inspection: 03/22 Mileage Reads: 182,705 Hub Reads: N/A Wheel Chair Lift: Yes Wheel Chair Lift Condition: Needs Work Interior Condition: Fair Interior Problems: In Line With Age Of Bus Exterior Condition: Fair Exterior Problems: In Line With Age Of Bus Tires Condition: Fair Tire Problems: None Additional Information: N/A Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed</p> <p>- Current Condition Unknown</p>	
6	<p>(1) 2001 Blue Bird School Bus TC2000 VIN #1221</p>	<p>Will Not Need To Be Towed Unit #34 Transit Style Passenger: 32 Engine Size & Type: Cummins ISB 5.9 Engine Located In Front Engine Problems: No Diesel Battery: Dead Runs: Yes Automatic Transmission Type: Allison Transmission Condition: Good Brakes: Air Inspection: 04/21 Mileage Reads: 221,522 Hub Reads: N/A Wheel Chair Lift: Yes Wheel Chair Lift Condition: Good Interior Condition: Fair Interior Problems: In Line With Age Of Bus Exterior Condition: Fair Exterior Problems: In Line With Age Of Bus Tires Condition: Fair Tire Problems: None Additional Information: N/A Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed</p> <p>- Current Condition Unknown</p>	



7	<p>(1) 2001 Blue Bird School Bus TC2000 VIN #1222</p>	<p>Will Not Need To Be Towed Unit #35 Transit Style Passenger: 32 Engine Size & Type: Cummins ISB 5.9 Engine Located In Front Engine Problems: No Diesel Battery: Dead Runs: Yes Automatic Transmission Type: Allison Transmission Condition: Good Brakes: Air Inspection: 09/21 Mileage Reads: 224,208 Hub Reads: N/A Wheel Chair Lift: Yes Wheel Chair Lift Condition: Needs Work Interior Condition: Fair Interior Problems: In Line With Age Of Bus Exterior Condition: Fair Exterior Problems: In Line With Age Of Bus Tires Condition: Fair Tire Problems: None Additional Information: N/A Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed</p> <p>- Current Condition Unknown</p>	
8	<p>(1) 2008 Blue Bird School Bus CV 2610S VIN #4468</p>	<p>Will Not Need To Be Towed Unit #44 Conventional Style Passenger: 53 Engine Size & Type: Cat C-7 Engine Located In Front Engine Problems: Yes (Unknown) Diesel Battery: Yes Runs: Yes Automatic Transmission Type: Allison Transmission Condition: Good Brakes: Air Inspection: 04/21 Mileage Reads: 141,501 Hub Reads: N/A Wheel Chair Lift: Yes Wheel Chair Lift Condition: Good Interior Condition: Fair Interior Problems: In Line With Age Of Bus Exterior Condition: Fair Exterior Problems: In Line With Age Of Bus Tires Condition: Fair Tire Problems: None Additional Information: N/A Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed</p> <p>- Current Condition Unknown</p>	


9	<p>(1) 2008 Blue Bird School Bus CV 2610S VIN #4469</p>	<p>Will Not Need To Be Towed Unit #45 Conventional Style Passenger: 53 Engine Size & Type: Cat C-7 Engine Located In Front Engine Problems: Yes (Unknown) Diesel Battery: Dead Runs: Yes Automatic Transmission Type: Allison Transmission Condition: Good Brakes: Air Inspection: 07/21 Mileage Reads: 140,589 Hub Reads: N/A Wheel Chair Lift: Yes Wheel Chair Lift Condition: Good Interior Condition: Fair Interior Problems: In Line With Age Of Bus Exterior Condition: Fair Exterior Problems: In Line With Age Of Bus Tires Condition: Fair Tire Problems: None Additional Information: N/A Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed</p> <p>- Current Condition Unknown</p>	
10	<p>(1) 2009 Blue Bird School Bus CV 2311S VIN #5315</p>	<p>Will Need To Be Towed Unit #50 Conventional Style Passenger: 47 Engine Size & Type: Cummins ISB 5.9 Engine Located In Front Engine Problems: Yes (Unknown) Diesel Battery: Yes Runs: No Automatic Transmission Type: Allison Transmission Condition: Good Brakes: Air Inspection: 10/21 Mileage Reads: 198,087 Hub Reads: N/A Wheel Chair Lift: Yes Wheel Chair Lift Condition: Needs Work Interior Condition: Fair Interior Problems: In Line With Age Of Bus Exterior Condition: Fair Exterior Problems: In Line With Age Of Bus Tires Condition: Fair Tire Problems: None Additional Information: N/A Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed</p> <p>- Current Condition Unknown</p>	

11	(1) 1999 Blue Bird School Bus TC2000 VIN #4828	<p>Will Not Need To Be Towed Unit #239 Transit Style Passenger: 72 Engine Size & Type: Cummins ISB 5.9 Engine Located In Front Engine Problems: No Diesel Battery: Dead Runs: Yes Automatic Transmission Type: Allison Transmission Condition: Good Brakes: Air Inspection: 03/21 Mileage Reads: 143,163 Hub Reads: N/A Wheel Chair Lift: No Wheel Chair Lift Condition: N/A Interior Condition: Fair Interior Problems: In Line With Age Of Bus Exterior Condition: Fair Exterior Problems: In Line With Age Of Bus Tires Condition: Fair Tire Problems: None Additional Information: N/A Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed</p> <p>- Current Condition Unknown</p>	
12	(1) 2001 Blue Bird School Bus TC2000 VIN 1224	<p>Will Not Need To Be Towed Unit #240 Transit Style Passenger: 72 Engine Size & Style: Cummins ISB 5.9 Engine Located In Front Engine Problems: No Diesel Battery: Dead Runs: Yes Automatic Transmission Type: Allison Transmission Condition: Good Brakes: Air Inspection: 10/19 Mileage Reads: 16,256 Hub Reads: N/A Wheel Chair Lift: No Wheel Chair Lift Condition: N/A Interior Condition: Fair Interior Problems: In Line With Age Of Bus Exterior Condition: Fair Exterior Problems: In Line With Age Of Bus Tires Condition: Fair Tire Problems: None Additional Information: N/A Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed</p> <p>- Current Condition Unknown</p>	

13	(1) 2002 B /B IH School Bus CV 7800 VIN #6269	<p>Will Not Need To Be Towed Unit #242 Conventional Style Passenger: 77 Engine Size & Type: IH T444E Engine Located In Front Engine Problems: No Diesel Battery: Dead Runs: Yes Automatic Transmission Type: Allison Transmission Condition: Good Breaks: Air Inspection: 02/21 Mileage Reads: 22,888 Hub Reads: N/A Wheel Chair Lift: No Wheel Chair Lift Condition: N/A Interior Condition: Fair Interior Problems: In Line With Age Of Bus Exterior Condition: Fair Exterior Problems: In Line With Age Of Bus Tires Condition: Fair Tire Problems: None Additional Information: N/A Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed</p> <p>- Current Condition Unknown</p>	
14	(1) 2003 B /B IH School Bus CV 7800 VIN #6270	<p>Will Not Need To Be Towed Unit #243 Conventional Style Passenger: 77 Engine Size & Type: IH T444E Engine Located In Front Engine Problems: No Diesel Battery: Dead Runs: Yes Automatic Transmission Type: Allison Transmission Condition: Good Brakes: Air Inspection: 03/21 Mileage Reads: 40,695 Hub Reads: N/A Wheel Chair Lift: No Wheel Chair Lift Condition: N/A Interior Condition: Fair Interior Problems: In Line With Age Of Bus Exterior Condition: Fair Exterior Problems: In Line With Age Of Bus Tires Condition: Fair Tire Problems: None Additional Information: N/A Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed</p> <p>- Current Condition Unknown</p>	

15	(1) 2003 B /B IH School Bus CV 7800 VIN #6271	<p>Will Not Need To Be Towed Unit #244 Conventional Style Passenger: 77 Engine Size & Type: IH T444E Engine Located In Front Engine Problems: No Diesel Battery: Dead Runs: Yes Automatic Transmission Type: Allison Transmission Condition: Good Brakes: Air Inspection: 04/20 Mileage Reads: 83,570 Hub Reads: N/A Wheel Chair Lift: No Wheel Chair Lift Condition: N/A Interior Condition: Fair Interior Problems: In Line With Age Of Bus Exterior Condition: Fair Exterior Problems: In Line With Age Of Bus Tires Condition: Fair Tire Problems: None Additional Information: N/A Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed</p> <p>- Current Condition Unknown</p>	
16	(1) 2003 B /B IH School Bus CV 7800 VIN #6272	<p>Will Not Need To Be Towed Unit #245 Conventional Style Passenger: 77 Engine Size & Type: IH T444E Engine Located In Front Engine Problems: No Diesel Battery: Yes Runs: Yes Automatic Transmission Type: Allison Transmission Condition: Good Brakes: Air Inspection: 05/21 Mileage Reads: 15,771 Hub Reads: N/A Wheel Chair Lift: No Wheel Chair Lift Condition: N/A Interior Condition: Fair Interior Problems: In Line With Age Of Bus Exterior Condition: Fair Exterior Problems: In Line With Age Of Bus Tires Condition: Fair Tires Problems: None Additional Information: N/A Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed</p> <p>- Current Condition Unknown</p>	

17	(1) 2004 IH School Bus CE- SB VIN #7937	<p>Will Not Need To Be Towed Unit #246 Conventional Style Passenger: 77 Engine Size & Type: IH DT-466 Engine Located In Front Engine Problems: No Diesel Battery: Yes Runs: Yes Automatic Transmission Type: Allison Transmission Condition: Good Brakes: Air Inspection: 06/21 Mileage Reads: 12,652 Hub Reads: N/A Wheel Chair Lift: No Wheel Chair Lift Condition: N/A Interior Condition: Fair Interior Problems: In Line With Age Of Bus Exterior Condition: Fair Exterior Problems: In Line With Age Of Bus Tires Condition: Fair Tire Problems: None Additional Information: N/A Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed</p> <p>- Current Condition Unknown</p>	
18	(1) 2004 IH School Bus CE- SB VIN #7938	<p>Will Not Need To Be Towed Unit #247 Conventional Style Passenger: 77 Engine Size & Type: IH DT-466 Engine Located In Front Engine Problems: No Diesel Battery: Yes Runs: Yes Automatic Transmission Type: Allison Transmission Condition: Good Brakes: Air Inspection: 07/21 Mileage Reads: 201,164 Hub Reads: N/A Wheel Chair Lift: No Wheel Chair Lift Condition: N/A Interior Condition: Fair Interior Problems: In Line With Age Of Bus Exterior Condition: Fair Exterior Problems: In Line With Age Of Bus Tires Condition: Fair Tire Problems: None Additional Information: N/A Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed</p> <p>- Current Condition Unknown</p>	

19	(1) 2004 IH School Bus CE- SB VIN #7939	<p>Will Not Need To Be Towed Unit #248 Conventional Style Passenger: 77 Engine Size & Type: IH DT-466 Engine Located In Front Engine Problems: No Diesel Battery: Yes Runs: Yes Automatic Transmission Type: Allison Transmission Condition: Good Brakes: Air Inspection: 08/21 Mileage Reads: 22,968 Hub Reads: N/A Wheel Chair Lift: No Wheel Chair Lift Condition: N/A Interior Condition: Fair Interior Problems: In Line With Age Of Bus Exterior Condition: Fair Exterior Problems: In Line With Age Of Bus Tires Condition: Fair Tire Problems: None Additional Information: N/A Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed</p> <p>- Current Condition Unknown</p>	
20	(1) 2004 IH School Bus CE- SB VIN #7940	<p>Will Not Need To Be Towed Unit #249 Conventional Style Passenger: 77 Engine Size & Type: IH DT-466 Engine Located In Front Engine Problems: No Diesel Battery: Yes Runs: Yes Automatic Transmission Type: Allison Transmission Condition: Good Brakes: Air Inspection: 09/21 Mileage Reads: 67,112 Hub Reads: N/A Wheel Chair Lift: No Wheel Chair Lift Condition: N/A Interior Condition: Fair Interior Problems: In Line With Age Of Bus Exterior Condition: Fair Exterior Problems: In Line With Age Of Bus Tires Condition: Fair Tire Problems: None Additional Information: N/A Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed</p> <p>- Current Condition Unknown</p>	