.ot Number	Title	Description	Thumbnail
		All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes IMPORTANT NOTICE FOR CITY OF MISSOURI CITY TX (FLEET SERVICES) AUCTION: **All purchases will be subject to a (14%) buver's premium. There Will Be A 3% Fee For All Purchases Not Made By Cash, Cashier's Check, Direct Deposit, Money Order & Wire Transfer*	
		CDC COVID-19 GUIDELINES WILL BE OBSERVED – WEAR A MASK AND STAY AT LEAST 6 FT. APART. Preview: (By Appointment Only-Mandatory-No Exceptions) Thursday, August 5, 2021 (Hours Of Operation: 8:00 A.M. – 11:00 A.M. / 1:00 P.M. – 3:00 P.M.) Location: Fleet Services – 1919 Scanlin Rd., Missouri City, TX 77489 Driving Directions Removal Dates & Times: (By Appointment Only-Mandatory-No Exceptions) Wednesday, August 11, 2021/Thursday, August 12, 2021/Friday, August 13, 2021 (Hours Of Operation: 8: 00 A.M. – 11:00 A.M. / 1:00 P.M. – 3:00 P.M.)	
0	Preview & Removal Information	Preview & Removal Contact: 281-403-8583 Mike Tubbs, Fleet Superintendent Or Hung Hoang, Shop Foreman Removal Note: There Will Be A Forklift Available For Removal. There Will Be No Manpower, No Employee Assistance Or Equipment Available For Removal of Any Lots. Buyer Must Remove All Lots In Their Entirety. Buyer Is Solely Responsible For Loading & Unloading, Bring Own Manpower, Equipment, Dollies Or Other Adequate Moving Devices or Equipment, Etc. To Remove Items. Buyer Must Have Adequate Transportation To Move Purchased Items.	'ATTENTION' Read Me
		Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All Defects And Flaws With A Vehicle Will Be The Buver's Responsibility Once Purchased By Buver. Buver Should Be Aware That They Are Purchasing A Used Vehicle As It Sits On The Auction Location With No Warranty Or Guarantee Whatsoever. Seller And Auctioneer Have Made A Diligent Attempt To Supply The Buver With A General Description Of Each Unit And Do Not Guarantee The Accuracy Of The Information Supplied. Seller And Auctioneer Recommend Buyers To Thoroughly Inspect Each Vehicle Prior To Bidding. **	
		Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And /or Removed.	

Type/Model: Business Class M2

Unit #: 4203 Passengers: 2

Engine Size/Type: Mercedes Benz

Engine Problems: ABS Light Is On In The Dashboard, Could Possibly Need New Brakes

Gas

Battery: Yes Runs: Yes Automatic Brakes: Hydraulic Inspection Sticker: 07/21 Mileage: 202,258 Interior Condition: Fair

Interior Problems: Headliner Is Loose - Needs Cleaning

Body Condition: Fair

Body Problems: Oxidized Paint - Surface Scratches, Dents & Rust - Minor Crack & Peeling Paint On

Front Bumper Tire Condition: Fair Tire Problems: Unknown

Additional Information: GVWR = 25,500 Lbs. - Has Outriggers In Front Of Service Bed - Has Storage

Tool Boxes - (1) Fuel Tank

Lift Info: Versalift, Model: VST-471 - Mfg. Date: May 2008 - 400 Lb. Capacity - Platform Height: 47

Ft. - Insulated: Boom - 46 KV Voltage - Current Inspection: Unknown

Bed Info: Dakota Bodies Inc. - Model: 132-LB

- Current Condition Unknown

Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.

**All Defects And Flaws With A Vehicle Will Be The Buver's Responsibility Once Purchased By Buver. Buver Should Be Aware That They Are Purchasing A Used Vehicle As It Sits On The Auction Location With No Warranty Or Guarantee Whatsoever. Seller And Auctioneer Have Made A Diligent Attempt To Supply The Buver With A General Description Of Each Unit And Do Not Guarantee The Accuracy Of The Information Supplied. Seller And Auctioneer Recommend Buyers To Thoroughly Inspect Each Vehicle Prior To Bidding. **

Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And /or Removed.



1

(1) 2009

Bucket

#1238

Truck, Vin

Freight Liner

Type/Model: FL80 Unit #3142 Passengers: 5 Engine Size/Type: Unknown Engine Problems: Unknown Diesel Battery: Yes Runs: Yes Automatic Brakes: Air Inspection Sticker: 09/20 Mileage: 13,679 - Hours: 1,320 Interior Problems: Normal Wear On Seats - Needs Cleaning - Dashboard Is Worn Body Problems: Surface Scratches, Dents & Rust Tire Problems: Unknown (1) 1999 E-Additional Information: GVWR = 37,000 - Foam Pro Foam Systems Fire Equipment - Hale Master One Intake Valve - 1250 Capacity - Type: QSG125-23 Performance 2 Freightliner - Current Condition Unknown Fire Truck, Vin #9615 Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All Defects And Flaws With A Vehicle Will Be The Buyer's Responsibility Once Purchased By Buyer, Buyer Should Be Aware That They Are Purchasing A Used Vehicle As It Sits On The Auction Location With No Warranty Or Guarantee Whatsoever. Seller And Auctioneer Have Made A Diligent Attempt To Supply The Buver With A General Description Of Each Unit And Do Not Guarantee The Accuracy Of The Information Supplied. Seller And Auctioneer Recommend Buyers To Thoroughly Inspect Each Vehicle Prior To Bidding. * Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And /or Removed. Unit #6101 Passengers: 5 Engine Size: 2.5L Engine Problems: Unknown Gas Battery: Yes Runs: Yes Automatic Brakes: Hydraulic Inspection Sticker 07/21 Mileage: 60,569 Interior Condition: Fair Interior Problems: Needs Cleaning Body Condition: Fair Body Problems: Surface Scratches, Dents & Rust Tire Condition: Good Tire Condition: Unknown (1) 2010 Additional Information: See Video, A/C Worked At Time Of Demo Ford Escape. 3 Vin #1199 - Current Condition Unknown Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All Defects And Flaws With A Vehicle Will Be The Buyer's Responsibility Once Purchased By Buyer, Buyer Should Be Aware That They Are Purchasing A Used Vehicle As It Sits On The Auction Location With No Warranty Or Guarantee Whatsoever. Seller And Auctioneer Have Made A Diligent Attempt To Supply The Buyer With A General Description Of Each Unit And Do Not Guarantee The Accuracy Of The Information Supplied. Seller And Auctioneer Recommend Buyers To Thoroughly Inspect Each Vehicle Prior To Bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And /or Removed.

4	(1) Ferris Zero Turn Riding Lawn Mower	Model: IS-32007, Gas Has Key, Has Battery Hours: 584 Unit #: 5152 Blade Protection Guard Is Missing - Current Condition Unknown	
5	(Lot) Electric Hammer Drill & Air Wrench	(1) Bosch Bulldog Extreme Max Hammer Drill - Worn (1) Chicago Air Wrench, Model: BP776-6 - Worn - Current Condition Unknown	AP
6	(1) Truck Toolbox With 60 Gallon Gas Tank	Mfg: RDS Manufacturing - NO KEY - Current Condition Unknown	0
7	(1) Stihl Tree Trimmer	Model: HT131 - Gas - Unit Does Pull - Current Condition Unknown	
8	(1) Briggs & Stratton Elite Series Portable Generator	5500 Watts - Gas - Unit #: 42216 - Current Condition Unknown	
9	(1) Briggs & Stratton Elite Series Portable Generator	5500 Watts - Gas - Unit #: 42215 - Current Condition Unknown	
10	(Lot) Office Chairs	(Approx. 17) - Various Styles, Colors & Sizes - Current Condition Unknown	
11	(Lot) Matching Stackable Chairs	(Approx. 83) - Current Condition Unknown	
12	(Lot) Round Plastic Folding Tables	(Approx. 3) - (Approx. Size 60") - Current Condition Unknown	
13	(Lot) Plastic Aerobic Steps & Misc.	(Approx. 27) Steps - Complete Unknown - Current Condition Unknown	