












Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	<p><b>**All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes**</b></p> <p><b>IMPORTANT NOTICE FOR JUDSON ISD (Buses) ONLINE AUCTION: **All purchases will be subject to a (14%) Buyer's Premium. There Will Be A 3% Fee For All Purchases Not Made By Cash, Cashier's Check, Direct Deposit, Money Order &amp; Wire Transfer**</b></p> <p>Preview: (By Appointment Only-Mandatory-No Exceptions) <b>Thursday, July 29, 2021</b> (Hours Of Operation: 8:00 A.M. - 2:00 P.M.)  Location:, Converse, TX 78109  Removal Dates &amp; Times: (By Appointment Only-Mandatory-No Exceptions) <b>Monday, August 9, 2021/Tuesday, August 10, 2021/Wednesday, Wednesday, August 11, 2021</b> (Hours Of Operation: 8:00 A.M. - 2:00 P.M.)  Preview &amp; Removal Contact:</p> <p><b>Removal Note:</b> <i>There Will Be No Manpower, No Employee Assistance Or Equipment Available For Removal. Buyer Must Remove All Lots In Their Entirety. Buyer Is Solely Responsible For Loading &amp; Unloading, Bring Own Manpower, Equipment, Dollies Or Other Adequate Moving Devices or Equipment, Etc. To Remove Items. Buyer Must Have Adequate Transportation To Move Purchased Items.</i></p> <p><b>Note For Vehicles:</b> There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>VEHICLE TITLE INFORMATION :</b> Lemons Auctioneers &amp; Online Pros will contact you concerning the title preparation information for the Title(s) of your Vehicle(s). Buvor must remove their Vehicle(s) from Seller's auction location before the Title Preparation will be processed. Titles can take up to thirty (30) days to be received by Buvor due to processing and delivery. Buvors may pick up their processed titles in person at Lemons Auctioneers &amp; Online Pros office location by appointment only at 18810 Juergen Road. Tomball, Texas 77377 between the hours of 9 a.m. – 3 p.m., Monday thru Friday. You may call 281-357-4977 or email lemons@onlinepros.com .</p> <p><b>**All Defects And Flaws With A Vehicle Will Be The Buvor's Responsibility Once Purchased By Buvor. Buvor Should Be Aware That They Are Purchasing A Used Vehicle As It Sits On The Auction Location With No Warranty Or Guarantee Whatsoever. Seller And Auctioneer Have Made A Diligent Attempt To Supply The Buvor With A General Description Of Each Unit And Do Not Guarantee The Accuracy Of The Information Supplied. Seller And Auctioneer Recommend Buyers To Thoroughly Inspect Each Vehicle Prior To Bidding. **</b></p> <p><b>Removal Note For Vehicles:</b> Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/Or Removed.</p>	



68	(1) 2010 IC School Bus, Vin #3802	<p>Will Need To Be Towed - Does Not Run - See Additional Information Below  Unit #68  Conventional Style  Passenger: 71  Engine Size/Type: 6.5L MAXX-7  Front Engine - Engine Problems: Blow By  Diesel  Battery: Yes/Dead  Runs: No  Automatic Transmission - Type: Allison - Condition: Good  Air Brakes  Inspection Sticker Date: 02/19  Mileage: Unknown  Wheel Chair Lift: No  Interior Condition: Fair  Interior Problems: Needs Cleaning  Body Condition: Good  Body Problems: Missing Lights  Tires Condition: Good  Tire Problems: Unknown  **Additional Information: Was Regular Bus Route Before Engine Failure - SOLD AS IS**  Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All Defects And Flaws With A Vehicle Will Be The Buyers Responsibility Once Purchased By Buyer. Buyer Should Be Aware That They Are Purchasing A Used Vehicle As It Sits On The Auction Location With No Warranty Or Guarantee Whatsoever. Seller And Auctioneer Have Made A Diligent Attempt To Supply The Buyer With A General Description Of Each Unit And Do Not Guarantee The Accuracy Of The Information Supplied. Seller And Auctioneer Recommend Buyers To Thoroughly Inspect Each Vehicle Prior To Bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
79	(1) 2010 IC School Bus, Vin #3805	<p>Will Need To Be Towed - Does Not Run - See Additional Information Below  Unit #79  Conventional Style  Passenger: 71  Engine Size/Type: Unknown  Front Engine - Engine Problems: Engine Knock, Blow By, Missing Engine Parts  Diesel  Battery: Yes/Dead  Runs: No  Automatic Transmission - Type: Allison - Condition: Good  Air Brakes  Inspection Sticker Date: 02/18  Mileage: Unknown  Wheel Chair Lift: No  Interior Condition: Good  Interior Problems: Needs Cleaning  Body Condition: Fair  Body Problems: Missing Lights Front &amp; Rear, Upper Windows Broken At Rear, Right Side Missing Panel At Bumper  Tires Condition: Good  Tire Problems: Unknown  **Additional Information: Was Regular Bus Route Before Engine Failure - SOLD AS IS**  Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All Defects And Flaws With A Vehicle Will Be The Buyers Responsibility Once Purchased By Buyer. Buyer Should Be Aware That They Are Purchasing A Used Vehicle As It Sits On The Auction Location With No Warranty Or Guarantee Whatsoever. Seller And Auctioneer Have Made A Diligent Attempt To Supply The Buyer With A General Description Of Each Unit And Do Not Guarantee The Accuracy Of The Information Supplied. Seller And Auctioneer Recommend Buyers To Thoroughly Inspect Each Vehicle Prior To Bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	


81	(1) 2008 IC School Bus, Vin #9869	<p>Will Need To Be Towed - Does Not Run - See Additional Information Below  Unit #81  Conventional Style  Passenger: 71  Engine Size/Type: VT-365  Front Engine - Engine Problems: No Compression, Missing Engine Parts, CPU, Etc.  Diesel  Battery: No  Runs: No  Automatic Transmission - Type: Allison - Condition: Unknown  Air Brakes  Inspection Sticker Date: Unknown  Mileage: Unknown  Wheel Chair Lift: No  Interior Condition: Fair  Interior Problems: Needs Cleaning, Missing Panels, Dash Panels &amp; Etc.  Body Condition: Poor  Body Problems: Needs Cleaning, Missing Parts, Fenders, Front Windshield &amp; Windows  Tires Condition: Fair  Tire Problems: Some Are Flat  **Additional Information: Parts Bus Missing Parts, Some Additional Parts Inside Bus - SOLD AS IS**  Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All Defects And Flaws With A Vehicle Will Be The Buyers Responsibility Once Purchased By Buyer. Buyer Should Be Aware That They Are Purchasing A Used Vehicle As It Sits On The Auction Location With No Warranty Or Guarantee Whatsoever. Seller And Auctioneer Have Made A Diligent Attempt To Supply The Buyer With A General Description Of Each Unit And Do Not Guarantee The Accuracy Of The Information Supplied. Seller And Auctioneer Recommend Buyers To Thoroughly Inspect Each Vehicle Prior To Bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
97	(1) 2000 IC School Bus, Vin #4324	<p>Will Need To Be Towed - Does Not Run - See Additional Information Below  Unit #97  Conventional Style  Passenger: 71  Engine Size/Type: 7.3L 444e  Front Engine - Engine Problems: Damaged Engine Head Right Side  Diesel  Battery: No  Runs: No  Automatic Transmission - Type: Unknown - Condition: Missing  Air Brakes  Inspection Sticker Date: Unknown  Mileage: Unknown  Wheel Chair Lift: No  Interior Condition: Fair  Interior Problems: Needs Cleaning, Torn Seats  Body Condition: Fair  Body Problems: Missing Front Bumper, Right Side Windows &amp; Front Windshield Missing  Tires Condition: Fair  Tire Problems: Some Are Flat  **Additional Information: Parts Bus Missing Parts, Some Additional Parts Inside Bus - SOLD AS IS**  Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All Defects And Flaws With A Vehicle Will Be The Buyers Responsibility Once Purchased By Buyer. Buyer Should Be Aware That They Are Purchasing A Used Vehicle As It Sits On The Auction Location With No Warranty Or Guarantee Whatsoever. Seller And Auctioneer Have Made A Diligent Attempt To Supply The Buyer With A General Description Of Each Unit And Do Not Guarantee The Accuracy Of The Information Supplied. Seller And Auctioneer Recommend Buyers To Thoroughly Inspect Each Vehicle Prior To Bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	

99	(1) 2000 IC School Bus, Vin #4344	<p>Will Need To Be Towed - Does Not Run - See Additional Information Below  Unit #99  Conventional Style  Passenger: 71  Engine Size/Type: 7.3L 444e  Front Engine - Engine Problems: None, Does Have Oil Leaks  Diesel  Battery: Yes/Dead  Runs: No  Automatic Transmission - Type: Allison - Condition: Poor  Air Brakes  Inspection Sticker Date: Unknown  Mileage: Unknown  Wheel Chair Lift: No  Interior Condition: Fair  Interior Problems: Needs Cleaning  Body Condition: Good  Body Problems: Dents &amp; Scratches, Missing Lights, Front Headlights Missing, Hood Is Not Attached  Tires Condition: Good  Tire Problems: Some Tires Have Low Air  **Additional Information: Was Regular Bus Route Before Transmission Failure - SOLD AS IS**  Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All Defects And Flaws With A Vehicle Will Be The Buyers Responsibility Once Purchased By Buyer. Buyer Should Be Aware That They Are Purchasing A Used Vehicle As It Sits On The Auction Location With No Warranty Or Guarantee Whatsoever. Seller And Auctioneer Have Made A Diligent Attempt To Supply The Buyer With A General Description Of Each Unit And Do Not Guarantee The Accuracy Of The Information Supplied. Seller And Auctioneer Recommend Buyers To Thoroughly Inspect Each Vehicle Prior To Bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
107	(1) 2005 IC School Bus, Vin #5073	<p>Will Need To Be Towed - Does Not Run - See Additional Information Below  Unit #107  Conventional Style  Passenger: 71  Engine Size/Type: VT-365  Engine Problems: Unknown  Diesel  Battery: Yes/Dead  Runs: No  Automatic Transmission - Type: Allison - Condition: Good  Air Brakes  Inspection Sticker Date: Unknown  Mileage: Unknown  Wheel Chair Lift: No  Interior Condition: Fair  Interior Problems: Needs Cleaning, No Driver Seat Bottom, Missing Dash Panels  Body Condition: Good  Body Problems: Missing Lights And Windows  Tires Condition: Good  Tire Problems: Unknown  **Additional Information: SOLD AS IS  Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All Defects And Flaws With A Vehicle Will Be The Buyers Responsibility Once Purchased By Buyer. Buyer Should Be Aware That They Are Purchasing A Used Vehicle As It Sits On The Auction Location With No Warranty Or Guarantee Whatsoever. Seller And Auctioneer Have Made A Diligent Attempt To Supply The Buyer With A General Description Of Each Unit And Do Not Guarantee The Accuracy Of The Information Supplied. Seller And Auctioneer Recommend Buyers To Thoroughly Inspect Each Vehicle Prior To Bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	

121	(1) 2005 IC School Bus, Vin #4555	<p>Will Need To Be Towed - Does Not Run - See Additional Information Below  Unit #121  Conventional Style  Passenger: 71  Engine Size/Type: VT-365  Engine In Front  Engine Problems: Blow By, Is Missing Some Engine Parts  Diesel  Battery: Yes  Runs: No  Automatic Transmission - Type: Allison - Condition: Good  Air Brakes  Inspection Sticker Date: 12/18  Mileage: Unknown  Wheel Chair Lift: No  Interior Condition: Poor  Interior Problems: Missing Seats  Body Condition: Fair  Body Problems: Missing Lights And Entry Door  Tires Condition: Fair  Tire Problems: Front Left Tire Is Flat  **Additional Information: Was Regular Route Bus Before Engine Failure - SOLD AS IS **  Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All Defects And Flaws With A Vehicle Will Be The Buyers Responsibility Once Purchased By Buyer. Buyer Should Be Aware That They Are Purchasing A Used Vehicle As It Sits On The Auction Location With No Warranty Or Guarantee Whatsoever. Seller And Auctioneer Have Made A Diligent Attempt To Supply The Buyer With A General Description Of Each Unit And Do Not Guarantee The Accuracy Of The Information Supplied. Seller And Auctioneer Recommend Buyers To Thoroughly Inspect Each Vehicle Prior To Bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
126	(1) 2006 IC School Bus, Vin #8708	<p>Will Need To Be Towed - Does Not Run - See Additional Information Below  Unit #126  Conventional Style  Passenger: 71  Engine Size/Type: VT-365  Engine In Front  Engine Problems: No Compression  Diesel  Battery: Yes/Dead  Runs: No  Automatic Transmission - Type: Allison - Condition: Unknown  Air Brakes  Inspection Sticker Date: Unknown  Mileage: Unknown  Wheel Chair Lift: No  Interior Condition: Poor  Interior Problems: Needs Cleaning, Some Seat Bottoms Missing  Body Condition: Fair  Body Problems: Missing Front Bumper, Front Grill, Lights, Windshield &amp; Missing Windows  Tires Condition: Fair  **Additional Information: Was A Parts Bus And May Have Additional Parts Inside Bus - SOLD AS IS**  Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All Defects And Flaws With A Vehicle Will Be The Buyers Responsibility Once Purchased By Buyer. Buyer Should Be Aware That They Are Purchasing A Used Vehicle As It Sits On The Auction Location With No Warranty Or Guarantee Whatsoever. Seller And Auctioneer Have Made A Diligent Attempt To Supply The Buyer With A General Description Of Each Unit And Do Not Guarantee The Accuracy Of The Information Supplied. Seller And Auctioneer Recommend Buyers To Thoroughly Inspect Each Vehicle Prior To Bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	

130	(1) 2006 IC School Bus, Vin #8705	<p>Will Need To Be Towed - Does Not Run - See Additional Information Below  Unit #130  Conventional Style  Passenger: 71  Engine Size/Type: VT-365  Engine In Front  Engine Problems: No Compression  Diesel  Battery: Yes/Dead  Runs: No  Automatic Transmission - Type: Allison - Condition: Good  Air Brakes  Inspection Sticker Date: 08/18  Mileage: Unknown  Wheel Chair Lift: No  Interior Condition: Good  Interior Problems: Needs Cleaning  Body Condition: Good  Body Problems: Missing Lights  Tires Condition: Good  Tire Problems: Some Tires Low Air  **Additional Information: Was A Regular Route Bus Before Engine Failure - SOLD AS IS**  Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All Defects And Flaws With A Vehicle Will Be The Buyers Responsibility Once Purchased By Buyer. Buyer Should Be Aware That They Are Purchasing A Used Vehicle As It Sits On The Auction Location With No Warranty Or Guarantee Whatsoever. Seller And Auctioneer Have Made A Diligent Attempt To Supply The Buyer With A General Description Of Each Unit And Do Not Guarantee The Accuracy Of The Information Supplied. Seller And Auctioneer Recommend Buyers To Thoroughly Inspect Each Vehicle Prior To Bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
134	(1) 2006 IC School Bus, Vin #8704	<p>Will Need To Be Towed - Does Not Run/No Engine/No Transmission - See Additional Information Below - Unit #134  Conventional Style  Passenger: 71  Engine Size/Type: VT-365  Engine Problems: No Engine  Diesel  Battery: Yes  Runs: No  Automatic Transmission - Type: Allison - Transmission Missing  Air Brakes  Inspection Sticker Date: 08/17  Mileage: Unknown  Wheel Chair Lift: No  Interior Condition: Fair  Interior Problems: Needs Cleaning, Missing Dash Panels, Steering Wheel &amp; Interior Parts, Etc.  Body Condition: Good  Body Problems: Missing Lights, Rear Bumper Damage  Tires Condition: Fair  Tire Problems: No Left Side Outer Tire  **Additional Information: Rear Left Side X Missing - Was Used For Parts Bus - SOLD AS IS**  Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All Defects And Flaws With A Vehicle Will Be The Buyers Responsibility Once Purchased By Buyer. Buyer Should Be Aware That They Are Purchasing A Used Vehicle As It Sits On The Auction Location With No Warranty Or Guarantee Whatsoever. Seller And Auctioneer Have Made A Diligent Attempt To Supply The Buyer With A General Description Of Each Unit And Do Not Guarantee The Accuracy Of The Information Supplied. Seller And Auctioneer Recommend Buyers To Thoroughly Inspect Each Vehicle Prior To Bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	

141	(1) 2008 IC School Bus, Vin #9907	<p>Will Need To Be Towed - Does Not Run - See Additional Information Below  Unit #141  Conventional Style  Passenger: 71  Engine Size/Type: VT-365  Engine In Front  Engine Problems: No Compression  Diesel  Battery: No  Runs: No  Automatic Transmission - Type: Allison - Condition: Good  Air Brakes  Inspection Sticker Date: 07/18  Mileage: Unknown  Wheel Chair Lift: No  Interior Condition: Good  Interior Problems: Needs Cleaning, Is Missing Driver Seat  Body Condition: Good  Body Problems: Missing Lights  Tires Condition: Good  Tire Problems: Unknown  **Additional Information: This Was A Regular Route - SOLD AS IS**  Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All Defects And Flaws With A Vehicle Will Be The Buyers Responsibility Once Purchased By Buyer. Buyer Should Be Aware That They Are Purchasing A Used Vehicle As It Sits On The Auction Location With No Warranty Or Guarantee Whatsoever. Seller And Auctioneer Have Made A Diligent Attempt To Supply The Buyer With A General Description Of Each Unit And Do Not Guarantee The Accuracy Of The Information Supplied. Seller And Auctioneer Recommend Buyers To Thoroughly Inspect Each Vehicle Prior To Bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
146	(1) 2009 IC School Bus, Vin #9708	<p>Will Need To Be Towed - Does Not Run - See Additional Information Below  Unit #146  Conventional Style  Passenger: 71  Engine Size/Type: MAXX-7 V8  Engine In Front  Engine Problems: No Compression, Blow By  Diesel  Battery: Yes/Dead  Runs: No  Automatic Transmission - Type: Allison - Condition: Good  Air Brakes  Inspection Sticker Date: 07/18  Mileage: Unknown  Wheel Chair Lift: No  Interior Condition: Fair  Interior Problems: Needs Cleaning  Body Condition: Good  Body Problems: No Rear Bumper, Missing Lights, Windows, Entry Door Panel &amp; Dash Panel, Needs Cleaning  Tires Condition: Good  Tire Problems: Unknown  **Additional Information: Was A Regular Route Bus Until Engine Lost Compression - SOLD AS IS**  Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All Defects And Flaws With A Vehicle Will Be The Buyers Responsibility Once Purchased By Buyer. Buyer Should Be Aware That They Are Purchasing A Used Vehicle As It Sits On The Auction Location With No Warranty Or Guarantee Whatsoever. Seller And Auctioneer Have Made A Diligent Attempt To Supply The Buyer With A General Description Of Each Unit And Do Not Guarantee The Accuracy Of The Information Supplied. Seller And Auctioneer Recommend Buyers To Thoroughly Inspect Each Vehicle Prior To Bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	

171	(1) 2009 IC School Bus, Vin #9721	<p>Will Need To Be Towed - Does Not Run - See Additional Information Below  Unit #171  Conventional Style  Passenger: 71  Engine Size/Type: MAXX-7 V8  Engine In Front  Engine Problems: Missing Engine Parts, Blow By Diesel  Battery: Yes/Dead  Runs: No  Automatic Transmission - Type: Allison - Condition: Unknown  Air Brakes  Inspection Sticker Date: Unknown  Mileage: Unknown  Wheel Chair Lift: Yes  Interior Condition: Poor  Interior Problems: Needs Cleaning Missing Seats, Foams, Dash Panels, Driver Seat, No Steering Wheel, Side Panels Missing, Etc.  Body Condition: Good  Body Problems: Missing Windows, Light Various Parts  Tires Condition: Good  Tire Problems: No Front Tires, Rear Tires Low On Air, But Good  **Additional Information: Was Used As A Parts Bus - Missing Parts - SOLD AS IS**  Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All Defects And Flaws With A Vehicle Will Be The Buyers Responsibility Once Purchased By Buyer. Buyer Should Be Aware That They Are Purchasing A Used Vehicle As It Sits On The Auction Location With No Warranty Or Guarantee Whatsoever. Seller And Auctioneer Have Made A Diligent Attempt To Supply The Buyer With A General Description Of Each Unit And Do Not Guarantee The Accuracy Of The Information Supplied. Seller And Auctioneer Recommend Buyers To Thoroughly Inspect Each Vehicle Prior To Bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	
259	(1) 2005 IC School Bus, Vin #4564	<p>Will Need To Be Towed - Does Not Run - See Additional Information Below  Unit #259  Conventional Style  Passenger: 25  Engine Size/Type: VT-365  Engine In Front  Engine Problems: Hole In Block, Missing Engine Parts, Used As Parts Bus  Diesel  Battery: No  Runs: No  Automatic Transmission - Type: Allison - Condition: Unknown  Air Brakes  Inspection Sticker Date: 07/17  Mileage: Unknown  Wheel Chair Lift: No  Interior Condition: Poor  Interior Problem: Needs Cleaning - Missing Seats, Covers, Dash Panels, Driver Seat, Etc.  Body Condition: Fair  Body Problems: Missing Hood And Fenders  Tires Condition: Poor  Tire Problems: No Front Tires, No Left Side Outer Tire  **Additional Information: Was Used As A Parts Bus - Missing Parts - SOLD AS IS - No Steering Knuckles, No Front Entry**  Note For Vehicles: There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All Defects And Flaws With A Vehicle Will Be The Buyers Responsibility Once Purchased By Buyer. Buyer Should Be Aware That They Are Purchasing A Used Vehicle As It Sits On The Auction Location With No Warranty Or Guarantee Whatsoever. Seller And Auctioneer Have Made A Diligent Attempt To Supply The Buyer With A General Description Of Each Unit And Do Not Guarantee The Accuracy Of The Information Supplied. Seller And Auctioneer Recommend Buyers To Thoroughly Inspect Each Vehicle Prior To Bidding. ** Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p> <p>- Current Condition Unknown</p>	