










Lot Number	Title	Description	Thumbnail
0	Preview and Removal Information	<p>**All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes**</p> <p>IMPORTANT NOTICE FOR SEGUIN ISD ONLINE AUCTION: **All purchases will be subject to a (14%) buyer's premium. There Will Be A 3% Fee For All Purchases Not Made By Cash, Cashier's Check, Direct Deposit, Money Order & Wire Transfer*</p> <p>CDC COVID-19 GUIDELINES WILL BE OBSERVED – WEAR A MASK AND STAY AT LEAST 6 FT. APART.</p> <p>Location 1: (Lots T1-T5) Central Office (Grounds) 1241 E. Kingsbury St, Seguin TX 78155 Driving Directions) Preview: (By Appointment Only-Mandatory-No Exceptions) Friday, November 12, 2021 Operation: 7:00 A.M. - 3:30 P.M.)</p> <p>Removal Dates & Times: (By Appointment Only-Mandatory-No Exceptions) (Monday, November 29, 2021/Tuesday, November 30, 2021 /Wednesday, December 1, 2021 (Hours Of Operation: 07:00 A.M. - 03:30 P.M.)</p> <p>Preview & Removal Contact: Robert Gonzales – 830-379-6721 or 830-743-3132 or Maintenance 830-401-8611</p> <p>Location 2: (Lots B1-B5) Transportation, 1005 E. Seidemann St, Seguin TX 78155 Driving Directions) Preview: (By Appointment Only-Mandatory-No Exceptions) Friday, November 12, 2021 (Hours Of Operation: 08:00 A.M. – 11:00 A.M./02:00P.M. – 05:00 P.M.)</p> <p>Removal Dates & Times: (By Appointment Only-Mandatory-No Exceptions) (Monday, November 29, 2021/Tuesday, November 30, 2021 /Wednesday, December 1, 2021 (Hours Of Operation: 08:00 A.M. – 11:00 A.M./02:00P.M. – 05:00 P.M.)</p> <p>Preview & Removal Contact: Jason Smith – 830-372-4420 Ext 12508</p> <p>Removal Note: <i>There Will Be No Manpower, No Employee Assistance Or Equipment Available For Removal. Buyer Must Remove All Lots In Their Entirety. Buyer Is Solely Responsible For Loading & Unloading, Bring Own Manpower, Equipment, Dollies Or Other Adequate Moving Devices or Equipment, Etc. To Remove Items. Buyer Must Have Adequate Transportation To Move Purchased Items.</i></p> <p>Note For Vehicles: <i>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</i></p> <p>VEHICLE TITLE INFORMATION : Lemons Auctioneers & Online Pros will contact you concerning the title preparation information for the Title(s) of your Vehicle(s). Buyer must remove their Vehicle(s) from Seller's auction location before the Title Preparation will be processed. Titles can take up to thirty (30) days to be received by Buyer due to processing and delivery. Buyers may pick up their processed titles in person at Lemons Auctioneers & Online Pros office location by appointment only at 18810 Juergen Road, Tomball, Texas 77377 between the hours of 9 a.m. – 3 p.m., Monday thru Friday. You may call 281-357-4977 or email lemons@onlinepros.com .</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a</p>	

		<p><i>diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracv of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding. **</i></p> <p>Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper Cables, Towing Equipment, Tow Trucks, Etc. To Get Vehicle Started And/or Removed.</p>	
B1	(1) 2010 Bluebird Bus Vision Vin# 8998 - WILL NEED TO BE TOWED	<p>Bus# S-16 Conventional Style 25 Passenger Engine Size: 8.1L GM Propane runs rough Engine in Front Propane No Battery Transmission: Auto Alison Air Brakes Inspection 12/2021 Unable to read mileage Has wheel chair lift (Missing parts) Interior Condition: Fair (needs cleaning) Body Condition: Fair (Dents and scratches) Tires Condition: Poor Parts are missing from wheel chair lift</p>	
B3	(1) 2001 International IRC Bus Vin# 3612 - WILL NEED TO BE TOWED	<p>Bus# 47 Conventional Style 71 Passenger Engine Size: DT466E Engine in Front Won't Start Diesel Battery is dead Doesn't Run Automatic Transmission Type: Allison Air Brakes Inspection Date 7/2022 Mileage Reads 240,4012 (Not Actual) Wheel Chair Lift: No Interior Condition: Needs cleaning, windows won't stay up Body Condition: Fair, dents and scratches Tires Condition: Poor</p> <p>- Current Condition Unknown</p>	
B2	(1) 1997 International Bus Vin# 0745 - WILL NEED TO BE TOWED	<p>Bus# 43 Conventional Style 43 Passenger Engine Size DT466E Engine in front (Won't start) Diesel Battery: Dead Does NOT run Transmission: Allison Air brakes Inspection 7/2021 No Wheel chair lift Interior: Fair (needs cleaning) Body Condition: Fair (Dents and scratches) Tires Condition: Poor</p>	
T1	(1) 2001 Ford F250 Pickup Vin# 1567 - WILL NEED TO BE TOWED	<p>Unit# 68A Engine in Front Gas Battery Runs Automatic Mileage Reads 16,069 (Not actual) Wheel Chair Lift: No Interior Condition: Fair Body Condition: Fair Tire Condition: Poor (dry rot) Rebuilt Motor, needs tuneup and coil packs, runs rough</p> <p>- Current Condition Unknown</p>	

B4	(1) 2010 Bluebird Bus Vision Vin# 8987 - WILL NEED TO BE TOWED	Bus# 82 Conventional Style 71 Passenger Engine Size 8.1 L GM Engine in Front Won't Start Propane Battery: Dead Automatic Transmission Type: Alision Brakes: Air Inspection Sticker 2/2020 Unable to read mileage Wheel Chair Lift: No Interior Condition: Poor, holes in seat, covers missing Body Condition: Poor: parts missing, dents, and scratches Tires Condition: Poor - Current Condition Unknown	
T2	(1) 2002 Ford F250 Pickup Vin# 7878 - WILL NEED TO BE TOWED	Unit# 85A Engine in Front Gas Battery Runs Automatic Mileage Reads 116,898 (Actual) Wheel Chair Lift: No Interior Condition: Fair Body Condition: Fair Tire Condition: Poor (Dry rot) Starts but has bad flywheel - Current Condition Unknown	
B5	(1) 2010 Bluebird Bus Vision Vin# 8994 - WILL NEED TO BE TOWED	Bus# 83 Conventional Style 71 Passenger Engine Size: 8.1L GM Propane Engine in Front Propane No battery Does not run Automatic Transmission: Alision Air Brakes Inspection 4/2021 Unable to read mileage Wheel Chair Lift: No Interior Condition: Poor (missing parts) Body Condition: Poor: dents, scratches and parts missing Tires Condition: Poor - Current Condition Unknown	
T3	(1) 2002 Ford F250 Pickup Vin# 7880 - WILL NEED TO BE TOWED	Unit# 87A Engine in Front Gas Battery Runs Automatic Mileage Reads 88,888 (Actual) Wheel Chair Lift: No Interior Condition: Fair Body Condition: Fair Tires Condition: Poor (dry rot) Starts and runs but issues with the A/C - Current Condition Unknown	

T4	(1) 2004 Ford F250 Pickup Vin# 8359 - WILL NEED TO BE TOWED	Unit# 55A Engine in Front Gas Battery Runs Automatic Mileage Reads 85,883 (Actual) Wheel Chair Lift: No Interior Condition: Fair Body Condition: Fair Tires Condition: Poor (dry rot) A/C works but truck overheats - Current Condition Unknown	
T5	(1) 2006 Ford Cargo Van Vin# 7561 - WILL NEED TO BE TOWED	Unit# 70A Engine in Front Gas Battery Runs Automatic Mileage Reads 57,925 (Actual) Wheel Chair Lift: No Interior Condition: Fair Body Condition: Fair Tires Condition: Poor (Dry rot) Runs rough, side cable doors and rear door broken - Current Condition Unknown	