

Stark Exterminators 9337 W Oaklawn Rd Suite A Biloxi, MS 39532 228-896-3499

Service Inspection Report

ORDER #: 61632298

WORK DATE: 05/27/2025

BILL-TO 1040838

4515 Harrison Ave Gulfport, MS 39507-4028 Email:

Phone: 504-491-3253

LOCATION 1040838

4515 Harrison Ave Gulfport, MS 39507-4028 Email:

Phone: 504-491-3253

Time In: 05/27/2025 09:26:38 AM **Time Out:** 05/27/2025 10:09:19 AM

Customer Signature

202

Dale Brehm

Technician Signature

pars

Jonathan Campbell License #:

Purchase Order	Terms	Service Description	Quantity	Amount
None	DUE UPON RECEIPT	Sentricon Guarantee/Coverage	1.00	
			Subtotal	0.00
			Tax	0.00
			Total	0.00
			Prior Balance:	0.00
			Total Due:	0.00

GENERAL COMMENTS / INSTRUCTIONS

SCHEDULED @9; RENEWAL PAID

CONDITIONS / OBSERVATIONS Reported Severity Responsibility Reviewed

None Noted.

PRODUCTS APPLICATION SUMMARY

None Noted.

DEVICE INSPECTION SUMMARY

AREA COMMENTS

01 RENEWAL SERVICE: RENEWAL SERVICE: Inspection Only. No products or materials applied during this service. PLEASE NOTE: CUSTOMER MUST NOTIFY ARROW IN WRITING OF ANY ADDITIONS OR MODIFICATIONS TO STRUCTURE. PAYMENT: When a check is provided as payment, the Customer agrees that the COMPANY is authorized to use check information to make a one-time electronic funds transfer from Customer's account or to process the payment as a check transaction. For inquiries, please call 1-888-GO-ARROW. Exterior Inspected Inspected Garage Inspected Attito pull-down inaccessible. Tower Inspected Wine cellar Inspected INACCESSIBLE AREAS: The following areas were inaccessible for viewing and sounding; therefore, no report can be made in regard to the presence or absence of infestation/damage: Wall voids, Floor coverings, Personal items. No visible signs of activity observed at time of inspectionThank you for your business!

DEVICE INSPECTION EXCEPTIONS

None Noted.

Printed: 05/27/2025 Page: 1/2



Stark Exterminators 9337 W Oaklawn Rd Suite A Biloxi, MS 39532 228-896-3499

Service Inspection Report

ORDER #: 61632298

WORK DATE: 05/27/2025

INSPECTION DETAIL						
Area	Time	Туре	Status	Pest Findings		
01 RENEW	01 RENEWAL SERVICE					
	10:09:06 AM	Area	No Activity			

PRODUCTS APPLIED

None Noted.

Printed: 05/27/2025 Page: 2/2



9337 W Daklawn Rd Suite A Bilowi, MS 39532 228-896-3499

SERVICE ADDRESS

4515 Harrison Ave 39507-4028 Gulfport, MS

RT# JASONMSMIT

RENEWAL SERVICE SLIP / INVOICE

GUARANTEE TYPE / ACCOUNT #

1040838/56

☐ RECEIVED AT INSPECTION: \$

CHECK ONE

PREPAID

CASH

CHECK

CHECK ONE

VISA

STEPS Services:

PLEASE PAY FROM THIS INVOICE

AMOUNT NOW DUE

508.00 + 42.56 = 650.58

RENEWAL MONTH / YEAR:

MAPCODE: FORM II ON FILE:

GENERAL INSPECTION REPORT OF FINDINGS AND/OR TREATMENT

INSPECTION GRAPH FOLINE 12/105 Mono (stucco SERVICE CODES SUBTERRANEAN TERMITES ST DT = DRYWOOD TERMITES PPB = POWDER POST BEETLES WB = WOOD BORERS = FUNGUS F M = MOISTURE CONDITION WG = WOOD TO GROUND CONTACT STRAW = INACCESSIBLE AREAS

MESSAGES/CONTACTS

SCHEDULED @12; RENEWAL PAID. PLEASE CALL HIM ON THE WAY

FINDINGS	YES	NO
•INACCESSIBLE AREAS	V	
THE FOLLOWING AREAS WERE INACCESSIBLE FOR VIEWIN THEREFORE NO REPORT CAN BE MADE IN REGARD TO THI ABSENCE OF INFESTATION/DAMAGE.	G AND SOUNDING. E PRESENCE OR	

WALLYOUDS FLOORIUS

AREAS OF INSPECTION	YES
EXTERIOR	V
INTERIOR	2
GARAGE	V
CRAWL SPACE	ASM
BASEMENT	NA
ATTIC	

FOUND DURING INSPECTION OF ACCESSIBLE AREAS COMMENTS: No ACKVE ISSUES

✓ I have verified the Sentricon System is intact and providing termite protection for your structure.

PAYMENT: When a check is provided as payment, the Customer agrees that the COMPANY is authorized to use check information to make a one-time electronic funds transfer from Customer's account process the payment as a check transaction. For inquiries, please call 1-855-61APK-NOW.

PLEASE NOTE: CUSTOMER MUST NOTIFY STARK IN WRITING OF ANY ADDITIONS OR MODIFICATIONS TO STRUCTURE

THE ABOVE WORK HAS BEEN SATISFACTORILY PERFORMED

CUSTOMER SIGNATURE

See customer information on reverse sid WHITE - OFFICE COPY YELLOW - CUSTOMER COPY

SERVICE PROFESSIONAL

STK-SAS-201 Rev.