

OPERATION PERMIT

APPALACHIAN DISTRICT 126 Poplar Grove Connector Boone, NC 28607

Phone: 336-246-3356

For Office Use Only

*CDP File Number

241575 - 1

County ID Number:

15235-089

Evaluated For:

EXPANSION

Applicant:	Miller, Stephen S.	Property Owner:	Miller, Stephen S.	Tit - 20. 3
Address:	241 Esther Road	Address:	241 Esther Road	
City:	Roxboro	City:	Roxboro	
State/Zip:	NC/ 27573	State/Zip:	NC/ 27573	
Phone #:	(336) 599-6339	Phone #:	(336) 599-6339	

Property Location & Site Information NEW Address/Road #: Water Tank Road Fleetwood, NC Subdivision: Phase: 28626 Lot: **Directions** Highway 221 South to Fleetwood. Turn Left on Water SINGLE FAMILY Structure: Tank Road. go approx .2 miles to site across creek on right. 3 # of Bedrooms: # of People: 6 **SPRINGS** *Water Supply: *System Classification/Description: 1380 - Blethen, Andrew *IP Issued by: TYPE III B. SYSTEM W/SINGLE EFFLUENT PUMP 1380 - Blethen, Andrew *CA Issued by: *Distribution Type: PUMP TO GRAVITY *Pre-Treatment: N/A 360 Design Flow:

Soil Application Rate: 0.500 Comments: -System expansion of a 2 bedroom septic system to a 3 bedroom. Increasing flow by 120 GPD.

Drain field Nitrification Field 656 Sq. ft. INFILTRATOR QUICK4 PLUS STANDARD *System Type: 2 No. Drain Lines James Dennis Galliher (A1 Backhoe Sevice) Installer: 164 ft. Total Trench Length: 1071 Certification #: Inches O.C. 10 -18 Trench Spacing: ▼Feet O.C. Inches 2419 - Branch, Marcus *EHS: Trench Width: **X**Feet 11/15/2017 inches Date: Aggregate Depth: 14 Inches Minimum Trench Depth: Approval Status - 10 Inches Minimum Soil Cover: Maximum Trench Depth: 14 Inches X Approved □ Disapproved 10 Inches Maximum Soil Cover:

DP File Number	241	575 ·	- 1				60	ptic Tank		County File Number: 15235-089	ميرميد ا
14							36				
Manufacturer:								Lat:			
STB:								Long:	lomo	o Donnio Callibor (A4 Backbar	
Gallons:		.047								s Dennis Galliher (A1 Backhoe	
	08/16/2			_				Certification #:			
*Filter Brand:								_		- Branch, Marcus	
ST Marker:			Ä					Date:	11/15	5/2017	
Reinforced Tank:										Approval Status	1
1 Piece Tank:	☐ Yes	S	X	No						☑ Approved ☐ Disapproved	
			***				Pu	ımp Tank			•
Manufacturer:	B & C							Installer:	Jame	es Dennis Galliher	
PT:	169							Certification #:	1071		
Gallons:	1000							*EHS:	2419	- Branch, Marcus	
Date:	08/16/2	2017						Date:	11/15/	2017	
Riser Sealed:	X Yes	S		No							
Riser Height:	X Yes	S		No	(Min. 6	in.)			/		
Reinforced Tank:	⊠ Ye	s		No						Approval Status	
1 Piece Tank:	☐ Ye	s		No						■ Approved □ Disapproved	·
							S	upply Line			
Pipe Size		2		inch	n diamet	or			. Jam	es Dennis Galliher	
Pipe Length		87	_	feet		~ .		Certification #	-		
*Schedule			_	1001						9 - Branch, Marcus	
0011000110										15/2017	
Pressure Rated	4 X Ye	3C		No				Date	 /	10,2017	
Approved fittings				No						Approval Status	
Approved intings	, ш ы 16	<i>7</i> 3		140					(☑ Approved ☐ Disapproved	
							Pump	Requirement			
Pump Type:	E a ffluen	t Pur	mp					Installer:	Jame	s Dennis Galliher (A1 Backhoe service)	
Dosing Volume:		Gal						Certification #:			
Draw Down:			4	Inche	3 S					- Branch, Marcus	
*Chain:	ROPE							Date:	11/15	5/2017	
Valves Acce	essible:	X	Yes		ON [N/A				
Flow Adjustment	Valve:	X	Yes		□ No		N/A		1	Approval Status	
Check	k-valve:	X	Yes		J No		N/A				
PVC I	Unions:	X	Yes		□ No		N/A		ļ	☑ Approved ☐ Disapproved	
Ver	nt Hole:		Yes] No	X	N/A				_
Anti-sipho	n Hole:		Yes		No	\mathbf{x}	N/A				

*CDP File Number 241575 - 1	County File Number:	15235-089
*Operation Permit completed by: 2419 - Branch, Marcus	<i>:</i>	
Authorized State Agent: Maure Brund, REHS	Date of Issue: 11/15/2017	
Owner/Applicant: X Stephen & William	×41/20/	17
This system has been installed in compliance with applicable NC General Statutes: Article Sewage Treatment and Disposal, 15A NCAC 18A .1900 et. Seq., and all conditions of the licenstruction Authorization. This property is served by a TYPE III B. sewage septic system.	·	
Rule .1961 requires that a Type TYPE III B. septic system meet the following criteria:		
Minimum System Review By The Local Health Department: 5 YRS.		
Management Entity: OWNER		
Minimum System Inspection/Maintenance Frequency By Certified Operator:		
<u>N/A</u>		
Reporting Frequency By Certified Operator: N/A		
Rule .1961 requires that a Type IV and V septic systems designed for a home/business own with a public management entity with a certified operator or a private certified operator for the		i

Rule .1961 requires that Type VI septic systems designed for a home/business owner must maintain a valid contract with a public management entity with a certified operator for the life of the septic system.

Rule .1961 (2) (e) requires a contract shall be executed between the system owner and a management entity prior to the issuance of an Operation Permit for a system required to be maintained by a public or private management entity, unless the system owner and certified operator are the same. The contract shall require specific requirements for maintenance and operation, responsibilities of the owner and systems operator, provisions that the contract shall be in effect for as long as the system is in use, and other requirements for the continued proper performance of the system. It shall also be a condition of the Operation Permit that subsequent owners of the systems execute such a contract.

Total Time:(HH:MM)

System Final Inspection Log

Drain Field

*CDP File Number 241575 - 1 * County File Number: 15235-089

٠,,

_	Electric Equipment										
(NEMA 4X Box or Equivalent	X	Yes		No	□ N/A	Installer:	James Dennis Galliher (A1 Backhoe service)			
	Box 12 inches Above Grade	X	Yes		No	□ N/A	Certification #:	1071			
	Box Adj. To Pump Tank		Yes	X	No	□ N/A	*EHS:	2419 - Branch, Marcus			
	Conduit Sealed	X	Yes		No	□ N/A	Date:	11/15/2017 12:00:00AM			
	Pump Manually Operable	X	Yes		No	□ N/A		Approval Status			
	*Activation Method	1: F	PIGGYE	BACK				Approved Disapproved			
	Alarm Audible	X	Yes		No	□ N/A					
ĺ	Alarm Visible	X	Yes		No	□ N/A					

*CDP File Number	241575 - 1	County File Number:	15235-089
Septic Tank	,		
Water Tested tank with	(2) 1' risers		
Pump Tank			
•	00112		
Water Tested Tank with	n one 30" riser		
Supply Line			
Cupply Line			
Pump Requirements			
rump requirements			
Electrical Equipment			

ITYT HEVTIH SLECIVIISL אצק 1000001100 458-915 671-Jd 74 Jump Jant 201X,QE De Sept Lepan trea 4MM Chambers House Has Crawl Space are Bulgared +,001-Spines 7 petal fund in lounding Non 18 9, MC - Pressured Like $\mathbf{y}_{\mathbf{z}}$ 10 -10, of 4. Mc Existing Septic Lites soluh न्र WISUBOXZ **Septic** Well NYWE OUSITE WASTEWATER PERMIT WELL PERMIT # SILE PLAN Alleghany (336) 372-8813 Ashe (336) 246-3356 Watauga (828) 264-4995 APPALACHIAN DISTRICT HEALTH DEPARTMENT