AES. LLC Specialty Contractors

CHAIN OF CUSTODY RECORD

Project: Palmer Estate	
Location: 3204 Seneca Park Rd, Louisville, Ky, 40207	Comments:
Sampled By: Keith Schnell Jr	
Sample Type: ☐ Composite ☒ Grab ☐ N/A	
Air Sample Type □ Clearance □ Personal □ Area	

Sample No.	Time	Date	Sample Type/Location	Test For Asbestos	Test For Lead
001A	10:00	5/15/23	Kitchen – Floor Tile	X	
001B	10:00	5/15/23	Kitchen – Black Mastic	X	
002A	10:00	5/15/23	Basement Office – Floor Tile	X	
002B	10:00	5/15/23	Basement Office – Black Mastic	X	
003A	10:00	5/15/23	Basement Rec Room – Floor Tile	X	
003B	10:00	5/15/23	Basement Rec Room – Black Mastic	X	
24					
	ž.				
					×
				3	

Time	Date	Received By: (Signature)
3:00	5/15/23	Minteres Marays
	7	3:00 5/15/22



MRS, Inc. Analytical Laboratory Division

332 West Broadway / Suite # 902 Louisville, Kentucky - 40202 - 2133 (502) 495-1212 Fax: (502) 491-7111

BULK SAMPLE ASBESTOS ANALYSIS

Address:	3204 Seneca Park Road	
	Louisville, KY - 40207	
	Address:	Address: 3204 Seneca Park Road Louisville, KY - 40207

				% FIBROUS ASBESTOS		% NON-ASBESTOS FIBERS			RS		
Sample ID	Color	Layered	Fibrous	Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 001 A	Offwh.	Yes	No	3%							97%
# 001 B	Black	Yes	No	3%				2%			95%
# 002 A	Mixed	Yes	No	7%							93%
# 002 B	Black	Yes	No	3%				2%			95%
# 003 A	White	Yes	No	5%							95%
# 003 B	Black	Yes	No	3%				2%			95%

Methodology	: EPA	Method 600/R-93-116		
Date Analyzed	d :	16-May-23		
Analyst	:	Winterford Mensah	Reviewed By:	Thinker our Menne

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AJHA #1 02459